

CONTENTS

1.	INTRODUCTION	1
1.1.	Summary	1
1.2.	Background to the post-accident review	1
1.3.	Format of the report	2
2.	THE IRRADIATION FACILITY	2
2.1.	History and general description of the facility	2
2.2.	The radioactive source	3
2.3.	The source hoist mechanism	3
2.4.	The product transport mechanism	7
2.5.	Safety interlocks and access control	10
2.5.1.	Control console	10
2.5.2.	Installed radiation monitor	11
2.5.3.	Other safety features	15
2.6.	Maintenance	15
2.7.	Operation, supervision and radiological training	16
3.	REGULATORY CONTROL	17
4.	THE ACCIDENT	18
4.1.	Initiating events	18
4.2.	Entry and exposure	19
4.3.	Subsequent actions	21
5.	ACTIONS AND LESSONS	21
5.1.	Findings of the investigation by Israeli authorities	22
5.1.1.	Conclusions	22
5.1.2.	Recommendations and actions	23
5.2.	Generic lessons	25
5.2.1.	Priorities	26
5.2.2.	Obstruction of the source rack	27
5.2.3.	Installed safety systems	27
5.2.4.	Instruction and training of staff	28
5.2.5.	Personal monitoring	29
5.2.6.	Inspections and audits	29

5.3. Initiatives by the IAEA	30
5.3.1. Training	30
5.3.2. Dissemination of information	30
6. OVERVIEW OF THE MEDICAL ASPECTS	31
6.1. Radiation effects and their treatment	31
6.2. Radiation effects in the present case	37
7. MEDICAL MANAGEMENT OF THE PATIENT	37
7.1. Initial assessment	37
7.2. General clinical course	39
7.3. Management of the haematological phase	62
7.4. Management of the gastrointestinal phase	66
7.5. Management of localized radiation injuries	67
7.6. Neuropsychological aspects	67
8. FINDINGS OF THE POST-MORTEM INVESTIGATION	68
9. LESSONS TO BE LEARNED	70
REFERENCES	73
LIST OF ABBREVIATIONS	75
CONTRIBUTORS TO DRAFTING AND REVIEW	77

