

Contents

1 Introduction	1
1.1 The Origin of Stresses	1
1.2 Methods of Measuring Residual Stresses	4
1.3 Some Examples of Residual Stresses	7
References	12
2 Fundamental Concepts in Stress Analysis	13
2.1 Introduction	13
2.2 Definitions	13
2.3 Stress and Strain	14
2.4 Forces and Stresses	15
2.5 Displacements and Strains	17
2.6 Transformation of Axes and Tensor Notation	20
2.7 Elastic Stress-Strain Relations for Isotropic Materials	25
2.8 Structure of Single Crystals	28
2.9 Elastic Stress-Strain Relations in Single Crystals	32
2.10 Equations of Equilibrium	37
2.11 Conditions of Compatibility	38
2.12 Basic Definitions in Plastic Deformation	39
2.13 Plastic Deformation of Single Crystals	41
2.14 Deformation and Yielding in Inhomogeneous Materials	44
Problems	45
Bibliography	46
3 Analysis of Residual Stress Fields Using Linear Elasticity Theory	47
3.1 Introduction	47
3.2 Macroresidual Stresses	47
3.3 Equations of Equilibrium for Macrostressess	51
3.4 Microstressess	52
3.5 Equations of Equilibrium for Micro- and Pseudo-Macrostressess	54
3.6 Calculation of Micro- and PM Stressess	56
3.7 The Total Stress State in Surface Deformed Multiphase Materials	61
3.8 Macroscopic Averages of Single Crystal Elastic Constantss	62
3.9 The Voigt Average	63
3.10 The Reuss Average	65
3.11 Other Approaches to Elastic Constant Determination	66
3.12 Average Diffraction Elastic Constantss	69

Summary	73
References	73
4 Fundamental Concepts in X-ray Diffraction	75
4.1 Introduction	75
4.2 Fundamentals of X-rays	75
4.3 Short-wavelength Limit and the Continuous Spectrum	76
4.4 Characteristic Radiation Lines	77
4.5 X-ray Sources	80
4.6 Absorption of X-rays	82
4.7 Filtering of X-rays	84
4.8 Scattering of X-rays	84
4.9 Scattering from Planes of Atoms	86
4.10 The Structure Factor of a Unit Cell	87
4.11 Experimental Utilization of Bragg's Law	89
4.12 Monochromators	90
4.13 Collimators and Slits	91
4.14 Diffraction Patterns from Single Crystals	93
4.15 Diffraction Patterns from Polycrystalline Specimens	94
4.16 Basic Diffractometer Geometry	95
4.17 Intensity of Diffracted Lines for Polycrystals	97
4.18 Multiplicity	98
4.19 Lorentz Factor	98
4.20 Absorption Factor	100
4.21 Temperature Factor	103
4.22 X-ray Detectors	103
4.23 Deadtime Correction for Detection Systems	108
4.24 Total Diffracted Intensity at a Given Angle 2θ	109
4.25 Depth of Penetration of X-rays	110
4.26 Fundamental Concepts in Neutron Diffraction	111
4.27 Scattering and Absorption of Neutrons	114
Problems	116
Bibliography and References	116
5 Determination of Strain and Stress Fields by Diffraction Methods	117
5.1 Introduction	117
5.2 Fundamental Equations of X-ray Strain Determination	117
5.3 Analysis of Regular "d" vs. $\sin^2\psi$ Data	119
5.4 Determination of Stresses from Diffraction Data	120
5.5 Biaxial Stress Analysis	122
5.6 Triaxial Stress Analysis	125
5.7 Determination of the Unstressed Lattice Spacing	126
5.8 Effect of Homogeneity of the Strain Distribution and Specimen Anisotropy	130
5.9 Average Strain Data from Single Crystal Specimens	131

5.10 Interpretation of the Average X-ray Strain Data Measured from Polycrystalline Specimens	136
5.11 Interpretation of Average Stress States in Polycrystalline Specimens	137
5.12 Effect of Stress Gradients Normal to the Surface on d vs. $\sin^2\psi$ Data	140
5.13 Experimental Determination of X-ray Elastic Constants	145
5.14 Determination of Stresses from Oscillatory Data	153
5.15 Stress Measurements with Neutron Diffraction	154
5.16 Effect of Composition Gradients with Depth	157
5.17 X-ray Determination of Yielding	159
5.18 Summary	160
Problem	162
References	162

6 Experimental Errors Associated with the X-ray Measurement of Residual Stress	164
6.1 Introduction	164
6.2 Selection of the Diffraction Peak for Stress Measurements	164
6.3 Peak Location	166
6.3.1 Half-Value Breadth and Centroid Methods	167
6.3.2 Functional Representations of X-ray Peaks	168
6.3.3 Peak Determination by Fitting a Parabola	171
6.3.4 Determination of Peak Shift	175
6.4 Determination of Peak Position for Asymmetric Peaks	178
6.5 Statistical Errors Associated with the X-ray Measurement of Line Profiles	181
6.6 Statistical Errors in Stress	186
6.6.1 The $\sin^2\psi$ Technique	186
6.6.2 Two-Tilt Technique	187
6.6.3 Triaxial Stress Analysis	187
6.6.4 Statistical Errors in X-ray Elastic Constants	189
6.7 Instrumental Errors in Residual Stress Analysis	190
6.7.1 Variation of the Focal Point with θ and ψ	191
6.7.2 Effect of Horizontal Divergence on Focusing	192
6.7.3 Effect of Vertical Beam Divergence	195
6.7.4 Effect of Specimen Displacement	196
6.7.5 Effect of ψ -axis not Corresponding to the 2θ -axis	199
6.7.6 Error Equations for the ψ -Goniometer	200
6.7.7 Effect of Errors in the True Zero Position of the ψ -axis	202
6.7.8 Alignment Procedures	203
6.8 Corrections for Macrostress Gradients	205
6.9 Corrections for Layer Removal	206
6.10 Summary	208
Problems	209
References	209

7 The Practical Use of X-ray Techniques	211
7.1 Introduction	211
7.2 The Use of Ordinary Diffractometers	211
7.3 Software and Hardware Requirements	212
7.4 Available Instruments	213
7.5 Selected Applications of a Portable X-ray Residual Stress Unit (By W. P. Evans)	214
Reference	229
8 The Shape of Diffraction Peaks – X-ray Line Broadening	230
8.1 Introduction	230
8.2 Slit Corrections	233
8.3 Fourier Analysis of Peak Broadening	238
Problem	245
References	247
Appendix A: Solutions to Problems	248
Appendix B	252
B.1 Introduction	252
B.2 The Marion-Cohen Method	252
B.3 Dölle-Hauk Method (Oscillation-free Reflections)	254
B.4 Methods of Peiter and Lode	256
B.5 Use of High Multiplicity Peaks	257
References	257
Appendix C: Fourier Analysis	259
Appendix D: Location of Useful Information in “International Tables for Crystallography”	266
Appendix E: Values of G_x for Various Materials (By Dr. M. James)	267
Appendix F: A Compilation of X-ray Elastic Constants (By Dr. M. James)	270
References	271
Subject Index	273