Contents

Preface *v*
Prologue *xi*
1. FUSION WELDING — PROCESS VARIABLES *1*
  Fusion welding *2*
    Principles of consumable development *4*
    Absorption of gases in the weld metal *9*
    Nitrogen absorption *10*
    Hydrogen absorption *11*
    Composition of welds *12*
    Summary of process variables *17*
  The weld thermal cycle *17*
    Heat-flow equations *17*
    The thermal cycle of the base metal *23*
    Refinements to the heat-flow equations *26*
    Heat flow in electroslag welding *28*
    Weld simulation *29*
    Summary of weld thermal cycle results *33*
  Residual stresses in welds *33*
    Stresses and strains generated by changes in temperature *33*
    Stresses generated by the $\gamma \rightarrow \alpha$ phase transformation *36*
    Measurement of residual stresses in welds *39*
    Numerical methods of estimating residual stresses in welds *42*
    Summary of residual stress work *44*
  References *46*
  Further reading *47*
2. THE WELD METAL *48*
  Characteristics of weld solidification *49*
  Geometry of the weld melt *49*
  Epitaxial solidification *56*
  Crystal growth and segregation *59*
    No diffusion in solid; perfect mixing in liquid *60*
    No diffusion in solid; diffusional mixing in liquid *62*

Cellular and dendritic solidification in welds *66*
Refining weld structures *73*
Phase transformations during cooling of the weld metal *75*
Kinetics of phase transformations *75*
Transformations in duplex stainless steel welds *83*
Transformations in carbon and low alloy steel welds *88*
Role of alloying in transformation kinetics *93*
Role of slag inclusions in transformation kinetics *96*
Predicting the microstructure and properties of weld metals *99*
References *102*
Further reading *103*
3. THE HEAT-AFFECTED ZONE *104*
The base material *105*
The base metal's carbon equivalent *110*
The heating cycle *112*
Recrystallization *113*
The $\alpha \rightarrow \gamma$ phase transformation *114*
Precipitate stability *115*
Precipitate coarsening during a weld thermal cycle *118*
Precipitate dissolution during a weld thermal cycle *121*
Grain growth *123*
Kinetics of grain growth *123*
Grain growth during welding, assuming particle dissolution *126*
Grain growth during welding, assuming particle coarsening *130*
Practical considerations of grain growth and grain growth control in the HAZ *132*
Reactions at the fusion line *138*
Transformations during cooling *141*
Grain growth zone *141*
Grain refined zone *141*
Partially transformed zone *143*
Zone of spheroidized carbides *143*
Zone of 'unchanged' base material *143*
Predicting the microstructure and properties of the HAZ *143*
Weld simulation *144*
Hardness measurements *144*
Weld CCT diagrams *147*
Weld microstructure diagrams *148*
Grain growth diagrams *148*
Multi-run welds *150*
The weld metal *151*
The HAZ *151*
References *154*
Further reading *155*
4. CRACKING AND FRACTURE IN WELDS *156*
Fracture toughness *156*
Fracture toughness testing *160*

Solidification cracking *164*
Solidification structure *164*
Segregation *166*
Residual stresses and joint geometry *168*
Mechanism of solidification cracking *168*
Liquation cracking *170*
Lamellar tearing *172*
Mechanism of lamellar tearing *174*
Cold cracking *180*
Role of hydrogen *181*
Role of stress *185*
Role of microstructure *187*
Mechanism of cold cracking *190*
Reheat cracking *194*
Effect of reheating on the microstructure of a 0.5Cr–Mo–V alloy *197*
Mechanism of reheat cracking *200*
Case study: The *Alexander Kielland* disaster *203*
Construction of the *Alexander Kielland* *206*
The construction and fitting of the sonar flange plate *206*
Capsize of the *Alexander Kielland* *209*
Metallographic examination of the sonar flange plate welds *212*
Possible effects of the weld thermal cycle on the bracing and flange plate materials *215*
Mechanism of failure: main conclusions *218*
References *219*
Further reading *220*
APPENDIX: Weld cracking tests and weldability formulae *223*
INDEX *227*