Contents

Foreword v
List of Symbols ix
Glossary of Selected Terms and Abbreviations x
Preface xi

1. Relationships Between Radiation Quantities and Units 1

2. Measurement of Energy Fluence 2
2.1 Calorimetry 2
2.2 Total Absorption Ionization Chambers 2
2.3 Chemical Methods 3
2.3.1 Values of G for Ferrous Sulfate Dosimeter 3
2.4 Solid State Devices 6
2.5 Experimental Corrections 6
2.6 Comparison of Methods 8

3. Spectral Distribution of Photons and Quality Specification 8
3.1 Determination of Primary and Secondary Photon Spectra 8
3.1.1 Target Filtration 11
3.1.2 Characteristic Radiation 13
3.2 Other Specifications of Quality 13
3.2.1 Problems in Quality Specification Below 50 kV 14
3.2.2 Changes in Spectral Distribution Due to Attenuation of the X-Ray Beam in Air 14
3.2.3 Data Regarding Other Factors Influencing Quality 14

4. Measurement of Exposure 15
4.1 Definitions 15
4.1.1 Exposure Standard 15
4.1.2 Reference Instrument 15
4.1.3 Field Instrument 15
4.2 Exposure Standards 15
4.2.1 Correction for Attenuation of Photons in Air 16
4.2.2 Correction for Recombination of Ions 17
4.2.3 Accuracy of Measurement 17
4.3 Reference and Field Instruments 17
4.3.1 Energy Dependence 18
4.3.2 Exposure-rate Dependence 19
4.3.3 Angular Dependence 20
4.3.4 Size 20
4.3.5 Leakage 21
4.3.6 Atmospheric Temperature, and Pressure 21
4.3.7 Scale Characteristics 21
4.3.8 Operation and Constancy Checks 21
4.3.9 Calibration 21

5. Determination and Measurement of Absorbed Dose 22
5.1 Calorimetric Methods 22
5.2 Chemical Methods 22
5.3 Ionization Methods 23
5.4 Solid State Methods 23
5.5 Determination from Energy Fluence and Mass Energy Absorption Coefficient 24

6. X-Ray Interaction Coefficients 25

Appendix **Details of Ferrous Sulfate Dosimetry** 29
A.1 Preparation of Ferrous Sulfate Dosimeter Solution 29

A.2 Irradiation Cells 29
A.3 Measurement of Ferric Ion 29
A.4 Effect of Dose, Dose Rate and Temperature 29
A.5 Effect of Acid Concentration 30
A.6 Oxidation in Absence of Radiation 30

References 31

ICRU Reports 36

Index 38