

6.	Metallurgical phenomena affected by segregation	908
6.1.	Surface free energy change: role in creep cavitation	909
6.2.	Grain-boundary diffusivity: role in diffusion creep	913
6.3.	Interfacial cohesion: role in temper-brittleness	915
6.4.	Further example of metallurgical phenomena influenced by microchemical processes	918
6.4.1.	Microchemical barrier layers	918
6.4.2.	Creep-embrittlement	920
6.4.3.	Intergranular stress-corrosion cracking	922
6.4.4.	Intergranular hydrogen-embrittlement	924
6.4.5.	Inhibition of surface oxidation in alloys	924
7.	Interfacial microchemistry and alloy design theory	925
	References	928
	Further reading	931

<i>Subject index</i>	S1
--------------------------------	----

PART II

<i>Chapter 14. Diffusive phase transformations in the solid state, by Roger D. Doherty</i>	933	
1.	General considerations	934
1.1.	Introduction	934
1.2.	Driving forces – free energy changes	934
1.3.	Stable and unstable free-energy curves	937
1.4.	Gibbs's two types of transformation	937
1.5.	First-order and higher-order transformations	939
1.6.	Short-range and long-range diffusion	940
1.7.	Techniques for studying phase transformations	941
2.	Nucleation-and-growth transformations	942
2.1.	Theory of nucleation	942
2.1.1.	Interfacial structure and energy	946
2.1.2.	Equilibrium shape	947
2.1.3.	Strain energy	950
2.1.4.	Heterogeneous nucleation	952
2.1.5.	Experimental studies of nucleation	955
2.2.	Growth processes	961
2.2.1.	Growth without change of composition	961
2.2.2.	Transformations involving long-range diffusion	964
2.2.3.	Role of interface structure in growth processes	967
2.2.4.	Growth of ledged interfaces	971
2.2.5.	Quantitative experimental observations of growth rates	975
2.2.6.	Growth instabilities	979
2.3.	Precipitate dissolution	985

2.4.	Competitive growth – Ostwald ripening	987
2.4.1.	After precipitation	987
2.4.2.	During initial nucleation and growth	990
2.4.3.	Coarsening of Widmanstätten precipitates	994
2.5.	Discontinuous reactions – reactions at a moving interface	996
2.5.1.	Eutectoidal decomposition	996
2.5.2.	Discontinuous precipitation	1000
2.5.3.	Discontinuous coarsening	1002
2.5.4.	Determination of lamellar spacing in discontinuous reactions	1004
2.5.5.	Diffusion-induced grain-boundary migration	1004
2.5.6.	Experimental results on discontinuous reactions	1006
2.6.	Bainitic transformations	1007
3.	Continuous transformations	1008
3.1.	Spinodal decomposition	1009
3.2.	Continuous ordering	1018
4.	Application of phase transformation theory to specific alloy systems	1021
5.	Problems in phase transformations	1022
	References	1024
	Further reading	1030
	<i>Chapter 15. Phase transformations, nondiffusive, by C.M. Wayman</i>	1031
1.	Overview	1032
2.	Martensitic transformations	1032
2.1.	Introduction and general characteristics	1032
2.2.	Experimental observations of crystallographic features	1034
2.3.	The phenomenological crystallographic theory of martensitic transformations	1038
2.3.1.	The inhomogeneous shear and martensite substructure	1039
2.3.2.	Mathematical description of the phenomenological crystallographic theory	1041
2.3.3.	Some other crystallographic observations	1043
2.3.4.	Further observations on the martensite morphology and substructure	1044
2.4.	Martensite-parent interfaces	1049
2.5.	Energetics of martensitic transformations	1050
2.5.1.	Transformation hysteresis and the reverse martensite-to-parent transformation	1050
2.5.2.	Thermoelastic and non-thermoelastic martensitic transformations	1051
2.5.3.	Free energy change of a martensitic transformation	1052
2.5.4.	Nucleation of martensite	1053
2.6.	Mechanical effects in non-thermoelastic martensitic transformations	1054
2.6.1.	Introductory comments	1054
2.6.2.	Chemical and mechanical driving forces	1055
2.6.3.	Critical stress to induce martensitic transformation	1056
2.6.4.	Transformation-induced plasticity	1057
2.7.	Mechanical effects in thermoelastic martensitic transformations	1059
2.7.1.	General	1059
2.7.2.	The shape memory effect	1059
2.7.3.	The two-way shape memory effect	1061
2.7.4.	The engine effect in shape-memory alloys	1062
2.7.5.	Pseudoelastic effects	1062
2.7.6.	Martensite-to-martensite transformations	1064

3.	Crystallographically similar transformations	1065
3.1.	The bainite transformation in steels	1065
3.2.	Oxides and hydrides	1065
3.3.	The CuAu II ordering reaction	1066
4.	Omega phase formation	1067
5.	Phase changes and charge density waves	1069
References		1073
General bibliography		1074
<i>Chapter 16. Physical metallurgy of steels, by E. Hornbogen</i>		1075
1.	Iron and steel	1076
1.1.	Introduction	1076
1.2.	Some properties of pure iron	1077
2.	Alloys of iron	1081
2.1.	Interstitial alloys	1081
2.2.	Substitutional alloys	1085
2.3.	Interstitial plus substitutional alloys	1088
3.	Transformation reactions	1091
3.1.	Pearlite	1091
3.2.	Martensite	1094
3.3.	Bainite	1098
3.4.	Time–Temperature–Transformation diagrams	1101
3.5.	Tempering of martensite	1102
4.	Deformation and recrystallization	1103
4.1.	Microstructure of deformed steel	1103
4.2.	Recovery and recrystallization	1105
5.	Mechanical properties	1108
5.1.	Strength of ferrite	1108
5.2.	Strength of ferrite–pearlite steels and dual-phase steel	1114
5.3.	Strength of martensite	1116
5.4.	Strength and ductility of tempered martensite	1117
5.5.	Precipitation-hardened ferritic steel	1118
5.6.	Maraging steel	1120
5.7.	Thermo-mechanical treatments	1122
5.8.	High-speed steels	1125
5.9.	Austenitic steel	1125
5.10.	Low-temperature steels	1126
6.	Other physical properties	1129
6.1.	Absorber steels	1130
6.2.	Transformer steel	1130
6.3.	Invar alloy	1131
7.	Solidification	1132
7.1.	Rimming steel, killed steel	1132
7.2.	Cast iron	1133

References	1136
Further reading	1138
<i>Chapter 17. Point defects, by H.J. Wollenberger</i>	1139
1. Introduction	1140
2. Vacancy properties	1141
2.1. Theoretical background	1141
2.2. Experimental methods and results	1143
2.2.1. Enthalpy and entropy of formation	1143
2.2.2. Activation enthalpy of migration	1153
2.2.3. Agglomeration	1163
2.2.4. Interaction with other defects	1165
2.3. The controversy over the recovery-stage III interpretation	1165
3. Self-interstitials	1167
3.1. Production of interstitial atoms	1167
3.1.1. Questions of relevance in the present context	1167
3.1.2. Atomic displacement cross-section for electron irradiation	1167
3.1.3. Frenkel-defect production by neutrons and ions	1171
3.2. Determination of Frenkel-defect concentrations	1174
3.3. Interstitial properties	1176
3.3.1. Results of model calculations	1176
3.3.2. Experimental methods and results	1184
4. Radiation damage at high particle fluences	1201
4.1. General remarks	1201
4.2. Void formation and growth	1202
4.3. Irradiation-induced creep	1205
4.4. Radiation-induced phase transformation	1205
References	1208
Further reading	1220
<i>Chapter 18. Dislocations, by J.P. Hirth</i>	1223
1. Elementary geometrical properties	1224
2. Elastic fields of dislocations	1226
2.1. Displacement and stresses	1226
2.2. Peach–Koehler force	1228
2.3. Dislocation interactions	1229
2.4. Surface effects	1231
2.5. Line tension	1233
3. Crystal lattice effects	1234
3.1. Peierls barrier	1234
3.2. Core structure and energy	1236
3.3. Stacking faults and partial dislocations	1237
3.4. Slip systems	1240
3.5. Jogs	1240

4.	Dislocation behavior at low homologous temperatures	1241
4.1.	Kink motion	1241
4.2.	Point forces and bowout	1242
4.3.	Granato–Lücke internal friction theory	1243
4.4.	Dislocation sources	1244
4.5.	Dislocation pile-ups	1245
4.6.	Pinning in alloys	1246
4.7.	Work-hardening	1248
5.	Dislocation behavior at high homologous temperatures	1249
5.1.	Osmotic climb forces	1249
5.2.	Jog drag	1251
5.3.	Climb	1252
5.4.	Solute drag	1253
6.	Grain boundaries	1255
	References	1257

<i>Chapter 19. Mechanical properties, mildly temperature-dependent, by J. Weertman and J.R. Weertman</i>	1259
--	------

1.	Introduction	1260
2.	Stress-strain curves	1260
2.1.	Geometry of slip	1262
2.2.	Stress-strain curves of hcp metals	1264
2.3.	Critical resolved shear stress	1269
2.4.	Slip of face-centered cubic crystals	1269
2.5.	Slip of body-centered cubic crystals	1270
2.6.	Asymmetric deformation of bcc metals	1272
3.	Effect of temperature on stress-strain curves	1273
3.1.	Cottrell–Stokes Law	1275
4.	Work-softening	1278
4.1.	Haasen–Kelly effect	1279
4.2.	Very large plastic deformation	1280
5.	Theories of work-hardening	1281
5.1.	Long-range hardening	1281
5.2.	Stage I hardening	1284
5.3.	Stage II hardening	1285
5.4.	Stage III hardening	1287
5.5.	Short-range hardening theories	1288
5.6.	Dislocation cells	1292
6.	Theory of the temperature-dependence of the flow stress	1293
7.	Lüders bands and yield points	1296
8.	Dependence of the lower yield stress on grain size	1299
9.	Bauschinger effect	1301
10.	Mechanical twinning	1302

References	1305
Further reading	1307
<i>Chapter 20. Mechanical properties, strongly temperature-dependent, by J. Weertman and J.R. Weertman</i>	1309
1. Creep of metals	1310
1.1. Stress relaxation	1310
1.2. The three main types of creep and their locations on the creep diagram	1311
1.3. Anelastic creep (recoverable creep)	1313
1.4. Low-temperature creep (logarithmic creep)	1315
1.5. General theory of logarithmic creep	1317
1.6. High-temperature creep (Andrade creep)	1320
1.7. Temperature dependence of steady-state creep	1321
1.8. Stress dependence of steady-state creep	1323
1.9. Theory of high-temperature creep	1326
1.10. Nabarro–Herring–Coble creep	1332
2. Creep fracture and superplasticity	1334
2.1. Superplasticity	1334
2.2. Creep fracture	1335
2.3. Isoidionic maps	1337
References	1339
Further reading	1340

<i>Chapter 21. Mechanical properties of solid solutions and intermetallic compounds, by P. Haasen</i>	1341
Introduction	1342
1. Solid-solution hardening	1343
1.1. Survey of stress-strain curves of fcc alloy single crystals	1343
1.2. Slip lines, etch pits, and electron transmission observations	1344
1.2.1. Slip lines and etch pits	1344
1.2.2. Electron transmission pictures of fcc alloys	1346
1.3. Theories of solid-solution hardening	1349
1.3.1. Dislocation locking mechanisms	1351
1.3.2. Summation of solute forces acting on moving dislocations	1353
1.4. Solid-solution effect on fcc stress-strain curves	1357
1.4.1. Critical shear stress τ_0 of fcc solid solutions	1357
1.4.2. The yield phenomenon in fcc alloys	1361
1.4.3. Easy glide and overshoot in fcc alloys	1363
1.4.4. Linear hardening	1363
1.4.5. Dynamic recovery	1364
1.4.6. Deformation twinning in fcc alloys	1365
1.5. Solid-solution hardening in hcp crystals	1366

1.6.	Solid-solution hardening in the bcc structure	1368
1.7.	Hardening in the NaCl and diamond structures	1371
1.8.	Creep of solid solutions	1372
1.8.1.	Steady-state creep through dislocation climb	1373
1.8.2.	Creep limited by dislocation drag (class I) and the Portevin–Le Chatelier effect .	1374
1.9.	Fatigue of solid solutions	1375
2.	Precipitation-hardening	1376
2.1.	Interactions between dislocations and precipitate particles	1376
2.2.	Direct observations of precipitate–dislocation interactions	1379
2.3.	Mechanical properties of precipitation-hardened Al alloys	1381
2.3.1.	Oversized alloys	1381
2.3.2.	Zone-hardened alloys	1383
2.4.	Precipitation-hardening in other alloy systems	1383
2.4.1.	Copper–cobalt	1383
2.4.2.	Iron–carbon	1384
2.4.3.	Spinodally decomposed Cu–Ti alloys	1386
3.	Order-hardening	1387
3.1.	The superdislocation	1388
3.2.	Theoretical dependence of the yield stress on the degree of order	1391
3.2.1.	Distortion of a partially ordered structure	1391
3.2.2.	Change of lattice parameter with order	1392
3.2.3.	Anti-phase domains of finite size	1392
3.2.4.	Thickness of anti-phase boundary	1393
3.2.5.	Climb of superdislocations	1394
3.2.6.	Short-range order hardening	1394
3.2.7.	Quench-hardening	1394
3.3.	Temperature dependence of the flow stress of ordered alloys	1394
3.4.	Creep in ordered alloys	1396
3.5.	Twinning of ordered alloys	1397
4.	Plasticity of intermetallic compounds	1397
4.1.	Effect of temperature on strength	1398
4.2.	Creep of indium antimonide	1399
	References	1403
	Further reading	1408
	<i>Chapter 22. Mechanical properties of multiphase alloys, by Jean-Loup Strudel</i> . .	1411
1.	Introduction	1412
2.	Description and microstructure of dispersed-phase alloys	1413
3.	Tensile properties of two-phase alloys	1417
3.1.	Experimental results in macroscopic tests	1417
3.1.1.	Initial yield stress	1418
3.1.2.	Stress–strain curves	1419
3.1.3.	Bauschinger effect	1420
3.2.	Microscopic mechanisms and models	1420
3.2.1.	Initial yield stress	1421
3.2.2.	Work-hardening at low temperature in alloys with small particles	1422
3.2.3.	Heterogeneous deformation of alloys containing large particles	1430

3.3. Stress relaxation and recovery effects	1432
3.4. A continuum-mechanics approach to the internal stress	1432
4. High-temperature behavior of dispersed-phase alloys	1440
4.1. High-temperature subgrains in polycrystalline oxide-dispersion-strengthened alloys	1440
4.2. Apparent and effective creep parameters	1443
4.3. Average internal stresses in dispersed-phase alloys	1444
5. Composition and microstructure of precipitation-hardened alloys	1447
6. Tensile properties of precipitation-hardened alloys – behavior under high stress	1452
6.1. Macroscopic properties	1452
6.2. Deformation modes and hardening mechanisms	1454
6.2.1. Superlattice stacking faults	1456
6.2.2. Mechanical twinning of the ordered phase	1458
7. High-temperature creep of precipitation-hardened alloys	1459
7.1. Creep curves	1461
7.2. Deformation modes	1462
7.3. Internal stress	1462
7.4. Oriented coalescence of the hardening phase under strain	1465
8. Recrystallization	1466
8.1. Particle size and amount of strain	1466
8.2. Interparticle spacing	1468
8.3. Effect of temperature	1470
8.4. Micromechanisms	1470
9. Duplex structures and multiphase alloys	1471
9.1. Duplex structures	1472
9.2. Multiphase precipitation-hardening	1474
9.3. Mechanical alloying of complex alloys	1475
9.4. Grain-size effects in multiphase alloys	1476
References	1481
Further reading	1485
 <i>Chapter 23. Fracture, by Robb M. Thomson</i>	1487
1. Introduction and fracture overview	1488
2. Qualitative and observational aspects of fracture	1492
2.1. Fracture modes	1492
2.2. Fractographic observations	1493
2.3. The basis for fracture science	1496
3. Elastic analysis of cracks	1500
3.1. Stress analysis	1500
3.2. Eshelby's theorem and the J-integral	1505
4. Dislocation-crack interactions	1511
5. Equilibrium configurations	1515
5.1. The Griffith crack	1515
5.2. Shielding by one dislocation	1516
5.3. General shielding	1517
5.4. Summary	1521

6.	Atomic structure of cracks: thermal and chemical effects	1523
6.1.	Theory	1523
6.2.	Experimental observations	1529
7.	Atomic structure of cracks: dislocation emission	1532
8.	Summary of basic ideas	1536
9.	Some practical implications	1538
9.1.	Implications for final materials reliability	1538
9.2.	Brittle crack initiation	1540
9.3.	Ductile fracture and hole growth	1541
9.4.	Ductile–brittle transitions – temperature and rate effects	1541
9.5.	Chemical effects – hydrogen embrittlement	1544
9.6.	Grain-boundary impurities	1545
9.7.	Liquid-metal embrittlement	1546
9.8.	Film formation	1547
9.9.	Transformation-toughening	1547
	References	1548
	Further reading	1550
	<i>Chapter 24. Fatigue, by P. Neumann</i>	1553
1.	Introduction	1554
2.	Fatigue tests and the representation of fatigue data	1555
3.	Cyclic hardening	1557
3.1.	Matrix dislocation structure	1558
3.2.	Instabilities during cyclic hardening	1561
4.	Persistent slip bands	1563
4.1.	Properties of persistent slip bands	1564
4.2.	Dislocation models of persistent slip bands	1567
4.3.	Surface topography	1570
4.4.	Models for extrusion formation	1574
4.5.	PSBs in various materials	1578
5.	Crack initiation and stage-I crack growth	1579
5.1.	Crack initiation in persistent slip bands	1579
5.2.	Effect of environment on crack initiation and early growth	1582
6.	Stage-II crack propagation	1584
6.1.	Mechanism of stage-II crack propagation	1585
6.2.	Fracture-mechanical concepts	1589
	References	1594
	<i>Chapter 25. Recovery and recrystallization, by R.W. Cahn</i>	1595
1.	Classification of phenomena	1596
2.	Recovery	1597
2.1.	Recovery of electrical properties	1597

2.2. Recovery of stored internal energy	1597
2.3. Recovery of mechanical properties	1599
2.4. Recovery of microstructure	1604
2.4.1. Polygonization and subgrains	1604
2.4.2. Cell formation	1607
3. Primary recrystallization	1611
3.1. Laws of recrystallization	1611
3.2. Kinetics of primary recrystallization	1614
3.3. Nucleation of primary grains	1617
3.4. Growth of primary grains and the role of impurities	1630
3.4.1. Impurity drag	1630
3.4.2. Special orientations	1636
3.4.3. Vacancies in grain boundaries	1638
3.5. Recrystallization during hot-working	1641
3.6. Annealing textures	1642
3.7. Primary recrystallization of two-phase alloys	1646
4. Grain growth and secondary recrystallization	1653
4.1. Mechanism and kinetics of grain growth	1653
4.2. Formation of annealing twins	1656
4.3. Secondary recrystallization	1658
4.3.1. General features	1658
4.3.2. Surface-controlled secondary recrystallization	1662
4.3.3. Secondary recrystallization and sintering	1665
References	1665
Further reading	1670

<i>Chapter 26. Magnetic properties of metals and alloys, by F.E. Luborsky, J.D. Livingston and G.Y. Chin</i>	1673
--	------

1. Origins of fundamental magnetic properties	1674
2. Magnetic measurements	1679
2.1. Magnetization	1680
2.2. Magnetic field	1681
2.3. Demagnetizing field	1681
2.4. Curie temperature	1681
2.5. Magnetic anisotropy	1682
2.6. Magnetostriction	1682
2.7. Core loss	1682
3. Permanent-magnet materials	1682
3.1. Reversal mechanisms and coercivity	1683
3.2. Microstructure and properties	1685
3.3. Shape-anisotropy materials	1688
3.3.1. EDS magnets	1688
3.3.2. Spinodal alloys	1689
3.4. Crystal-anisotropy materials	1691
3.4.1. Cobalt–rare earths	1692
3.4.2. Hard ferrites	1694
3.4.3. Mn–Al–C	1694
3.4.4. Co–Pt and related alloys	1695

4. Soft magnetic materials	1695
4.1. Iron and low-carbon steels	1696
4.2. Iron–silicon alloys	1698
4.2.1. Phase diagram and intrinsic magnetic properties	1698
4.2.2. Magnetic permeability	1698
4.2.3. Core loss	1699
4.2.4. Metallurgy of silicon steels	1703
4.3. Iron–aluminium and iron–aluminium–silicon alloys	1704
4.4. Nickel–iron alloys	1705
4.4.1. Phase diagram and intrinsic magnetic properties	1705
4.4.2. Metallurgy of nickel–iron alloys	1707
4.5. Iron–cobalt alloys	1712
4.5.1. Metallurgy of equiatomic Fe–Co alloys	1712
5. Amorphous magnetic materials	1713
5.1. Introduction	1713
5.2. Preparation	1714
5.3. Properties	1716
5.3.1. Curie temperature	1716
5.3.2. Saturation magnetization	1716
5.3.3. Anisotropy	1723
5.3.4. Magnetostriction	1725
5.3.5. Low-field properties	1727
6. Magnetic measurements in metallurgy	1728
References	1730
Further reading	1734
<i>Chapter 27. Superconducting materials, by W.L. Johnson</i>	1735
1. Introduction	1736
2. Background and theory	1736
2.1. Phenomenology	1736
2.2. Microscopic theory	1738
2.3. Inhomogeneous superconducting states: Ginzburg–Landau theory	1742
2.4. Special solutions to the GL equations	1743
2.5. Type-I and type-II superconductors	1747
3. Pure metals	1749
3.1. Simple metals	1749
3.2. Transition metals	1751
4. Superconducting alloys and compounds	1756
4.1. Selected example of materials	1756
4.1.1. Solid solutions	1756
4.1.2. A15 compounds and other special structures	1760
4.1.3. Amorphous alloys	1767
4.2. High T_c ’s, lattice instabilities, and soft phonons	1770
4.3. Flux pinning, critical current, and applications	1773
References	1776
Further reading	1778

<i>Chapter 28. Alloys rapidly quenched from the melt, by R.W. Cahn</i>	1779
1. General features of rapid quenching from the melt	1780
1.1. Experimental methods	1780
1.2. Forms of metastability resulting from rapid solidification processing	1784
1.3. Cooling rates in rapid solidification processing	1785
1.4. Process physics of rapid quenching	1788
1.5. Rapid solidification processing of surfaces	1789
1.5.1. Laser surface treatment	1789
1.5.2. Electron-beam surface treatment	1792
2. Solidification theory of rapid quenching	1793
2.1. The thermodynamic criterion	1793
2.2. The morphological criterion	1796
2.3. The heat-flow criterion	1797
2.4. Glass-forming criteria	1798
2.4.1. The kinetic criterion	1798
2.4.2. Structural glass-forming criteria	1800
3. Metallic glasses	1804
3.1. Structure	1804
3.2. The glass transition and free volume	1812
3.2.1. Free volume	1815
3.3. Relaxation	1816
3.4. Diffusion in metallic glasses	1820
3.5. Crystallization of metallic glasses	1825
3.6. Plastic deformation and fracture	1830
3.7. Other properties of metallic glasses	1835
4. Rapid-solidification-processed crystalline alloys	1836
4.1. General characteristics	1836
4.2. Microcrystalline alloys from glasses	1840
4.3. Steels	1840
4.4. Superalloys	1843
Concluding note	1844
References	1845
Further reading	1851
<i>Chapter 29. Metallic composite materials, by G. Frommeyer</i>	1853
1. Classification	1854
2. Dispersion-strengthened composite materials	1857
3. Particle-reinforced composites	1861
4. Fibre- and laminate-reinforced composites	1866
4.1. Continuous fibres and layers	1866
4.2. Discontinuous fibre composites	1872
4.3. Composites with extremely thin fibres and layers	1877
References	1882

<i>Chapter 30. Sintering processes, by H.E. Exner and E. Arzt</i>	1885
Introduction	1886
1. Solid-state sintering	1886
1.1. Driving energy	1887
1.2. Material sinks and sources	1890
1.3. Neck growth and shrinkage equations	1891
1.4. Development of microstructure and grain growth	1899
2. Hot pressing (pressure-sintering)	1901
2.1. Stresses and mechanisms	1902
2.2. Densification models	1903
2.3. Hot-pressing maps	1906
3. Sintering with a liquid phase	1906
References	1908
Further reading	1911
<i>Author index</i>	1913
<i>Subject index</i>	S1