

# Table of Contents

<b>1. Concerning Methods. By U. Gonser</b> .....	1
1.1 Descriptive Methods .....	2
1.2 Abbreviated Methods .....	2
1.3 Name-Tag Methods .....	4
<b>2. Scanning Acoustic Microscopy</b>	
By M. Hoppe and A. Thaer (With 24 Figures) .....	7
2.1 Principle of Scanning Acoustic Microscopy (SAM) .....	7
2.2 The Image Contrast of Solids in the Reflection Scanning Acoustic Microscope; $V(z)$ -Curves .....	14
2.3 Examples of Practical Applications of Reflection Scanning Acoustic Microscopy .....	18
2.3.1 Grain Structure .....	18
2.3.2 Diffusion Zones .....	21
2.3.3 Materials Defects .....	22
2.4 Outlook .....	27
References .....	27
<b>3. High-Resolution Electron Microscopy</b>	
By F. E. Fujita and M. Hirabayashi (With 30 Figures) .....	29
3.1 Background .....	29
3.1.1 Historical Development .....	29
3.1.2 Conventional vs. High-Resolution Electron Microscopy ..	32
3.2 Basic Principles of High-Resolution Electron Microscopy .....	36
3.2.1 Formation of Lattice Fringe Images .....	36
3.2.2 Formation of Many-Beam Lattice Images .....	38
3.2.3 Image Simulation by the Multislice Method .....	43
3.3 Applications .....	45
3.3.1 Defect and Defect Analysis .....	45
3.3.2 Amorphous Metals and Alloys .....	54
3.3.3 Ordered Alloys and Intermetallic Compounds .....	60
3.3.4 Phase Transformation .....	65
3.3.5 Surface, Grain Boundary and Interface .....	66
3.4 Outlook .....	69
References .....	71

<b>4. Field Ion Microscopy</b>	
By N. Ernst and G. Ehrlich (With 26 Figures) .....	75
4.1 Principles and Techniques .....	77
4.1.1 Magnification, Resolution, and Image Formation .....	77
4.1.2 Field Evaporation and Desorption .....	79
4.1.3 Specimen Preparation .....	81
4.1.4 Image Detection .....	83
4.1.5 Variants of the Field Ion Microscope .....	85
4.1.6 Field Emission Field Ion Microscopy .....	85
4.1.7 The Atom-Probe .....	87
4.2 Illustrative FIM Studies .....	90
4.2.1 Atomic Events on Solids .....	90
4.2.2 Field Evaporation and Desorption Measurements .....	100
References .....	111
<b>5. X-Ray and Neutron Diffraction</b>	
By C.N.J. Wagner (With 16 Figures) .....	117
5.1 Diffraction of Neutrons and X-Rays by Poly- and Non-Crystalline Alloys .....	119
5.1.1 Neutron and X-Ray Scattering .....	119
5.1.2 General Scattering Theory for Solid and Liquid Solutions .....	120
5.1.3 Binary Alloys .....	124
5.1.4 Chemical Short-Range Order in Binary Alloys .....	127
5.1.5 Topological Order in Crystalline Solid Solutions .....	127
5.1.6 Integrated Intensity .....	128
5.2 Experimental Techniques .....	129
5.2.1 X-Ray and Neutron Sources .....	129
5.2.2 Instrumentation .....	130
5.3 Applications .....	132
5.3.1 Structure of Metallic Glasses and Liquids .....	132
5.3.2 Phase Analysis of Poly-Crystalline Mixtures .....	137
5.3.3 Small-Angle Scattering .....	139
5.3.4 Line Profile Analysis of Powder Pattern Peaks .....	140
5.3.5 Residual Stress Measurements .....	144
5.3.6 Grazing Incidence X-Ray Scattering .....	148
References .....	150
<b>6. Extended X-Ray Absorption Fine Structure</b>	
By D.G. Stearns and M.B. Stearns (With 5 Figures) .....	153
6.1 Theory .....	153
6.1.1 Overview .....	153
6.1.2 The Standard EXAFS Formula .....	154
6.1.3 Validity of the Theory .....	159

6.2	Experimental Techniques .....	162
6.3	Analysis .....	165
6.3.1	Basic Manipulations .....	165
6.3.2	Determination of Structural Parameters .....	168
6.3.3	Guidelines for Using EXAFS Spectroscopy .....	170
6.4	Experimental Applications .....	170
6.4.1	Local Environment Surrounding Solute Atoms .....	171
6.4.2	Comparison to Theoretical Models .....	173
6.4.3	Debye-Waller Factors - Mean-Square Displacements ....	175
6.4.4	Structure of Amorphous Metals .....	179
	References .....	190
<b>7.</b>	<b>X-Ray Photoelectron Spectroscopy</b>	
	By G.K. Wertheim (With 14 Figures) .....	193
7.1	Historical .....	193
7.2	Basic Principles .....	194
7.2.1	Photoemission .....	194
7.2.2	The Core-Electron Binding Energy in a Metal .....	195
7.2.3	Core-Electron Satellites .....	197
7.2.4	Plasmons, Electron Mean-Free Path, and Surface Aspects of XPS .....	198
7.2.5	Measurement of Core-Electron Binding Energy by XPS .	200
7.3	Related Methods .....	202
7.3.1	Angle-Resolved Photoemission Spectroscopy (ARPES) .	203
7.3.2	Inverse Photoemission Spectroscopy (IPES) .....	203
7.3.3	X-Ray Absorption Edge Spectroscopy (XAS) .....	203
7.3.4	X-Ray Emission Spectroscopy (XES) .....	204
7.3.5	Auger Electron Spectroscopy (AES) .....	204
7.3.6	Electron Energy Loss Spectroscopy (EELS) .....	205
7.4	Applications .....	205
7.4.1	Chemical Analysis .....	205
7.4.2	Binding Energy Shifts .....	207
7.4.3	Valence Electron Density of States .....	208
7.4.4	Conduction-Electron Screening .....	212
7.5	Recent Developments .....	214
7.5.1	Surface Atoms .....	214
7.5.2	Metal Clusters .....	215
	References .....	216
<b>8.</b>	<b>Auger Electron Spectroscopy</b>	
	By M.P. Seah (With 22 Figures) .....	219
8.1	History .....	221
8.2	Principles .....	223
8.2.1	The Auger Energies .....	223
8.2.2	The Auger Electron Emission Depth .....	226

8.2.3	Quantitative Analysis by AES .....	227
8.2.4	Composition Depth Profiling .....	229
8.2.5	Spatial Resolution in Auger Microscopy .....	231
8.3	The Instrument .....	233
8.4	Related Methods .....	235
8.5	Applications .....	236
8.5.1	Grain Boundary Segregation Studies .....	236
8.5.2	Surface Segregation .....	240
8.5.3	Grain Boundary Diffusion .....	242
8.5.4	Defect-Enhanced Diffusion .....	243
8.5.5	Other Studies .....	244
8.6	Future Developments .....	245
	References .....	246

## 9. Positron Annihilation

	By W. Triftshäuser (With 28 Figures) .....	249
9.1	Background .....	249
9.2	Basic Principles .....	251
9.2.1	Positron Thermalization .....	251
9.2.2	Annihilation Process .....	251
9.3	Experimental Methods .....	255
9.3.1	Positron Sources .....	255
9.3.2	Angular Correlation of Annihilation Photons .....	256
9.3.3	Doppler Broadening of Annihilation Radiation .....	259
9.3.4	Lifetime Measurements of Positrons .....	261
9.3.5	Monoenergetic Positron Beams .....	263
9.4	Applications .....	266
9.4.1	Fermi Surfaces in Metals and Alloys .....	266
9.4.2	Metals at Various Temperatures .....	269
9.4.3	Radiation Induced Defects .....	276
9.4.4	Amorphous Alloys .....	285
9.4.5	Surfaces .....	287
9.5	Conclusions and Outlook .....	288
	References .....	290

## 10. Muon Spectroscopy

	By J. Chappert and A. Yaouanc (With 13 Figures) .....	297
10.1	Basic Principles of the Experimental Techniques .....	297
10.2	The Depolarization Functions .....	300
10.2.1	Slow Dipole Fluctuations .....	300
10.2.2	Dipole Fluctuations and Correlation Functions .....	302
10.3	Diffusion Studies by $\mu^+$ SR .....	303
10.3.1	Standard Theory of the Diffusion of a Light Interstitial in a Metal .....	304
10.3.2	Effects of Impurities and Defects on the $\mu^+$ Damping Rate .....	305

10.3.3	Quantum $\mu^+$ Diffusion in Metals .....	306
10.3.4	Classical $\mu^+$ Diffusion in Metals .....	308
10.3.5	$\mu^+$ Diffusion in Hydrides .....	308
10.4	Magnetic Studies by $\mu^+$ SR .....	309
10.4.1	Static Properties .....	309
10.4.2	Dynamic Properties .....	312
10.5	Conclusions .....	314
	References .....	315
<b>11.</b>	<b>Perturbed Angular Correlation</b>	
	By Th. Wichert and E. Recknagel (With 31 Figures) .....	317
11.1	Background .....	317
11.2	Principles .....	319
11.2.1	Spin Alignment .....	320
11.2.2	Spin Precession .....	323
11.3	Detection of Hyperfine Fields .....	324
11.3.1	Magnetic Dipole Interaction .....	327
11.3.2	Electric Quadrupole Interaction .....	330
11.4	Radioactive Probes, Preparation and Techniques .....	337
11.4.1	Probe Atoms and Sample Preparation .....	337
11.4.2	Data Recording and Analysis .....	340
11.4.3	PAC and Mössbauer Spectroscopy .....	342
11.5	Applications .....	343
11.5.1	Hyperfine Fields at Impurities .....	344
11.5.2	Surface Studies .....	350
11.5.3	Diffusion of Light Gases in Tantalum .....	352
11.5.4	Defects and Impurities .....	355
11.6	Future Developments and Conclusions .....	362
	References .....	363
<b>12.</b>	<b>Nuclear Magnetic Resonance</b>	
	By P. Panissod (With 25 Figures) .....	365
12.1	Introductory Comments .....	365
12.2	Physical Background of an NMR Experiment — Hyperfine Interactions .....	368
12.2.1	Nuclear Paramagnetism .....	368
12.2.2	Thermal Equilibrium and Dynamic Properties of the Spin System .....	369
12.2.3	Electric Interaction — Nuclear Quadrupole Moment ...	370
12.2.4	Summary .....	371
12.3	Basic NMR Experiment — Principles and Setup .....	371
12.3.1	Spin Movement in a Magnetic Field .....	371
12.3.2	Free Induction Decay — Transverse Relaxation Time ...	373
12.3.3	Spin Echo — Homogeneous and Inhomogeneous Broadenings .....	373

12.3.4 Spin-Lattice Relaxation Measurement .....	375
12.3.5 Spectrum Measurement .....	375
12.3.6 NMR Techniques and Instruments .....	376
12.3.7 Phase Coherent Pulsed NMR Spectrometer .....	376
12.3.8 Feasibility of an NMR Observation .....	377
12.4 NMR Outputs — Microscopic Origin .....	380
12.4.1 Hyperfine Fields .....	380
12.4.2 Frequency Shifts .....	382
12.4.3 Relaxation Times .....	384
12.4.4 Electric Field Gradient .....	386
12.4.5 Summary .....	387
12.5 Applications — Structural Investigations .....	388
12.5.1 Phase Analysis .....	388
12.5.2 Chemical Short-Range Order .....	390
12.5.3 Structure of Amorphous Metals .....	391
12.5.4 Atomic Motion in Metals .....	393
12.6 Applications — Electronic and Magnetic Properties .....	395
12.6.1 Local Magnetic Susceptibilities and Moments .....	396
12.6.2 Impurities in Metals .....	398
12.6.3 Magnetic Impurities — Occurrence of Magnetism .....	398
12.6.4 Concentrated Alloys — Local Environment Effects .....	399
12.6.5 Magnetic Structure and Phase Transition .....	400
12.6.6 Spin Fluctuations in Rare Earth Based Compounds .....	403
12.6.7 Electronic Phase Transitions .....	404
12.7 Conclusion and Outlook .....	406
References .....	407
<b>13. Mössbauer Spectroscopy. By U. Gonser (With 19 Figures) .....</b>	<b>409</b>
13.1 History .....	409
13.2 Principles .....	411
13.2.1 Line Width .....	412
13.2.2 Line Shape .....	414
13.2.3 Line Intensity (Recoil-Free Fraction) .....	415
13.3 Mössbauer Isotopes .....	416
13.3.1 Sources .....	417
13.3.2 Absorbers .....	418
13.4 Methodology .....	419
13.4.1 Classical Setup .....	419
13.4.2 Scattering Geometry .....	421
13.5 Hyperfine Interactions .....	422
13.5.1 Isomer Shift .....	422
13.5.2 Magnetic Hyperfine Interaction .....	423
13.5.3 Electric Quadrupole Interaction .....	424
13.5.4 Mixed Interactions .....	425
13.5.5 Polarimetry .....	426

13.6 Relativistic Effects .....	428
13.7 Time-Dependent Effects .....	429
13.8 Applications .....	430
13.8.1 Iron .....	430
13.8.2 Phase Analysis .....	432
13.8.3 Texture .....	435
13.8.4 Defects .....	437
13.8.5 Amorphous .....	438
13.8.6 Relaxation Phenomena .....	443
13.9 Outlook .....	445
References .....	446
<b>Additional References with Titles .....</b>	<b>449</b>
<b>Subject Index .....</b>	<b>451</b>