

# Contents

<b>1. Introduction</b>	1
1.1 Brief Historical Survey	1
1.2 Hydrogen Isotopes	2
1.3 Hydrogen in Metals	4
1.4 Helium in Metals	5
1.5 Organization of the Book	5
<b>2. General Aspects of Tritium</b>	7
2.1 Production of Tritium	7
2.1.1 Natural Tritium Production	7
2.1.2 Tritium Production in Nuclear Reactors	8
2.1.3 Tritium Production in Future Fusion Reactors	8
2.1.4 Tritium Production by Nuclear Explosions	9
2.2 Risks Associated with Tritium	10
2.2.1 Incorporation	10
2.2.2 More Indirect Risks	12
2.3 Discharge of Tritium to the Environment	13
2.4 Tritium Handling in Future Fusion Reactors	14
2.4.1 Multiple Containment	15
2.4.2 Pumping and Recycling	15
Pumps and Impurity Removal	16
Hydrogen Isotope Separation	17
2.4.3 Tritium Breeding Materials	17
2.4.4 Planned Tritium Use at JET	17
2.5 Tritium Waste Handling	18
<b>3. Preparation of Metal Tritides</b>	21
3.1 Electrolytical Charging of Metals with Tritium	21
3.2 Breeding of Tritium in Metals	21
3.3 Tritium Charging of Metals by Means of Nuclear Reactions and Ion Implantation	22
3.4 Tritium Charging of Metals from the Gas Phase	22
3.4.1 Uranium Tritide Storage Containers	24
3.4.2 A Typical Sample Chamber	25
3.4.3 Capacitance Manometers	26
3.4.4 Glove Boxes	28
3.4.5 Material for the First Containment	30

3.5	Tritium Charging of Metals by Means of Metal Tritides . . .	31
3.6	Metals Employed for Tritium Storage . . . . .	32
3.6.1	Uranium Tritide . . . . .	34
3.6.2	Palladium Tritide . . . . .	34
3.6.3	LaNi <sub>5-x</sub> Al <sub>x</sub> Tritides . . . . .	35
3.6.4	Vanadium Tritide . . . . .	36
3.6.5	Tritides of Ti, Zr, La and the Rare Earths . . . . .	36
3.6.6	Stability of Binary and Ternary Metal Tritides . . . . .	37
3.7	Permeability of Tritium in Metals . . . . .	38
<b>4.</b>	<b>Analysis of Tritium in Metals . . . . .</b>	<b>41</b>
4.1	Outgassing and/or Combustion . . . . .	41
4.2	Gas Release Behaviour of MT <sub>r</sub> Samples . . . . .	42
4.3	Tritium Induced X Rays . . . . .	43
4.4	Tritium Imaging . . . . .	45
4.5	Tritium Autoradiography . . . . .	46
<b>5.</b>	<b>Properties of Protium, Deuterium and Tritium</b>	
	<b>in Selected Metals . . . . .</b>	<b>48</b>
5.1	Solubility of Protium, Deuterium and Tritium	
	in Palladium . . . . .	48
5.1.1	Solubility of Protium, Deuterium and Tritium	
	in the $\alpha$ Phase of the Pd-X (X=H,D,T) System . . . . .	48
5.1.2	Solubility of Protium, Deuterium and Tritium in the $\alpha$ ,	
	$\alpha+\beta$ and $\beta$ Phases of the Pd-X (X=H,D,T) System . . .	59
5.2	Solubility of Protium, Deuterium and Tritium	
	in Palladium Silver Alloys . . . . .	63
5.2.1	Solubility of Protium, Deuterium and Tritium in Palladium	
	Silver Alloys for Hydrogen Concentrations $r \leq 0.02$ . . .	65
5.2.2	Solubility of Protium, Deuterium and Tritium in Palladium	
	Silver Alloys for Hydrogen Concentrations $r \leq 0.50$ . . .	69
5.3	Solubility of Protium, Deuterium and Tritium	
	in Lithium and Yttrium . . . . .	72
5.4	Solubility of Protium and Deuterium in Vanadium . . . . .	75
5.5	Isotope Dependence of the Phase Boundaries	
	in the Pd-X, V-X and Nb-X (X = H, D, T) Systems . . . . .	77
5.5.1	Phase Boundaries of the Pd-H, Pd-D and Pd-T Systems	78
5.5.2	The Phase Diagram of the V-T System . . . . .	80
5.5.3	The Phase Diagram of the Nb-T System . . . . .	86
5.6	Optical Vibrations of Protium, Deuterium and Tritium	
	in Niobium . . . . .	87
5.7	Superconductivity of the Pd-H, Pd-D and Pd-T Systems . . .	90
5.8	Isotope Dependence of Phonon Dispersion Curves	
	in PdD <sub>0.63</sub> and PdT <sub>0.7</sub> . . . . .	92
5.9	Isotope Effect in Dingle Temperatures and Extremal Cross	
	Sections of the Fermi Surface in PdH <sub>r</sub> , PdD <sub>r</sub> and PdT <sub>r</sub> . . . .	95

5.10 Diffusion of Protium, Deuterium and Tritium in Selected Metals . . . . .	96
5.10.1 Diffusion of H, D, T in V, Nb, Ta . . . . .	98
5.10.2 Diffusion of H, D, T in Dilute Pd-Fe Alloys . . . . .	101
5.10.3 Diffusion of H, D, T in Cu and Ni . . . . .	103
5.11 Lattice Dilatation in V, Nb, and Ta Produced by Protium, Deuterium and Tritium . . . . .	105
<b>6. Properties of Helium-3 in Selected Metals . . . . .</b>	<b>108</b>
6.1 Basic Properties of Helium in Metals . . . . .	109
6.1.1 Energetics of Helium in Metals . . . . .	109
6.1.2 Kinetics of Helium Precipitation in Metals . . . . .	111
6.2 Helium Release from Metal Tritides . . . . .	112
6.3 He Bubbles in Metal Tritides . . . . .	114
6.3.1 NMR Measurements . . . . .	114
6.3.2 TEM Measurements . . . . .	114
TEM Measurements of PdT <sub>r<sub>0</sub>-c</sub> He <sub>c</sub> Samples . . . . .	115
TEM Measurements of VT <sub>r<sub>0</sub>-c</sub> He <sub>c</sub> Samples . . . . .	115
TEM Measurements of NbT <sub>r<sub>0</sub>-c</sub> He <sub>c</sub> Samples . . . . .	115
TEM Measurements of ZrT <sub>r<sub>0</sub>-c</sub> He <sub>c</sub> Samples . . . . .	116
6.3.3 Observation of Solid-Fluid Transitions of <sup>3</sup> He in the Bubbles of PdT <sub>r<sub>0</sub>-c</sub> He <sub>c</sub> Samples . . . . .	119
6.4 Acoustic Emission by Metal Tritides . . . . .	119
6.5 Swelling of Various Metal Tritides . . . . .	119
6.6 Lattice Parameter and Width of the Rocking Curves of TaT <sub>r<sub>0</sub>-c</sub> He <sub>c</sub> Samples in the α Phase . . . . .	122
6.6.1 X-Ray Diffraction Measurements of TaT <sub>r<sub>0</sub>-c</sub> He <sub>c</sub> . . . . .	123
6.6.2 Neutron-Scattering Measurements of TaT <sub>r<sub>0</sub>-c</sub> He <sub>c</sub> . . . . .	126
6.7 Preliminary Results for Helium-3-Induced Effects in Selected Metals . . . . .	128
6.7.1 Mechanical Properties of Metal Tritides . . . . .	128
6.7.2 He-Induced Change of the Tritium Diffusion in Dilute Tantalum Tritides . . . . .	128
6.7.3 Phase Transitions in Metal Tritides . . . . .	129
6.7.4 Resistivity of Lutetium Tritides . . . . .	131
6.7.5 Analysis of Metal Tritides Using Positron-Annihilation Techniques . . . . .	131
6.7.6 Room-Temperature Creep of Metal Tritides . . . . .	132
<b>7. Conclusion and Outlook . . . . .</b>	<b>134</b>
<b>References . . . . .</b>	<b>137</b>
<b>Subject Index . . . . .</b>	<b>153</b>