

CONTENTS

Foreword	v
Preface	ix
PART ONE. Selection of Material	
<i>by H. W. Gillett</i>	3
PART TWO. Mechanical Properties of Metals in Design	
1 Significance of Mechanical Property Data <i>by H. W. Gillett</i>	11
2 High-temperature Considerations in Design	
2.1 Power Plants <i>by H. D. Emmert and Robert Matters</i>	18
2.2 Petroleum Heaters <i>by M. W. Barnes</i>	29
3 Plasticity Considerations in Design <i>by Evan A. Davis</i>	32
4 Residual Stresses <i>by Oscar J. Horger</i>	42
5 Vibration Considerations in Design <i>by N. O. Myklestad</i>	63
6 Fatigue Characteristics	
6.1 Types of Stress <i>by Herbert F. Moore</i>	80
6.2 Stress Range <i>by Thomas J. Dolan</i>	82
6.3 Method of Testing <i>by Thomas J. Dolan</i>	89
6.4 Physical Properties <i>by Thomas J. Dolan</i>	93
6.5 Surface Finish <i>by B. C. Hanley and Thomas J. Dolan</i>	100
6.6 Fillets, Oil Holes, and Keyways <i>by R. E. Peterson</i>	107
6.7 Grain Flow <i>by R. L. Templin, E. C. Hartmann, and F. M. Howell</i>	112
6.8 Shot Peening <i>by Herbert F. Moore</i>	121
6.9 Cold Working <i>by Oscar J. Horger</i>	123

6.10	Decarburization <i>by Oscar J. Horger</i>	134
6.11	Case Carburizing <i>by Herbert F. Moore and Walter H. Bruckner</i>	138
6.12	Nitriding <i>by Carl F. Floe</i>	144
6.13	Metallic Coatings <i>by R. R. Moore</i>	148
6.14	Flame Strengthening <i>by J. H. Zimmerman</i>	166
6.15	Riveted Structural Joints <i>by W. M. Wilson</i>	169
6.16	Bolted Joints <i>by W. C. Stewart</i>	171
6.17	Press-fitted Assembly <i>by Oscar J. Horger</i>	178
6.18	Welded Structural Joints <i>by W. M. Wilson</i>	190
6.19	Overstressing and Understressing in Fatigue <i>by J. B. Kommers</i>	192
7	Wear Considerations in Design <i>by H. W. Gillett</i>	198
8	Impact Considerations in Design <i>by W. P. Welch</i>	202
PART THREE. Mechanical Factors Influencing Corrosion		
1	Stress Corrosion, Corrosion Fatigue, and Erosion Corrosion <i>by H. R. Copson</i>	217
2	Fretting Corrosion and Fatigue <i>by George Sachs</i>	230
PART FOUR. Metallurgical Factors in Design		
1	Nondestructive Testing	
1.1	Magnetic-particle Inspection <i>by C. E. Betz</i>	237
1.2	Ultrasonic Testing and Inspection <i>by John C. Smack</i>	240
1.3	X-ray Examination <i>by R. M. Landis</i>	251
1.4	Electrical Methods <i>by G. R. Greenslade and W. J. Eisenbeis</i>	260
1.5	Core-loss Principle <i>by P. E. Cavanagh and R. T. Cavanagh</i>	267
1.6	Magnetic and Electromagnetic Methods <i>by G. R. Greenslade and W. J. Eisenbeis</i>	270

PART FIVE. Processing Considerations in Design

- | | | |
|---|---|-----|
| 1 | Designing for Production
<i>by Roger W. Bolz</i> | 277 |
| 2 | Surface-finish Requirements in Design
<i>by James A. Broadston</i> | 284 |

PART SIX. Design Procedures

- | | | |
|-----|--|-----|
| 1 | Design Practice
<i>by Charles Lipson and G. C. Noll</i> | 297 |
| 2 | Design Theory | |
| 2.1 | Elements of Theory of Elasticity
<i>by S. Timoshenko and Joseph Marin</i> | 306 |
| 2.2 | Theories of Failure
<i>by Joseph Marin</i> | 317 |
| 2.3 | Working Stresses
<i>by Joseph Marin</i> | 328 |
| 3 | Experimental Design | |
| 3.1 | Strain Gages
<i>by C. O. Dohrenwend</i> | 332 |
| 3.2 | Brittle Coating
<i>by Greer Ellis</i> | 345 |
| 3.3 | Photoelasticity
<i>by Max M. Frocht</i> | 347 |
| 4 | Plates and Shells
<i>by I. A. Wojtaszak and W. A. Nash</i> | 361 |
| 5 | Magnesium
<i>by J. C. Mathes</i> | 384 |
| 6 | Aluminum
<i>by E. C. Hartmann</i> | 390 |

INDEX	401
--------------	-----