

Contents

1 Production of atomic defects in metals (P. JUNG)	1
1.1 Introduction	1
1.1.1 General remarks	1
1.1.2 Definitions	1
1.1.3 Symbols and units	1
1.1.4 Abbreviations	2
1.2 Methods to produce atomic defects in metals	3
1.3 Stability of atomic defects in metals	3
1.4 Methods to determine concentrations of atomic defects in metals	4
1.5 Production of atomic defects in metals in thermal equilibrium	4
1.6 Production of atomic defects in metals by plastic deformation	5
1.7 Production of atomic defects in metals by irradiation	6
1.7.1 Production of atomic defects in pure, polycrystalline metals	8
1.7.1.1 Electron irradiation	8
1.7.1.2 Ion irradiation	11
1.7.1.3 Ion implantation	13
1.7.1.4 Thermal neutron irradiation	14
1.7.1.5 Fission neutron, fast neutron, and fission fragment irradiation	15
1.7.2 Production of atomic defects in pure, single crystalline metals	16
1.7.2.1 Displacement energy maps	16
1.7.2.2 Average displacement energy	18
1.7.3 Production of atomic defects in predamaged metals	19
1.7.3.1 Quenched metals	19
1.7.3.2 Deformed metals	19
1.7.3.3 Preirradiated metals	20
1.7.4 Production of atomic defects in metals at high defect densities	20
1.7.4.1 Subthreshold effects	20
1.7.4.2 Defect saturation	21
1.7.4.3 Cascade production	24
1.7.5 Production of atomic defects in alloys	26
1.7.5.1 Dilute alloys	26
1.7.5.2 Concentrated alloys	27
1.7.5.3 Ordered alloys	27
1.7.6 Production of atomic defects in metallic glasses	31
1.7.7 Surface effects	31
1.7.7.1 Threshold energy for sputtering	31
1.7.7.2 Energy dependence of the sputtering yield	33
1.7.7.3 Dependence of the sputtering yield on crystal orientation	33
1.7.7.4 Temperature dependence of the sputtering yield	33
1.7.8 Temperature effects on the production of atomic defects in metals	34
1.7.9 Computer simulation of atomic defect production	34
1.7.9.1 Computer simulation of low energy events	34
1.7.9.2 Computer simulation of high energy cascades	35
1.7.9.3 Computer simulation of temperature effects on atomic defect production	36
Figures for 1	37
References for 1	77

2 Properties and interactions of atomic defects in metals and alloys	88		
2.1 Introduction (P. EHRHART)	88		
2.1.1 General remarks	88		
2.1.2 Frequently used symbols and abbreviations	90		
2.1.3 Characterization of interstitial atoms and vacancies	92		
2.1.3.1 Formation entropies and energies and equilibrium concentrations	92		
2.1.3.2 Structure of defects and their agglomerates	93		
2.1.3.3 Defect dynamics, migration energies and jump frequencies	95		
2.1.3.4 Defect-solute interaction	98		
2.1.3.5 Defect reactions and annealing stages	100		
2.1.4 Experimental methods	102		
2.1.4.1 Residual electrical resistivity ($\Delta\varrho$)	102		
2.1.4.2 Calorimetry (Cal)	102		
2.1.4.3 Differential dilatometry (DD)	103		
2.1.4.4 Diffuse scattering of X-rays or neutrons, Huang scattering (DXS)	103		
2.1.4.5 Extended X-ray absorption fine structure (EXAFS)	104		
2.1.4.6 Inelastic neutron scattering (INS)	104		
2.1.4.7 Mechanical relaxation (elastic after-effect, internal friction, ultrasonic attenuation) (MechR)	104		
2.1.4.8 Magnetic relaxation (MagR)	104		
2.1.4.9 Change of the elastic constants (Δc_{ij})	105		
2.1.4.10 Mössbauer spectroscopy (MS)	105		
2.1.4.11 Perturbed angular correlation (PAC)	105		
2.1.4.12 Positron annihilation spectroscopy (PAS)	106		
2.1.4.13 Muon spin rotation experiments (μ SR)	106		
2.1.4.14 Nuclear magnetic resonance (NMR)	106		
2.1.4.15 Ion channeling (Chann)	107		
2.1.4.16 Transmission electron microscopy (TEM)	107		
2.1.4.17 Field ion microscopy (FIM)	107		
2.1.4.18 Thermal helium desorption spectroscopy (THDS)	107		
Figures for 2.1	108		
References for 2.1	363		
2.2 bcc metals (H. SCHULTZ)	115		
2.2.1 Special remarks	115		
2.2.2 Concepts of data evaluation	121		
2.2.3 Data	122		
Cr 122	Fe 125	K 135	Li 138
Mo 140	Na 147	Nb 149	Ta 161
V 173	W 179		
References for 2.2	191		
2.3 fcc metals (P. EHRHART)	202		
2.3.1 Special remarks	202		
2.3.2 Data	203		
Ag 203	Al 211	Au 224	Ce 230
Cu 231	Ir 241	Ni 242	Pb 250
Pd 254	Pt 256	Rh 262	Th 263
References for 2.3	363		
2.4 hcp metals (P. EHRHART)	264		
2.4.1 Special remarks	264		
2.4.2 Data	265		
Be 265	Cd 266	Co 271	Mg 274
Re 278	Sc 281	Tl 282	Ti 282
Y 284	Zn 284	Zr 288	RE 296
References for 2.4	363		
2.5 Metals with other structures (P. EHRHART)	304		
2.5.1 Special remarks	304		

2.5.2 Data	304		
Bi 304	Ga 306	Hg 307	In 308
Sb 309	Sn 310	U 312	
References for 2.5	363		
2.6 Concentrated alloys (P. EHRHART)	313		
2.6.1 Special remarks	313		
2.6.2 Data	316		
AgAl 316	AgAu 318	AgZn 320	AlCu 322
AlFe 324	AlNi 329	AuCu 332	CoFe 338
CoPt 343	CrFe 343	CrFeNi 345	CrNi 349
CuMn 351	CuNi 352	CuZn 354	FeNi 358
MnNi 360	MoNi 361	superconducting alloys	361
References for 2.1 and 2.3 . . . 2.6	363		
3 Helium in metals (H. ULLMAIER)	380		
3.1 Introduction	380		
3.1.1 General remarks	380		
3.1.2 Symbols and abbreviations	381		
3.1.3 Experimental and theoretical methods	383		
3.2 Production processes and rates	385		
3.2.1 (n, α)-Reactions	385		
3.2.2 Other nuclear reactions	386		
3.2.3 Implantation	386		
3.2.4 Concurrent displacement damage	388		
3.2.5 Tritium decay	388		
3.3 Atomistic properties	389		
3.3.1 Interstitial and substitutional solubility	389		
3.3.2 Binding to defects	391		
3.3.3 Diffusion	395		
3.4 Clusters and bubbles	397		
3.4.1 Formation without vacancy clustering	397		
3.4.2 Nucleation involving vacancy migration	398		
3.4.3 Growth and coarsening	400		
Figures for 3	402		
References for 3	432		
Subject index for 3	436		