

Contents

Phase Diagrams and Physical Properties of Nonequilibrium Alloys

Subvolume A: Nonequilibrium phase diagrams of ternary amorphous alloys

1	Introduction	
1.1	IMR data project (Y. KAWAZOE)	1
1.2	Introductory remarks (J.-Z. YU)	2
1.2.1	Data source and distribution	2
1.2.2	Classification of preparation methods and formation data	6
1.2.3	Presentation of formation data	7
1.2.4	Acknowledgements	8
1.3	Process and technology (A.-P. TSAI)	9
1.3.1	Liquid quenching process	9
1.3.1.1	Splat cooling	10
1.3.1.2	Single roller melt-spinning	10
1.3.1.3	In-rotating water melt spinning	10
1.3.1.4	Metallic mold casting	10
1.3.1.5	Gas atomization	11
1.3.2	Sputtering (gas condensation)	11
1.3.3	Solid state reaction	12
1.3.4	References for 1.3	12
1.4	Formation of amorphous alloys (T. AIHARA JR.)	13
1.4.1	Glas transition	13
1.4.2	Structural and dynamical properties through glass transition	14
1.4.3	Control of crystallization	17
1.4.4	Forming ability of amorphous alloys	17
1.4.5	References for 1.4	19
1.5	Recent progress of amorphous and amorphous based metallic materials (T. MASUMOTO)	20
1.5.1	Preliminary remarks	20
1.5.2	High strength light-weight amorphous alloys	21
1.5.3	Nanocrystals-dispersed amorphous alloys	22
1.5.4	A new class of soft magnetic materials having a nanocrystalline structure	25
1.5.5	More stable amorphous alloys with a wide super-cooled liquid region	26
1.5.6	New working processes by utilizing the large viscous flowability near T_g	29
1.5.7	Industrial applications of amorphous metallic materials	30
1.5.8	References for 1.5	32
2	Data	33
2.1	List of ternary amorphous alloys	33
2.2	Phase diagrams	35
2.3	Composition tables	101
3	References for 2	269

