

Contents

***Part I* Temperature Measurements in the Range from 0.1 K to 300 K**

Introduction	3
List of Symbols	5
 Chapter 1 The Concept of Temperature	 9
1.1. Definitions of Temperature	10
1.1.1. The Phenomenologic Approach	10
1.1.2. The Axiomatic Approach	16
1.1.3. The Microscopic Approach	19
1.1.4. Negative and Nonequilibrium Thermodynamic Temperatures ...	21
1.2. Temperature Scales	22
1.2.1. Thermodynamic Temperature	25
1.2.2. Empirical Temperature	29
1.2.3. Official Temperature Scales	34
1.3. Summary of a Temperature Scale Definition	36
 Chapter 2 Gas-Based Reference Points for Thermometry	 37
2.1. Thermodynamic States versus Standard Reference Materials	38
2.1.1. Substances and Standard Reference Materials	38
2.1.2. Thermodynamic States and Phase Diagrams	40
2.1.3. Reference Points: Triple, Boiling, and Critical Points	42
2.2. Physics Associated with Gas Triple Points	42
2.2.1. Triple Point of a Pure Substance	43
2.2.2. Triple Point of an Impure Substance. Cryoscopy	47
2.3. The Realization of Temperature Fixed Points Using Gas Triple Points	53
2.3.1. Thermal Problems in the Design of Triple-Point Cells	54
2.3.2. Chemicophysical Problems in Triple-Point Realizations	62

2.3.3. The Technique of Sealed Cells for the Realization of a Temperature Reference	68
2.4. Modern Design of Temperature Fixed Points Based on the Triple Point of Gases	75
2.4.1. Sealed Cells for Capsule Thermometers	76
2.4.2. Sealed Cells for Long-Stem Thermometers	80
2.5. Fixed Points Using Other Phase Transitions	85
2.5.1. Liquid-to-Liquid Transitions	85
2.5.2. Solid-to-Solid Transitions	88
2.6. The ITS-90 between 13.80 K and 273.16 K and Scale Approximations Using Sealed Fixed Points	90
2.6.1. Realization of the ITS-90 in the Laboratories	91
2.6.2. Approximating the ITS-90	93
2.7. Gaseous Standard Reference Materials and Sealed Cells	97
2.8. Summary of Triple-Point Sealed-Cell Design Criteria	98
2.9. Summary of Sealed-Cell Fabrication Techniques	99
2.10. Summary of the Sealed-Cell Measurement Procedures by Step-Melting	101

Chapter 3 Gas Thermometry between 0.5 K and 273.16 K 103

3.1. Constant-Volume Gas Thermometry	104
3.1.1. Influence of Physical Parameters	106
3.1.2. Influence of Technical Parameters	116
3.1.3. Gas Thermometer with Built-in Pressure-Measuring Device	129
3.2. Interpolating Constant-Volume Gas Thermometers	133
3.2.1. ICVGT Types with Stipulation of the Virial Function	139
3.2.2. ICVGT Types without Stipulations	142
3.3. Gas Thermometer Realization	148
3.3.1. CVGTs with Reference at Temperatures Lower than 273.16 K	149
3.3.2. CVGTs with Reference Temperature at 273.16 K	156
3.3.3. CVGTs Using a Cryogenic Pressure-Measuring Gauge	158
3.3.4. Realizations of Interpolating Gas Thermometers	160
3.4. Gas Thermometry in the ITS-90, and Future Development	161
3.5. Dielectric Constant, Refractive Index, and Acoustic Gas Thermometers	163
3.5.1. Dielectric Constant Gas Thermometer	163
3.5.2. Refractive Index Gas Thermometer	167
3.5.3. Acoustic Thermometer	169
3.6. Summary of Design Criteria for an Absolute CVGT in the Low-Temperature Range	173
3.7. Summary of Differences and Simplifications in Design Criteria of an ICVGT	175
3.8. Summary of the Measurements Procedures for an Absolute CVGT in the Low-Temperature Range	177
3.9. Summary of Differences and Simplifications in Measurements Procedures for an ICVGT	178

Chapter 4	Vapor-Pressure Thermometry	179
4.1.	Influence of Physical Parameters	182
4.1.1.	Purity of the Substance	182
4.1.2.	Amount of Substance	189
4.2.	Influence of Technical Parameters	191
4.2.1.	Thermometer with Gauge for Pressure Measurement at Room Temperature	191
4.2.2.	Use of Sealed Cells for Vapor-Pressure Measurements	196
4.2.3.	Thermometer with Gauge for Pressure Measurement at Low Temperature	198
4.2.4.	Liquid-Vapor versus Solid-Vapor Equilibria	199
4.3.	Realization of Vapor-Pressure Temperature Scales	200
4.3.1.	Equations for Vapor Pressure	201
4.3.2.	Helium Vapor Pressure	204
4.4.	Summary of Design Criteria for Vapor-Pressure Thermometers	213
4.5.	Summary of Fabrication Techniques for Vapor-Pressure Thermometers	216
4.6.	Summary of Measurement Procedures with Vapor-Pressure Thermometers	217
 Chapter 5	 Thermometry Based on the Melting Line of ^3He	 219
5.1.	The ^3He Melting-Line Thermometer	221
5.1.1.	Melting-Line Experiment below T_{min}	223
5.1.2.	Melting-Line Experiment above T_{min}	224
5.1.3.	Pressure and Temperature Measurement	225
 Chapter 6	 Cryostats for Thermometry and Gas-Based Temperature Control	 227
6.1.	Cryostats	227
6.1.1.	Refrigerator-Based Cryostats	227
6.1.2.	Liquid-Refrigerant Cryostats	230
6.2.	Temperature Control in Thermometry and Gas-Based Temperature Controls	234
6.2.1.	Control of the Cryogen Bath Temperature	235
6.2.2.	Vapor Flow Technique	236
6.2.3.	Passive Thermostats	236
6.2.4.	Self-Regulated Passive Shields	236
6.2.5.	Gas-Filled Heat Switches	237
6.3.	Strategy for Cryostat Selection	241
 References to Part I		 245
 Further Readings		 261

Part II Pressure Measurements in the Range from 10^2 Pa to 10^8 Pa

Introduction	265
List of Symbols	267
Chapter 7 Primary Standards for Pressure Measurements	273
7.1. Liquid-Column Manometers for Pressure Measurements	280
7.1.1. Operating Principles and General Precautions for Absolute Pressure Measurements below 0.3 MPa	281
7.1.2. Basic Apparatus in Metrological Laboratories—Different Methods for Height Measurements	284
7.1.3. Calculations Applicable with Mercury-Column Manometers. Pressure Measurement Uncertainty	295
7.1.4. Liquid Columns for Different Applications	305
7.2. Gas-Operated Piston Gauges	307
7.2.1. Basic Description	308
7.2.2. Absolute Pressure Measurements up to 5 MPa	313
7.2.3. Gauge Pressure Measurements up to 100 MPa	324
7.2.4. Uncertainty of Absolute and Gauge Pressure Measurements	334
7.2.5. Differential Gas Pressure Measurements	336
7.2.6. Results of Comparison Measurements in Gas Media	339
7.2.7. Comparisons of Liquid-Column Manometers and Piston Gauges	344
7.2.8. What Future for Primary Pressure Standards?	352
7.3. Summary of Typical Uncertainty Levels for Liquid-Column Manometers and Piston Gauges	353
Chapter 8 Pressure Transducers for Gaseous Media	357
8.1. Transfer Standards for Absolute Pressure Measurements below 120 kPa	359
8.1.1. Transfer Standards for Atmospheric Pressure Measurements	362
8.1.2. Transfer Standards for Gas Pressure Measurements from 100 Pa to 10 kPa	368
8.2. Transfer Standards for Pressure Measurements up to 100 MPa	370
8.3. Transducers Used for Differential Pressure Measurements and as Null Detectors	377
8.3.1. Differential Pressure Transducers for High Line Pressures	377
8.3.2. Differential Pressure Transducers Used as Null Detectors	380
8.4. Transducers for Pressure Measurements in Cryogenic Environments	383
8.4.1. Strain-Gauge Pressure Transducers for Cryogenic Applications	386
8.4.2. Resonant- and Capacitance-Type Pressure Transducers for Cryogenic Applications	391
8.5. Glossary: Terms used in the Metrological Characterization of a Pressure Transducer	395
8.6. Typical Procedure for the Static Calibration of a Pressure Transducer in Gaseous Media	397

Chapter 9	Gas-Based Pressure Fixed Points	401
9.1.	The Pressure Scale from 10^2 Pa to 10^8 Pa Based on Fixed Points	403
9.1.1.	Triple Points	405
9.1.2.	Other Pressure Fixed Points	406
9.2.	Experiences in the Use of Fixed Points as Pressure Transfer Standards	407
9.3.	Summary of Possible Fixed Points to Be Used as Transfer Standards for Gas Pressure Measurements from 100 Pa to Approximately 100 MPa	411
Chapter 10	The Thermomolecular Pressure Difference Effect	415
10.1.	The Calculation of the Thermomolecular Pressure Difference	416
10.2.	Experimental Measurements of the Thermomolecular Pressure Difference	423
10.3.	General Considerations on Experimental Measurements and Theoretical Calculations of the Thermomolecular Pressure Difference	429
	References to Part II	431
	Further Readings	441
Appendix A	The International Temperature Scale of 1990	443
Appendix B	List of Temperature and Pressure Fixed Points	457
Appendix C	Reference Data on Gases	461
Appendix D	Vapor Pressures	481
Appendix E	Reference Data for Liquid-Column Manometers	489
Appendix F	Reference Data for Piston Gauges	495
Index		503