

Contents

Chapter 1	Laser Parameters and Measurements	1
1.0	Introduction	1
1.1	Principal Laser Parameters	1
1.2	Treatment of Experimental Data	3
1.3	References	10
1.4	Principal Symbols, Notations, and Abbreviations	10
Chapter 2	Beam Sampling Techniques	11
2.0	Introduction	11
2.1	Amplitude Division	11
2.2	Sampling by Beam Scattering	19
2.3	Induced Fluorescence	20
2.4	Harmonic Conversion	21
2.5	Photo Decomposition	21
2.6	Resonant Transition Monitoring in Infrared Gas Lasers	21
2.7	The Sources of Error in Beam Monitoring	22
2.8	References	23
2.9	Principal Symbols, Notations, and Abbreviations	23
Chapter 3	Measurement of Beam Parameters	25
3.1	Introduction	25
3.2	Measurement of Transverse Intensity Distribution and Beam Divergence	35
3.3	Determination of the Number of Modes	63
3.4	Determination of Polarization	76
3.5	Measurement of Beam-Spot Size	81

3.6	Precision Measurement of Atmospheric Dispersion	82
3.7	References	88
3.8	Principal Symbols, Notations, and Abbreviations	91
Chapter 4	Measurement of Energy and Power	93
4.0	Laser Radiometry	93
4.1	Definitions and Units	95
4.2	Calorimetric Methods	98
4.3	Photoelectric Methods	103
4.4	Photochemical Methods	108
4.5	Mechanical Methods	111
4.6	Non-linear Field Methods	113
4.7	Energy-Density Measurements	114
4.8	Standards and Calibration	117
4.9	Attenuators	119
4.10	Qualitative Measurement of Laser-Energy Density and Intensity	122
4.11	Techniques for Optical Detection	123
4.12	References	190
4.13	Principal Symbols, Notations, and Abbreviations	195
Chapter 5	Measurement of Gain Parameters	199
5.0	Introduction	199
5.1	Methods of Measuring Optical Gain	212
5.2	Measurements of Electron Energy, Energy Density, and Temperature in Gas-Laser Plasmas	245
5.3	Techniques for Measurement of Lifetime	248
5.4	Technique for Determining the Degree of Population Inversion in Q -Switched Lasers	265
5.5	Determination of Cavity Losses	269
5.6	References	282
5.7	Principal Symbols, Notations, and Abbreviations	285
Chapter 6	The Measurement of Wavelength	289
6.0	Introduction	289
6.1	Line Broadening and Light Sources	290
6.2	Optical-Wavelength-Measuring Apparatus	296
6.3	Wavelength Standards	318
6.4	Measurement and Reduction of Data from Spectrographs	320
6.5	References	322
6.6	Principal Symbols, Notations, and Abbreviations	324

Chapter 7	Measurement of Band Width and Temporal Coherence	327
7.0	Introduction	327
7.1	Interferometric Measurements of Line Width	343
7.2	Measurement of Fluorescent Line Width	357
7.3	Direct Method of Measuring Doppler Line Width	358
7.4	Technique for Measuring Gain Narrowing in a Laser Amplifier	359
7.5	Technique for Measuring Gas-Laser Spectral Line Shape Using Excess Photon Noise	367
7.6	Technique of Tilted-Plate Line Selection in a Solid-State Laser	364
7.7	References	366
7.8	Principal Symbols, Notations, and Abbreviations	362
Chapter 8	Measurement of Frequency Stability	370
8.1	Definitions of Stability	370
8.2	The Frequency Stability of Lasers and its Magnitude	374
8.3	Measurement of Short-Term Stability	377
8.4	Measurement of Long-Term Stability	388
8.5	A Technique for Laser Absolute Wavelength Stability Measurement	398
8.6	References	408
8.7	Principal Symbols, Notations, and Abbreviations	410
Chapter 9	Measurement of Noise and Modulation of Laser Carriers	413
9.0	Introduction	413
9.1	Sources of Noise in Coherent Optical Systems	414
9.2	Expanded Definition of Noise in Coherent Systems	414
9.3	Laser Noise	419
9.4	General Method of Measuring Noise Performance of Nonresonant Amplifiers	431
9.5	Laser Amplifier	437
9.6	Errors in Interpretation of Laser Noise	441
9.7	Sources of More Extensive Treatments of Laser Noise Theory	442
9.8	Measurement of Modulation	442
9.9	Measurement of Single-Side-band Modulated Light	450
9.10	Direct Detection of Amplitude-Modulated Light	453
9.11	Direct Detection of Frequency-Modulated or Phase-Modulated Light	457

9.12 Measurement of Optical Modulation by Heterodyne Detection	471
9.13 Rejection of Coherent Interference	476
9.14 References	478
9.15 Principal Symbols, Notations, and Abbreviations	481
Index	485