

Contents

1 • Introduction	1
<i>A. J. Martin and D. R. Adolphson</i>	
2 • Flow and Fracture of Single Crystals	7
<i>Fritz Aldinger</i>	
1. Introduction	7
2. Nature of Interatomic Bondings in Beryllium	9
3. General Mechanical Behavior of Hexagonal Metals with Respect to Beryllium	11
3.1. Crystallography	12
3.2. Deformation Modes	14
3.3. Stacking Faults	16
3.4. Primary Slip Systems	22
3.5. Secondary Slip Systems	27
3.6. Fracture Modes	28
3.7. Conclusion	29
4. General Aspects for Testing Beryllium Single Crystals	29
4.1. Crystal Orientation	29
4.2. Geometry of Specimens	32
4.3. Strain Rate	32
4.4. Strain Resolution	32
4.5. Purity	34
5. Basal Slip (0001) $\langle 11\bar{2}0 \rangle$	36
5.1. Critical Resolved Shear Stress	36
5.2. Stress–Strain Behavior	50
5.3. Strain at Fracture	58
6. Prismatic Slip $\{10\bar{1}0\}$ $\langle 11\bar{2}0 \rangle$	60
6.1. Critical Resolved Shear Stress	60

6.2. Stress–Strain Behavior	70
6.3. Strain at Fracture	77
7. Pyramidal Slip $\{11\bar{2}2\}$ $\langle 11\bar{2}3 \rangle$	79
7.1. Critical Resolved Shear Stress	80
7.2. Stress–Strain Behavior	84
7.3. Strain at Fracture and Pyramidal Fracture	88
8. Twinning	89
9. Fracture	91
9.1. Basal Cleavage	92
9.2. $\{11\bar{2}0\}$ Prismatic Cleavage	104
9.3. Pyramidal Fracture	105
9.4. Twin Boundary Cleavage	106
10. The Brittleness Problem in Beryllium	106
References	107
3 • Flow and Fracture of Polycrystalline Beryllium	115
<i>H. J. Saxton and G. J. London</i>	
1. Introduction	115
2. Atomic Structure	117
3. Single Crystals	118
3.1. Deformation and Failure Mechanisms	118
3.2. Purity	121
3.3. Taylor–von Mises Criterion	123
4. Bicrystals	126
4.1. Deformation Behavior	126
5. Polycrystals	133
5.1. Single Crystal–Polycrystal Correlation	133
5.2. Ductility Improvement	133
6. Structures	138
7. Summary	142
References	143
4 • Grain Size Effects	145
<i>Graham I. Turner</i>	
1. Introduction	145
2. Polycrystalline Strength	146
2.1. Taylor Orientation Factor	146
2.2. Resistance of Grain Boundaries to Deformation	147
2.3. Grain Boundary Structure	150

3. Grain Size Development and Measurement in Beryllium	151
3.1. Grain Size Development	151
3.2. Grain Size Measurement	155
4. Uniaxial Tensile Properties	156
4.1. Strengths	156
4.2. Ductility	165
4.3. Brittle-to-Ductile Transition	171
5. Other Properties	173
5.1. Indentation Hardness	173
5.2. Impact Properties	175
5.3. Superplasticity	175
6. Summary	176
References	176
5 • Impurity Effects in Beryllium	181
<i>A. James Stonehouse</i>	
1. Introduction	181
2. Distribution of Impurity Phases	182
2.1. General Remarks	182
2.2. Low-Solubility Metallic Impurities	183
2.3. Soluble Metallic Impurities	184
2.4. Nonmetallic Impurities	185
2.5. The Ternary Al–Fe–Be Compound	187
3. Effect of Specific Impurities upon Mechanical Behavior	189
3.1. Fe/Al Effects at Room and Elevated Temperatures	189
3.2. Yield Point Phenomena	196
3.3. Effects of BeO	198
3.4. Effects of Low-Melting Impurities and BeO in High- Temperature Creep and Beryllium Powder Consolidation .	199
4. Overall Purity Levels and Mechanical Behavior	202
References	204
6 • Recrystallization and Grain Growth in Beryllium	207
<i>Donald Webster</i>	
1. Introduction	207
2. Recrystallization	208
2.1. Microstructural Changes during Recrystallization	208
2.2. Property Changes during and after Recrystallization	215
2.3. Factors Affecting Recrystallization Temperature	224

3. Grain Growth	227
4. Recommendations for Future Work	231
5. Summary	232
References	233
7 • Constitution of Beryllium and Its Alloys	235
<i>F. Aldinger and G. Petzow</i>	
1. Introduction	235
2. Crystal Structure	236
3. Electronic Structure	237
3.1. Influence of Temperature and Pressure	239
3.2. Influence of Alloying	241
4. Phase Stability	241
4.1. Phase Transformations	241
4.2. Heat Capacity	242
4.3. Vapor Pressure	243
4.4. Enthalpy and Entropy	243
4.5. Relative Phase Stability	244
4.6. Influence of Pressure	245
4.7. Influence of Alloying	246
5. Solid Solubility	248
6. Intermetallic Phases	252
7. Binary Phase Diagrams	257
7.1. Silver–Beryllium	261
7.2. Aluminum–Beryllium	262
7.3. Boron–Beryllium	263
7.4. Beryllium–Cobalt	265
7.5. Beryllium–Copper	266
7.6. Beryllium–Iron	267
7.7. Beryllium–Nickel	268
7.8. Beryllium–Silicon	273
8. Ternary Phase Diagrams and Intermetallic Phases	274
Bibliography of Ternary Beryllium Phase Diagrams	274
References	295
8 • Elevated Temperature Behavior	307
<i>Niels R. Borch</i>	
1. Introduction	307
2. High-Purity Beryllium	307
2.1. Definition	307

2.2. Tensile Properties	308
2.3. Creep	308
3. Low-Purity (Ingot) Beryllium	312
3.1. Definition	312
3.2. Impurity Reactions and Effects	312
3.3. Texture	313
3.4. Tensile Properties at Elevated Temperatures	313
3.5. Creep	315
4. Powder-Source Beryllium	316
4.1. Impurity Effects	316
4.2. Grain Size and Recrystallization	317
4.3. Substructure	318
4.4. Texture	318
4.5. Tensile Properties	319
4.6. Creep	322
5. Recommendations for Future Work	329
References	329

<i>Index</i>	331
--------------------	-----