

Contents

1 • Extraction	1
<i>Kenneth A. Walsh</i>	
1. History	1
2. Occurrence	1
2.1. Commercially Important Minerals	2
2.2. Minor Minerals	3
3. Industrialized Extraction Processes	4
3.1. Fluoride Process	4
3.2. Sulfate Process	5
3.3. Extraction from Bertrandite	6
4. Production of Metallic Beryllium	7
4.1. Reduction of Beryllium Fluoride with Magnesium	7
4.2. Electrolytic Processes	9
5. Melting and Casting	9
6. Summary	10
References	10
2 • Comminution and Consolidation	13
<i>Norman P. Pinto</i>	
1. Introduction	13
2. Comminution	14
2.1. Production Powder-Making	14
2.2. Alternate Powder-Making Methods	18
3. Consolidation	22
3.1. Hot-Pressing	23
3.2. Hot-Isopressing	25
	ix

3.3. Sintering	26
3.4. Hot-Working	27
References	28
3 • Casting	31
<i>R. W. Krenzer</i>	
1. Introduction	31
2. Chemical Purity and Solidification	32
3. Melting Techniques	33
3.1. Static Casting	33
3.2. Centrifugal Casting	42
4. Cast Structure	43
4.1. Controlled Solidification of Beryllium	44
4.2. Grain Refinement	47
5. Future Developments in Casting Technology	51
References	54
4 • Metalworking I: Rolling	57
<i>W. W. Leslie</i>	
1. Introduction	57
2. Powder-Source Beryllium Rolling	58
3. Ingot-Source Beryllium Rolling	58
4. Canned Rolling	59
5. Bare Rolling	63
6. Foil Rolling	65
7. Summary	66
References	66
5 • Metalworking II: Extrusion	67
<i>Paul Loewenstein</i>	
1. Background	67
2. Properties of Beryllium Affecting Extrusion Process	68
3. Extrusion Technique for Beryllium	68
3.1. Bare Extrusion	68
3.2. Canned Extrusion	69
3.3. Extrusion Tools	73
3.4. Extrusion Conditions and Limitations	74
3.5. Special Extrusion Techniques	76
3.6. Mechanical Properties	77

3.7. Dimensional Tolerances	78
3.8. Alloys and Composites	80
References	81

6 • Metalworking III: Forging 83
Arthur F. Hayes

1. Introduction	83
2. The Forging Process	84
3. Beryllium Deformation Characteristics	85
4. Mechanical-Property Characteristics	86
5. Forging Methods and Shapes Produced	86
6. Beryllium Powder Forging	87
7. Beryllium Ring Rolling	88
8. Forging Unclad Beryllium	89
9. Development of Forgeable Grades of Beryllium	97
10. Anisotropy	99
11. Microstructure–Property–Process Interrelationships	102
12. Prospectus	104
References	105

7 • Metalworking IV: Forming 107
Jack J. Blakeslee

1. Introduction	107
2. Formability of Beryllium	108
3. Deep Drawing	109
3.1. Introduction	109
3.2. Lubrication	110
3.3. Blank Development	110
3.4. Tool Designs	112
3.5. Temperature and Strain Rate	115
3.6. Practical Applications	117
4. Three-Roll Roll Forming	118
4.1. Introduction	118
4.2. Theory of Bending	119
4.3. Practical Applications	120
5. Stretch or Creep Forming	122
5.1. Introduction	122
5.2. Tooling Types	122
5.3. Practical Applications	122
6. Future Work	123
References	124

8 • Metalworking V: Wire Drawing	125
<i>John P. Denny</i>	
1. Introduction	125
2. Raw Materials	125
3. Drawing Technology	127
4. Properties of Wire	130
4.1. Mechanical Properties	130
4.2. Structure	132
5. Applications	133
References	134
9 • Plasma-Sprayed Beryllium	135
<i>Ian W. Dunmur</i>	
1. Introduction	135
2. Thermal Powder-Spray Coating Processes	135
3. Beryllium Powders	136
4. Morphology of Plasma-Spray Consolidated Beryllium	136
4.1. Macroscopic Structure	137
4.2. Grain Size, Crystallographic Texture, and Impurity Effects	139
4.3. Porosity, Surface Area, and Gas Permeability	143
5. Properties and Postspraying Heat Treatment	144
5.1. The Effect of Heat Treatment on Morphology	144
5.2. Gas Permeability and Electrical Conductivity	147
5.3. Thermal Conductivity	148
5.4. Thermal Expansion	148
5.5. Micro- and Macrohardness	150
5.6. Tensile Test Properties	153
6. Postspraying Hot Pressing	159
7. The Plasma-Spray Technique	160
7.1. Powder Preparation	160
7.2. Particle Heating	161
7.3. Powder Dispensers	162
7.4. The Arc Plasma Torch	163
7.5. Gases	164
7.6. Gas Shield	165
7.7. Workpiece Cooling	165
7.8. Workpiece Manipulation	166
7.9. Containment of the Process: Hazards	166
7.10. Substrate Preparation	168
7.11. Process Efficiency	169
7.12. Heat Treatment	169

8. Applications	170
9. Conclusion	173
References	173
10 • Machining	177
<i>J. E. J. Bunce and M. Hill</i>	
1. Introduction	177
2. Basic Machining Problems	177
2.1. Toxicity	177
2.2. Tool Life	178
2.3. Beryllium Machining Characteristics	178
3. Machining Techniques	179
3.1. General Guidelines	179
3.2. Lathe Turning	180
3.3. Milling	184
3.4. Drilling	186
3.5. Grinding	188
3.6. Sawing	189
3.7. Electric-Discharge Machining (EDM)	191
3.8. Electrochemical Machining (ECM)	191
4. Interstage and Postmachining Treatments	192
5. Bibliography	193
11 • Machining-Induced Surface Damage	197
<i>S. Beitscher</i>	
1. Introduction	197
2. Types of Surface Defects	199
2.1. Twins	199
2.2. Cracks	201
2.3. Residual Stress	202
2.4. Surface Texture	203
2.5. Plastically Strained Layer	203
2.6. Surface Roughness	204
3. Effects of Surface Damage	204
3.1. Smooth-Bar Tensile	204
3.2. Notched Tensile	205
3.3. Bend	208
3.4. Fatigue	210
3.5. Toughness	212
4. Methods to Eliminate or Reduce Surface Damage	214
4.1. Etching	215

4.2. Heat Treatment	217
4.3. Unconventional Machining	221
5. Detection of Surface Damage	223
5.1. Inspection during Machining	224
5.2. Optical Metallography	225
5.3. Other Methods	226
6. Conclusions	227
References	228
12 • Joining I: Mechanical/Adhesive	231
<i>Richard J. Switz</i>	
1. Introduction	231
2. General Considerations	232
3. Joints Made with Mechanical Fasteners	233
3.1. Drilling Holes	233
3.2. Electrical-Discharge Machining	235
3.3. Inspection	235
3.4. Tapping	237
3.5. Structural Inserts and Nut Plates	238
3.6. Rivets	238
4. Joints Made with Adhesive	239
4.1. Adhesive Choices	239
4.2. Allowable Strength Values	239
4.3. Surface Preparation	240
4.4. Application and Curing Techniques	240
4.5. Tooling and Assembly Considerations	241
5. Quality Control	244
6. Repair Techniques and Proof Testing	245
6.1. Hole Repair	245
6.2. Bonded Joint Repair	245
6.3. Proof Testing	246
7. Summary	246
References	247
13 • Joining II: Brazing and Soldering	249
<i>L. A. Grant</i>	
1. Introduction	249
2. Soldering of Beryllium	250
3. Zinc Brazing	251
3.1. Application	251
3.2. Shear Strengths of Zinc-Brazed Beryllium	252

4. Aluminum-Brazed Beryllium	252
4.1. Introduction	252
4.2. Shear Strengths	254
4.3. Beam-Bending Strengths	256
4.4. Butt Tensile Braze Test Results	260
4.5. Joint Designs	261
4.6. Complex Assemblies	263
4.7. Eggcrated Mirror Blanks	264
5. Silver Brazing	266
5.1. Introduction	266
5.2. Shear Strength	268
6. Conclusions	272
References	273
14 • Joining III: Diffusion Bonding	275
<i>D. L. Olson and A. L. Liby</i>	
1. Introduction	275
2. Concepts	276
3. Direct Beryllium Bonding	281
4. Bonding with an Intermediate Layer	284
5. Practice	289
5.1. Joint Design	289
5.2. Surface Preparation	290
5.3. Equipment	291
5.4. Nondestructive Evaluation	294
6. Summary	294
References	295
15 • Alloys and Composites	297
<i>Gilbert J. London</i>	
1. Introduction	297
2. Beryllium Alloys	298
2.1. Beryllium–Copper Alloys	298
2.2. Beryllium–Iron Alloys	299
2.3. Beryllium–Antimony Alloys	299
2.4. Beryllium–Aluminum Alloys	300
3. Beryllium–Titanium Composites	308
3.1. Fabrication	308
3.2. Properties	313
4. Other Beryllium Composites	316
References	317

16 • Properties 319

Norman P. Pinto

- 1. Introduction 319
- 2. Mechanical Properties 321
 - 2.1. Strength 322
 - 2.2. Modulus 331
 - 2.3. Poisson’s Ratio 332
 - 2.4. Ductility 333
 - 2.5. Bauschinger Effect 336
 - 2.6. Combined Stress Properties 337
 - 2.7. Hardness 338
 - 2.8. Fracture Toughness 339
 - 2.9. Impact Strength 341
- 3. Physical Properties 341
 - 3.1. Density 342
 - 3.2. Thermal Expansion 342
 - 3.3. Thermal Conductivity 343
 - 3.4. Thermal Diffusivity 345
 - 3.5. Electrical Resistivity 345
- 4. Effects of Radiation 346
 - References 346

17 • Fracture Mechanics 351

Roger Edwin Cooper

- 1. Introduction 351
- 2. Outline of Fracture Mechanics 352
- 3. Considerations in Choice of Specimen 357
 - 3.1. Specimen Type 357
 - 3.2. Specimen Size 359
- 4. Precracking Technique 360
 - 4.1. Introduction 360
 - 4.2. As-Machined Notch 361
 - 4.3. Dunegan Wedge Cracking 362
 - 4.4. Other Notching Methods 362
 - 4.5. Fatigue Precracking 362
 - 4.6. Root Radius Effects and a Comparison of Different Methods 362
- 5. Test Trace Shape 363
- 6. Microstructural Effects 365
 - 6.1. Introduction 365
 - 6.2. Purity 365

6.3. Grain Size	366
6.4. Heat Treatment Effects	369
6.5. The Effects of Porosity	370
6.6. Orientation	371
7. Thickness Effects	372
8. Effects of Temperature	373
9. The Application of Fracture Mechanics Data	374
10. Conclusions	376
References	377
18 • Design Considerations	379
<i>Forest E. Stone</i>	
1. Introduction	379
1.1. Baseline Design Application Defined	380
1.2. Design Requirements and Basis of Material Selection	380
1.3. Chapter Organization	381
2. Mechanical Property Influences and Loading Effects	382
2.1. Design Parameters	382
2.2. Stress–Strain Property Influence	383
2.3. A Ranking of Properties	390
2.4. Failure Criteria	392
3. Some Design Methodology Considerations	399
4. Fundamental Material and Construction Influences	404
4.1. Inherent Material Influences	404
4.2. Construction Influences	406
5. Summary of Design Issues	410
5.1. Psychological Considerations	410
5.2. Practical Considerations	411
5.3. Technical Considerations	412
6. Future Design Goal	412
References	414
19 • Corrosion	417
<i>John J. Mueller and Donald R. Adolphson</i>	
1. Introduction	417
2. Corrosion of Beryllium in Air	418
2.1. Causes of Corrosion in Air	418
2.2. Contamination from the Atmosphere	421
3. Aqueous Corrosion of Beryllium	422
4. In-Process Corrosion Problems and Handling and Storage Procedures	424

4.1. In-Process Problems	424
4.2. Handling and Storage Procedures	425
5. Corrosion-Protection Surface Treatments and Coatings	427
5.1. Chromate Coatings	427
5.2. Fluoride Coatings	428
5.3. Anodized Coatings	428
5.4. Plated Coatings	430
5.5. Organic Coatings	430
6. Summary and Conclusions	431
References	432
<i>Index</i>	435