

CONTENTS

METHODS FOR EMISSION SPECTROCHEMICAL ANALYSIS

For Contents in Numeric Sequence, see p. xi.

A complete subject index appears on p. 663.

GENERAL PRACTICES

<i>Recommended Practices for:</i>	PAGE
E 115 - 59 T. Photographic Processing in Spectrochemical Analysis.....	1
E 116 - 59 T. Photographic Photometry in Spectrochemical Analysis.....	12
E 130 - 57 T. Designation of Shapes and Sizes of Preformed Graphite Electrodes.....	36
E 158 - 60 T. Spectrochemical Computations.....	41
E 172 - 60 T. Describing and Specifying the Excitation Source in Emission Spectrochemical Analysis.....	52
Reagents for Chemical Analysis (Excerpt from E 50 - 60, Recommended Practices for Apparatus and Reagents for Chemical Analysis of Metals).....	57
E 29 - 60 T. Designating Significant Places in Specified Limiting Values.....	62
E 105 - 58. Probability Sampling of Materials.....	67
E 122 - 58. Choice of Sample Size to Estimate the Average Quality of a Lot or Process.....	72
E 141 - 59 T. Acceptance of Evidence Based on the Results of Probability Sampling.....	79
 <i>Suggested Practices for:</i>	
E-2 SM 1-1. Installation and Safe Operation of the Spectrochemical Laboratory.....	82
E-2 SM 1-2. (<i>Describing and Specifying the Excitation Source</i>) Replaced by E 172 - 60 T.	
E-2 SM 1-3. Describing and Specifying the Spectrograph.....	87
E-2 SM 2-3. (<i>Spectrochemical Computations</i>) Replaced by E 158 - 60 T.	
E-2 SM 2-4. Use of Statistical Methods in Spectrochemical Analysis.....	94
E-2 SM 2-5. Flame Photometric Methods of Spectrochemical Analysis.....	106
E-2 SM 2-6. Establishing and Controlling Spectrochemical Analytical Curves.....	125

NOMENCLATURE

Definitions of:

E 135 - 60 T. Terms and Symbols Relating to Emission Spectroscopy.....	132
E 131 - 59 T. Terms and Symbols Relating to Absorption Spectroscopy.....	136

Suggested Nomenclature in:

E-2 SM 3-1. (<i>Applied Spectroscopy</i>) Replaced by E 135 - 60 T.	
---	--

For Contents in Numeric Sequence, see p. xi.

SPECTROCHEMICAL ANALYSIS OF METALS

Copper, Nickel, and Their Alloys

<i>Tentative Method for Spectrochemical Analysis of:</i>		PAGE
E 129 – 57 T.	Nickel Alloys by the Powder – D-C Arc Technique.....	139

Suggested Methods for Spectrochemical Analysis of:

E-2 SM 5-2.	Wrought Copper Alloys by the D-C Arc Technique.....	144
E-2 SM 5-3.	Bronze by the Solution – Porous Cup – Spark Technique.....	150
E-2 SM 5-4.	Tin Bronze by the Cast Pin – Spark Technique.....	155
E-2 SM 5-5.	Nickel Sheet by the Point-to-Plane Spark Technique.....	159
E-2 SM 5-6.	Nickel Sheet by the A-C Arc Technique.....	162
E-2 SM 5-7.	70-30 Cupro-Nickel by the Cast Pin – Spark Technique.....	165
E-2 SM 5-8.	Admiralty Metal for Arsenic by the Cast Pin – D-C Arc Technique.....	170
E-2 SM 5-9.	Copper Alloys by the Point-to-Plane Spark Technique.....	174
E-2 SM 5-10.	Nickel-Base High-Temperature Alloys by the Point-to-Plane Spark Technique.....	178
E-2 SM 5-11.	Beryllium Copper Alloys by the Solution – Rotating Disk – Spark Technique.....	182

Lead, Tin, Zinc, and Related Metals

Tentative Methods for Spectrochemical Analysis of:

E 27 – 59 T.	Zinc-Base Alloys and High-Grade Zinc by the Solution Residue – D-C Arc Technique.....	186
E 51 – 59 T.	Tin Alloys for Minor Constituents and Impurities.....	190
E 117 – 59 T.	Pig Lead by the Point-to-Plane Spark Technique.....	193

Suggested Methods for Spectrochemical Analysis of:

E-2 SM 6-1.	Lead-Base Alloys by the Dry Power – D-C Arc Technique....	198
E-2 SM 6-2.	Pig Leads by the D-C Arc Technique.....	202
E-2 SM 6-4.	Tin-Base Alloys by the Dry Powder – D-C Arc Technique....	206
E-2 SM 6-5.	Lead-Tin Solders by the Dry Powder – D-C Arc Technique....	210
E-2 SM 6-6.	Antimonial Lead Alloys by the Point-to-Plane Spark Technique..	214
E-2 SM 6-7.	Lead-Base Bearing Alloys by the Cast Pin – Spark Technique..	218
E-2 SM 6-8.	Type Metal Alloys by the Point-to-Plane Spark Technique.....	221
E-2 SM 6-9.	Tin by the Cast Pin – Spark Technique.....	225
E-2 SM 6-10.	Bismuth-Cadmium Eutectic Alloy by the Powder – D-C Arc Technique.....	229
E-2 SM 6-11.	Tin-Cadmium Eutectic Alloy by the Powder – D-C Arc Technique.....	232
E-2 SM 6-12.	Zinc-Base Alloys by the Dry Powder – D-C Arc Technique....	235
E-2 SM 6-13.	Cadmium Metal by the Solution Residue – D-C Arc Technique..	240
E-2 SM 6-14.	Cadmium Metal by the Point-to-Point A-C Arc Technique....	243
E-2 SM 6-15.	Zinc Die-Casting Metal and High-Purity Zinc by the Cast Pin and Point-to-Plane Techniques.....	247
E-2 SM 6-16.	Antimony by the Point-to-Plane Spark Technique.....	252
E-2 SM 6-18.	Zinc and Its Alloys by the Point-to-Plane Spark and Condensed Arc Techniques Using a Recording Photoelectric Spectrometer.....	256
E-2 SM 6-19.	Lead and Its Alloys by the Point-to-Plane Condensed Arc Technique Using a Recording Photoelectric Spectrometer.....	261
E-2 SM 6-20.	Indium Alloys by the Solution – Porous Cup – Spark Technique.	266

For Contents in Numeric Sequence, see p. xi.

Aluminum, Magnesium, and Their Alloys

<i>Tentative Method for Spectrochemical Analysis of:</i>		PAGE
E 101 – 53 T.	Aluminum and Aluminum-Base Alloys by the Point-to-Plane Spark Technique.....	270

Suggested Methods for Spectrochemical Analysis of:

E-2 SM 7-2.	Aluminum-Base Alloys by the Dry Powder – D-C Arc Technique.	280
E-2 SM 7-4.	Magnesium-Base Alloys by the Point-to-Plane Spark Technique..	286
E-2 SM 7-9.	Aluminum and Its Alloys by the Pin-to-Pin Spark Technique....	290
E-2 SM 7-10.	Aluminum and Its Alloys by the Point-to-Plane Spark and Intermittent Arc Techniques Using a Recording Photoelectric Spectrometer.....	299
E-2 SM 7-11.	Magnesium and Its Alloys by the Pin-to-Pin Spark Technique..	312
E-2 SM 7-12.	Aluminum and Its Alloys by the Point-to-Plane Spark Technique Using a Clock-Indicating Photoelectric Spectrometer.....	317
E-2 SM 7-13.	Magnesium-Base Alloys by the Point-to-Plane Spark Technique Using a Grating Spectrograph.....	321
E-2 SM 7-14.	Aluminum-Base Alloys by the Solution – Rotating Disk – Spark Technique.....	325
E-2 SM 7-15.	Aluminum-Base Alloys Using an X-Ray Fluorescence Technique..	329

Titanium, Zirconium, and Related Metals*Suggested Methods for the Spectrochemical Analysis of:*

E-2 SM 8-7.	Titanium Metal by the Dry Powder – D-C Arc Technique.....	335
E-2 SM 8-8.	Titanium and Titanium Alloys by the Solution – Porous Cup – Spark Technique.....	340
E-2 SM 8-9.	Aluminum-Chromium-Titanium Alloy by the Point-to-Plane Spark Technique.....	348
E-2 SM 8-10.	Titanium Sponge and Metal by the Solution – Rotating Disk – Spark Technique.....	351
E-2 SM 8-11.	Titanium Alloys by the Solution – Rotating Disk – Spark Technique.....	358
E-2 SM 8-12.	Zirconium by the Barium Fluoride – Graphite Carrier – D-C Arc Technique.....	363
E-2 SM 8-13.	Zirconium by the Silver Chloride Carrier – D-C Arc Technique..	367

Ferrous Metals*Suggested Methods for Spectrochemical Analysis of:*

E-2 SM 9-1.	<i>(Low-Alloy Steel by the Point-to-Plane Spark Technique) Replaced by E-2 SM 9-13.</i>	
E-2 SM 9-2.	Alloy Cast Steel and Iron by the Cast Pin – Spark Technique....	371
E-2 SM 9-3.	<i>(Low-Alloy Steel by the Cast Pin – Spark Technique) Replaced by E-2 SM 9-14.</i>	
E-2 SM 9-4.	Steel for Boron by the Point-to-Plane Intermittent Arc Technique.....	375
E-2 SM 9-5.	<i>(Low-Alloy Steel by the Point-to-Plane A-C Arc Technique) Replaced by E-2 SM 9-13.</i>	
E-2 SM 9-6.	<i>(Low-Alloy Steel by the Point-to-Plane Spark Technique) Replaced by E-2 SM 9-13.</i>	
E-2 SM 9-7.	<i>(Low-Alloy Steel by the Pellet – Spark Technique) Replaced by E-2 SM 9-18.</i>	
E-2 SM 9-8.	<i>(Low-Alloy Steel for Residual Elements by the Pellet – Spark Technique) Replaced by E-2 SM 9-18.</i>	

For Contents in Numeric Sequence, see p. xi.

<i>Suggested Methods for Spectrochemical Analysis of:</i>		PAGE
E-2 SM 9-9.	<i>(Low-Alloy Steel by the Rod-to-Rod Spark Technique) Replaced by E-2 SM 9-14.</i>	
E-2 SM 9-10.	Alloy Cast Iron by the Cast Pin – Spark Technique.....	379
E-2 SM 9-11.	Stainless-Type Steels by the Point-to-Plane, Spark-Initiated, Intermittent Arc Technique Using a Recording Photoelectric Spectrometer.....	383
E-2 SM 9-12.	Cast Iron by the Point-to-Plane Spark Technique.....	390
E-2 SM 9-13.	Plain-Carbon and Low-Alloy Steel by the Point-to-Plane Spark Technique.....	398
E-2 SM 9-14.	Plain-Carbon and Low-Alloy Steel by the Rod-to-Rod Spark Technique.....	407
E-2 SM 9-15.	Stainless-Type Steels by the Point-to-Plane Spark Technique....	414
E-2 SM 9-16.	Steel by the Solution – Rotating Disk – Spark Technique.....	423
E-2 SM 9-17.	Cast Iron for Cerium by the Point-to-Plane Condensed Arc Technique.....	427
E-2 SM 9-18.	Plain-Carbon and Low-Alloy Steel by the Pellet Technique.....	433
E-2 SM 9-19.	Low-Alloy Steels and Cast Irons Using an X-Ray Fluorescence Technique.....	442
E-2 SM 9-20.	Tool Steel by the Point-to-Plane Spark and Condensed Arc Techniques Using a Recording Photoelectric Spectrometer....	446
E-2 SM 9-21.	Low-Alloy Steel for Acid-Soluble Aluminum by the Solution Residue – D-C Arc Technique.....	451
E-2 SM 9-22.	Carbon and Low-Alloy Steels by the Condensed Arc Technique Using a Recording Photoelectric Vacuum Spectrometer.....	455

SPECTROCHEMICAL ANALYSIS OF NONMETALS

Glass, Ceramics, Alkalies, and Cementitious Materials

Standard Method of Test for:

Potassium, Sodium, and Lithium Oxides in Refractory Materials by Flame Photometry (Excerpt from C 18 – 60, Chemical Analysis of Refractory Materials).....	462
--	-----

Tentative Method of Test for:

Sodium Oxide and Potassium Oxide in Portland Cement by Flame Photometry (Excerpt from C 114 – 58 T, Chemical Analysis of Portland Cement).....	465
--	-----

Suggested Methods for Spectrochemical Analysis of:

E-2 SM 10-1.	Silica Refractories by the Powder – Intermittent Arc Technique..	469
E-2 SM 10-3.	Alkaline Earth Titanates by Pellet – Spark and Intermittent Arc Techniques.....	472
E-2 SM 10-6.	Soda Ash and Other Sodium Salts by the Solution Residue – A-C Arc Technique.....	476
E-2 SM 10-8.	<i>(Caustic Soda by the Solution—A-C Arc Technique) Replaced by E-2 SM 10-15.</i>	
E-2 SM 10-9.	Ceramics and Other Nonmetallic Materials by the Powder – D-C Arc Technique.....	479
E-2 SM 10-10.	Silica Brick and Glass Sand by the Powder – D-C Arc Technique.	485
E-2 SM 10-13.	Glass for Alkali Elements by Flame Photometry.....	489
E-2 SM 10-14.	Alumina Ceramic Materials by the Powder – D-C Arc Technique.....	496
E-2 SM 10-15.	Caustic Soda by the Solution Residue – A-C Arc Technique....	502
E-2 SM 10-16.	Cement for Manganic, Sodium, and Potassium Oxides by the Flame Photometer Technique.....	508

For Contents in Numeric Sequence, see p. xi.

<i>Suggested Methods for Spectrochemical Analysis of:</i>	PAGE
E-2 SM 10-17. Glass for Alkaline Earth Elements by the Flame Photometer Technique.....	515
E-2 SM 10-18. Alumina by the Powder – D-C Arc Technique Using a Recording Photoelectric Spectrometer.....	522
E-2 SM 10-19. Titanium Oxide, Aluminum Oxide, and Zirconium Oxide for Alkali Oxides by the Recording Flame Photometer Technique..	526

Slags, Ores, Petroleum Products, and Other Miscellaneous Nonmetallic Materials

Tentative Methods of Test for:

D 1318 – 59 T. Sodium in Residual Fuel Oil by Flame Photometer.....	536
D 1428 – 56 T. Sodium and Potassium Ions in Industrial Water and Water-Formed Deposits by Flame Photometry.....	540
Sodium and Potassium in Polyols by Flame Photometry (Excerpt from D 1638 – 60 T, Methods of Testing Urethane Foam Raw Materials).....	549

Proposed Method of Test for:

Tetraethyl Lead in Gasoline by Flame Photometer.....	554
--	-----

Suggested Methods for Spectrochemical Analysis of:

E-2 SM 11-1. Cobaltic Oxide for Impurities by the Powder – D-C Arc Technique.....	559
E-2 SM 11-2. Unknown Materials by the Powder – D-C Arc Semiquantitative Technique.....	564
E-2 SM 11-3. Copper Strike Plating Solutions for Silver by the Solution Residue – D-C Arc Technique.....	569
E-2 SM 11-4. Nickel Plating Solutions for Zinc by the Solution Residue – A-C Arc Technique.....	572
E-2 SM 11-5. Metallic Silver and Silver Nitrate by the Powder – D-C Arc Technique.....	575
E-2 SM 11-6. Slags by the Powder – D-C Arc Technique.....	577
E-2 SM 11-7. Open-Hearth Slags for Lime-Silica Ratios by the Powder – Intermittent Arc Technique.....	581
E-2 SM 11-8. Basic Open-Hearth Slags for Lime-Silica Ratios by the Powder – Spark Technique.....	584
E-2 SM 11-9. Lithium-Bearing Ores for Lithium, Sodium, and Iron by the Solution Residue – A-C Arc Technique.....	589
E-2 SM 11-10. Blast-Furnace and Open-Hearth Sinter by the Pellet-Condensed Arc Technique.....	595
E-2 SM 11-11. Cerium Minerals for Rare Earths and Thorium by the Powder – D-C Arc Technique.....	599

Used Diesel Lubricating Oils

Proposed Recommended Practice for Applying Precision Data Given in ASTM Methods of Test for Petroleum Products and Lubricants.....	608
Suggested Method for Sampling Diesel Locomotive Lubricating Oil for Spectrographic Analysis.....	613
Suggested Spectrochemical Methods for Wear Metals in Used Diesel Lubricating Oils:	
Ashing Procedure.....	614
Dish Coking Procedure.....	619
Electrode Coking Procedure.....	624
Rotating-Disk Electrode Technique.....	628
Rotating-Platform Electrode Technique.....	633

For Contents in Numeric Sequence, see p. xi.

	PAGE
Suggested Direct-Reading Spectrochemical Methods for Wear Metals in Used Diesel Lubricating Oils:	
Rotating-Disk Electrode Technique.....	639
Ashing Procedure.....	642

APPENDICES

Appendix I—Unsolved Problems in Spectrochemical Analysis.....	647
Appendix II—ASTM Publications on Emission Spectroscopy and Related Subjects..	656
Appendix III—Committee E-2 Reports and Sponsored Technical Papers Available in the General Literature.....	660
Officers of Committee E-2 and Its Subcommittees.....	662

INDEX

Index.....	663
------------	-----

Recommendations for Preparation of ASTM Committee E-2 Spectrochemical Methods.....	687
---	-----

