



# CONTENTS

<i>Contributors</i> . . . . .	v
<i>Preface</i> . . . . .	vii

## Part 1. Fundamentals

1. Properties of X-rays . . . . .	1-3
2. Generation of X-rays . . . . .	2-1
3. Detection and Measurement of X-rays . . . . .	3-1
4. The Geometry of Crystals . . . . .	4-1
5. Design of Typical X-ray Laboratory . . . . .	5-1
6. Health and Safety . . . . .	6-1

## Part 2. Diffraction of X-rays by Polycrystalline and Amorphous Materials

7. Introduction to Powder Diffraction . . . . .	7-3
8. Camera Techniques . . . . .	8-1
9. Diffractometer Techniques . . . . .	9-1
10. The Precise and Accurate Determination of Lattice Parameters . . . . .	10-1
11. Qualitative Analysis by Powder Diffraction . . . . .	11-1
12. Quantitative Analysis by Powder Diffraction . . . . .	12-1
13. High-temperature Diffractometer Techniques . . . . .	13-1
14. High-temperature Camera Techniques . . . . .	14-1
15. Low-temperature Diffraction . . . . .	15-1
16. Small-angle Scattering of X-rays . . . . .	16-1
17. Crystallite-size Determination from Line Broadening and Spotty Patterns . . . . .	17-1
18. Determination of Preferred Orientation . . . . .	18-1
19. Stress Measurement in Metals . . . . .	19-1
20. Determination of Phase Diagrams . . . . .	20-1
21. Characterization of Polymers . . . . .	21-1
22. Radial-distribution Analysis . . . . .	22-1
23. Related Techniques . . . . .	23-1

## Part 3. Determination of Crystal Structure

24. Single-crystal Techniques . . . . .	24-3
25. Diffractometric Techniques for Single-crystal Analysis . . . . .	25-1
26. The Reciprocal Lattice . . . . .	26-1
27. Indexing Single-crystal Patterns . . . . .	27-1
28. Indexing of Powder Patterns . . . . .	28-1
29. X-ray Methods of Determining Crystal Structures . . . . .	29-1

**Part 4. X-ray Emission Spectroscopy**

30. Introduction to X-ray Emission Spectroscopy . . . . .	30-3
31. Optics . . . . .	31-1
32. Factors Which Determine Sensitivity. . . . .	32-1
33. Specimen-preparation Techniques . . . . .	33-1
34. Effects of Chemical State of Specimens . . . . .	34-1
35. Qualitative and Semiquantitative Techniques . . . . .	35-1
36. Quantitative Techniques . . . . .	36-1
37. Trace and Microanalysis . . . . .	37-1
38. Soft X-ray Emission Spectroscopy in the 10 to 150 Å Region. . . . .	38-1
39. Electron-probe Microanalysis . . . . .	39-1
40. High-speed Automatic Spectrometers and Continuous Analyzers. . . . .	40-1

**Part 5. X-ray Absorption Methods**

41. Absorptiometry with Polychromatic X-rays . . . . .	41-3
42. Absorptiometry with Monochromatic X-rays . . . . .	42-1
43. Fine Structure in Absorption-edge Spectra . . . . .	43-1
44. Measurement of Film Thickness . . . . .	44-1

**Part 6. Microradiography and X-ray Microscopy**

45. Contact Microradiography . . . . .	45-3
46. Contact Microradiography with Ultrasoft X-rays . . . . .	46-1
47. X-ray Projection Microscopy . . . . .	47-1
48. Reflection Microscopy . . . . .	48-1

*Index follows Chapter 48.*