

59.11.5

233 P
vol.
30 cm

426 AA
Pc-T
(1983)

Table of content

1. Introduction
(F. Engelmann and J.P. Rager)

2. Overall Summary and Conclusions
(F. Engelmann and J.P. Rager)

3. Topical Introductions and Summaries,
and Short Contributions from Laboratories

3.1 Confinement and Stability limits - Disruptions

3.1.1 Topical introduction (J. Hugill)

3.1.2 Contributions from the Laboratories

3.1.3 Conclusions

3.2 The Physics of RF Heating

3.2.1 Topical introduction (J. Jacquinot)

3.2.2 Introduction to different RF methods

3.2.3 Contributions from the Laboratories

3.2.4 Conclusions

3.3 Edge Physics

3.3.1 Topical summary (K. Lackner)

3.3.2 Contributions from the Laboratories

4. The Status of JET and NET

4.1 The Status of JET

(by the JET team, presented by L. De Kock)

4.2 Planning a time schedule for NET : Physics Considerations
(F. Engelmann)

5. Programme

5.1 Agenda

5.2 Organization of the Parallel Sessions

5.3 Programme for the RF heating Session

5.4 Programme for the parallel session on Edge Physics

6. List of Participants