CONTENTS

1.	The Theory of Radiation Induced Defect Production	•	•	1
	Mark T. Robinson			
	Introduction			1
	Primary Recoil Energy Spectra			3
	Electron and Ion Irradiations			3
	Thermal Neutron Irradiations			5
	Fast Neutron Irradiations			6
	The Displacement Cascade			10
	LSS Atomic Collision Theory			
	Electronic Stopping Cross Sections			
	The Displacement Process			
	Radiation Induced Defect Production	•	•	18
	The Damage Energy Model			
	Effects of Cascade Density	•	•	21
	Concluding Remarks			
		•	٠	44
2.	Field-Ion Microscope Studies of the Defect			
4.	Structure of the Primary State of Damage			
	of Irradiated Metals			00
	David N. Seidman	•	•	28
	David N. Seldman			
	Introduction			28
	The Field-Ion Microscope Technique	•	•	20
	Field Ionization			
	Field Evaporation			
	Resolution	•	•	37
	Cornell FIM Studies of Depleted Zones in			
	Irradiated Tungsten			
	Depleted Zones Created at 473K			
	Depleted Zones Created at 18K	•	•	45
	Other FIM Experiments on Vacancy Type Radiation			
	Damage			51
	Summary			54

З.	Defect Production by Energetic Particle	
	Bombardment	58
	K. L. Merkle	
	Particle Irradiation Experiments	59
	Determination of the Atomic Displacement	
	Threshold	62
	TEM of Displacement Cascades	68
	TEM of Depleted Zones	68
	Energy Dependence	70
	Defect Structure	78
	Size Distribution	79
	Depth Distribution	82
	Channeling	84
	Comparison between Cascade Structures Observed in	
	Neutron and Ion Irradiations	85
	Summary and Conclusions	88
4.	Defect Annealing Processes in Metals	95
	F. W. Young, Jr.	
	Stage I	97
	Stage II	106
	Stage III	11 0
	Stage IV	116
	Stage V	118
	Summary and Conclusions	119
5.	Radiation-Enhanced Diffusion in Metals and Alloys.	125
	Nghi Q. Lam and Steven J. Rothman	
	Introduction	125
	Kinetics of Diffusion by Radiation-Induced Point	
	Defects	127
	The Simple Model	127
	Time-Dependent Solutions	129
	Steady-State Solutions	131
	Deficiencies of the Simple Model	132
	Experimental Techniques, Results, and Discussion .	133
	Self-Diffusion	133
	Impurity Diffusion	138
	Chemical Diffusion	141
	Ordering and Clustering	143
	High-Voltage Electron Microscopy	150
	Conclusions	151

viii

Contents

6.	$\underline{Theory} \ of \ Defect \ Clustering \ and \ Void \ Formation$. H. Wiedersich	1 57
	Steady-State Defect Concentration	158
	Defect-Cluster Nucleation	169
	Swelling	179
	Sink-Annihilation Probabilities	184
	Summary and Conclusions	189
7.	Simulation Experiments with the High Voltage	
	Electron Microscope	194
	Introduction	194
	HVEM Parameters Atypical of Neutron Environments	195
	Non-Isotropic Flux	195
	Nature of the Displacement Event	196
	Displacement Rate Effects	197
	Limited Irradiation Volume	197
	Displacement Rate Gradients	199
	Beam Heating	200
	Surface Effects	202
	Stress Effects	207
	Electron Irradiation Parameters	208
	Applications of HVEM Irradiations	209
	Fundamental Studies	209
	Swelling Design Equations	217
	Summary and Conclusions	22 2
8.	The Effect of Metallurgical Variables on Void	
	Swelling	227
	and A. M. Turkalo	
	Void Swelling - A Metallurgical Problem	227
	Mechanism of Void Formation	2 2 9
	Predicted Effects of Metallurgical Variables	230
	Experimental Methods for Studying Void Swelling Nickel Ion Bombardment of Austenitic Stainless	232
	Steels	233
	Observed Effects of Structure on Swelling	236
	Effect of Major Alloy Composition on Swelling	238
	Effects of Minor Element Additions	
	Discussion of the Effects of Alloy Composition on	0
	Swelling	251
	Swelling Predictions Based on Observed Compositional	
	Effects	253

	The Control of Swelling Through Metallurgical	
	Variables	2 59
	Summary	260
9.	Radiation-Enhanced Creep	267
	Introduction	267
	Radiation Damage Cascades	268
	Phenomenology of Radiation Creep	269
	Creep Processes	275
	Low-Stress Radiation Creep	278
	Intermediate-Stress and High-Stress Radiation	0.00
	Creep	283
	Statistical Fluctuations and Dislocation Climb	289
	Summary	290
10.	Irradiation Strengthening and Embrittlement E. E. Bloom	295
	Abstract	295
	Introduction	296
	Effects of Irradiation on Deformation	298
	Dislocation Glide	299
	Dislocation Creep	304
	Diffusion Flow	309
	Effects of Irradiation on Fracture	309
	Fractures in Unirradiated Conditions	309
	Fracture of Irradiated Material	312
	Concluding Statement	324
11.	Radiation Effects on Superconductivity	330
		330
	Introduction	336
	Elemental Superconductors	
	Alloy Superconductors	343
	Compounds	351
	Conclusions	360
12.	Radiation Damage of Nonmetallic Solids	366
	Introduction	366
	Defects in Nonmetals	3 69
	Radiation Damage Processes in Nonmetals	370
	Concluding Remarks	391
Ind	lex	395

х