

Contents

	Page
Introduction.....	1
1. Theory.....	1
1.1. The Planck radiation equation.....	1
1.2. The International Practical Temperature Scale.....	1
1.3. The primary calibration at the gold point.....	2
1.4. The primary calibration above the gold point.....	2
1.5. The absorbing glasses.....	3
1.6. The relation between effective and mean effective wave- lengths.....	4
1.7. The use of non-blackbody sources in a primary calibration.....	5
2. Optical pyrometers.....	6
2.1. General characteristics of optical pyrometers.....	6
a. Pyrometer lamp.....	7
b. Apertures and filters.....	7
c. Fairchild's criterion.....	8
2.2. The NBS optical pyrometer.....	8
a. Objective lens assembly.....	8
b. Absorbing glasses, pyrometer lamp, and red filter.....	9
c. Microscope assembly.....	10
d. The electrical circuit.....	10
3. Sources.....	10
3.1. Blackbodies.....	10
a. Gold-point blackbodies.....	11
b. Lesser quality blackbodies.....	12
3.2. Tungsten strip lamps.....	13
a. Types of strip lamps.....	13
b. Factors affecting the reproducibility of strip lamps.....	13
3.3. Other sources.....	14
a. The carbon arc.....	14
b. High-pressure arcs.....	14
4. Primary calibration.....	15
4.1. Calibration at the gold point.....	15
4.2. Calibration above the gold point.....	16
4.3. Estimated accuracy.....	18
5. Secondary calibrations.....	19
5.1. Optical pyrometers.....	19
a. Inspection and cleaning.....	19
b. Determination of the effective wavelengths.....	19
c. Calibration procedure.....	20
d. Low-range calibration.....	21
e. High-range calibrations.....	21
5.2. Tungsten strip lamps.....	22
a. Calibration range.....	22
b. Mounting and orientation.....	22
c. The electrical system.....	23
d. Calibration.....	23
5.3. Precision and accuracy.....	23
a. Definition of precision and accuracy.....	23
b. Statistical model for calibration errors.....	24
c. Uncertainties on certificates.....	24
d. Differences between the IPTS and TTS.....	25
6. Applications.....	25
6.1. Temperature measurements.....	25
6.2. Spectrical radiance calibrations using strip lamps.....	25
6.3. Secondary standards.....	26
6.4. Recommendations for achieving high accuracy and pre- cision.....	26
6.5. Fundamental limitations.....	27
6.6. Photoelectric optical pyrometers.....	27
7. References.....	28