

---

# Contents

---

<i>Note on Units of Pressure</i>	Page v
<i>Acknowledgements</i>	vi
<i>Preface to Second Edition</i>	vii
<i>Preface to First Edition</i>	viii
<b>1 Mechanical Manometers</b>	<b>1</b>
1.1. Liquid manometers	1
1.2. The McLeod gauge	3
1.3. The diaphragm manometer	21
1.4. Viscosity gauges	35
<b>2 Thermal Conductivity Gauges</b>	<b>40</b>
2.1. Basic principles	40
2.2. Measurement of thermal conductivity	43
2.3. Sensitivity	46
2.4. End losses	47
2.5. Accommodation coefficient	47
2.6. Alternative methods of bridge control	50
2.7. Useful range of the constant-voltage bridge	50
2.8. The lower limit to the useful pressure range	51
2.9. The importance of bridge-voltage and temperature fluctuations at high pressure	56
2.10. Compensation for temperature and voltage fluctuations	57
2.11. Physical change in the gauge wire (ageing effects)	59
2.12. The construction and operation of a gauge for routine measurements	60
2.13. The thermocouple gauge	66
Appendix 2.1. Effect of heat conduction along the wire	70
Appendix 2.2. Effect of ambient temperature on the gauge reading	74
<b>3 Ionization Gauges</b>	<b>77</b>
3.1. Positive ion production in a gas	77
3.2. The principle of the thermionic cathode gauge	79
3.3. The relative sensitivity for different gases	81
3.4. The calculation of gauge sensitivity	84
3.5. Gauge construction	88
3.6. The measurement of very low pressures—the Bayard- Alpert gauge	92

<b>3 Ionization Gauges (continued)</b>	<b>Page</b>
3.7. The maximum useful operating pressure	100
3.8. The cathode	102
3.9. Electrical control circuits	104
3.10. Valve amplifiers for measurement of positive ion current	112
3.11. The cold-cathode ionization gauge—the Penning gauge	113
3.12. Hot cathode ionization gauges with crossed electric and magnetic fields	120
3.13. Gas clean-up in the hot-cathode ionization gauge	122
3.14. Gas clean-up in the Penning gauge	128
3.15. Operation of the hot-cathode ionization gauge	129
3.16. Operation of the cold-cathode ionization gauge	132
3.17. Gauges with radioactive sources.	132
<b>4 The Knudsen Radiometer Gauge</b>	<b>135</b>
4.1. Theoretical considerations	135
4.2. Experimental verification of theory	140
4.3. Practical developments of the Knudsen design	144
4.4. The pressure range with a linear scale	152
4.5. The gauge time constant	153
4.6. The radiometer force in the high-pressure range	154
4.7. Practical application of this gauge.	158
<b>5 Surface Reaction Techniques</b>	<b>159</b>
5.1. Surface contamination	159
5.2. Observations of work-function changes	160
5.3. Flash filament techniques	164
5.4. Field-emission microscope	166
<b>6 Gauge Calibration</b>	<b>168</b>
6.1. Static methods	168
6.2. Dynamic methods	170
6.3. Calibration standards	176
<b>7 Analysis of the Residual Gases in the Vacuum System</b>	<b>177</b>
7.1. Introduction	177
7.2. The magnetic deflection mass spectrometer	178
7.3. The trochoidal (or cycloidal) mass spectrometer	186
7.4. The omegatron	188
7.5. Linear resonance mass spectrometers	194
7.6. Time-of-flight mass spectrometers	196
7.7. A comparison of different analysers	198
<i>References</i>	202
<i>Subject Index</i>	213
<i>Author Index</i>	218