

CONTENTS

Chapter 1 INTRODUCTION	1
Chapter 2 BASIC PRINCIPLES	6
2.1 Quantities and units	6
2.2 Basic laws	7
2.3 Magnetic circuit	8
2.4 Poles and surface charges	10
2.5 Stray flux and demagnetizing factor	11
2.6 Magnetic materials	12
2.7 Parts of an electromagnet	14
Chapter 3 FIELDS OF SURFACE CHARGES AND DIPOLE DISTRIBUTIONS	15
3.1 Field of surface charges	15
3.2 Dipolar fields	19
3.3 Optimum magnetization	21
Chapter 4 COIL FIELDS	23
4.1 Introduction	23
4.2 Current distributions	23
4.3 Field and power dissipation	26
4.4 <i>G</i> -factor for homogeneous coils	28
4.5 Homogeneous coils with slits	30
4.6 Optimum shape of homogeneous coil	32
4.7 Optimum axial current distribution	34
4.8 Radial current distributions	38
4.9 Other current distributions	39
4.10 Long solenoids	39
Chapter 5 FLUX DENSITY AND AMPERE-TURNS	43
5.1 Approximations	44
5.2 Stray flux and flux density	48
5.3 Low and medium fields	49
5.4 Example	54
5.5 High field magnets	56
5.6 Example	60
5.7 Influence of magnetizing coil	62

Chapter 6 CORE, YOKE AND COIL DIMENSIONS	66
6.1 Coil parameters	67
6.2 Yoke considerations	70
6.3 Volume of the magnet	71
Chapter 7 DESIGN PROCEDURE FOR ELECTROMAGNETS	76
Chapter 8 COOLING	83
8.1 Heat conduction in coils	83
8.2 Thermal conductivity	84
8.3 Space factor	87
8.4 Heat flow in coils	89
8.5 Axial temperature distribution	89
8.6 Radial heat-flow	92
8.7 Calculation of coil temperature	96
8.8 Average coil temperature	99
8.9 Final remarks	100
8.10 Heat transfer	101
8.11 Velocity	103
8.12 Transferred power	105
8.13 Heat transfer to free convecting air	108
Chapter 9 CONSTRUCTIONAL DETAILS	109
9.1 Coil design	109
9.2 Tube-wound coils	109
9.3 Tape-wound coils	110
9.4 Coil winding	111
9.5 Cooling disk	113
9.6 Wire-wound coils	115
9.7 Mounting	116
9.8 Core and yoke construction	118
Chapter 10 EXAMPLES	121
10.1 General procedure	122
10.2 Magnets with wire-wound coils	123
10.2.1 Simple laboratory magnet of low power	123
10.2.2 Wire-wound magnet for Hall-effect measurements .	127
10.3 Magnets with tape-wound coils	129
10.3.1 Two high-field magnets	129
10.3.2 Rotating magnet	131

Chapter 11 COMPARISON OF MAGNETS	133
11.1 De Klerk's criterion	134
11.2 Montgomery's comparison	138
Chapter 12 POWER SUPPLIES	140
12.1 Power sources	141
12.1.1 Batteries	141
12.1.2 Motor-generator sets	141
12.1.3 Silicon rectifiers	143
12.1.4 Silicon-controlled rectifiers (thyristors) and thyratrons	144
12.2 Current stabilization	148
12.2.1 Regulator elements	149
12.2.2 Reference voltage	150
12.2.3 Measuring resistor	152
12.3 Low-stability regulators	153
12.3.1 Light-spot regulator	153
12.3.2 Electronic-mechanical regulator	154
12.3.3 Feedback amplifier	156
12.3.4 Current stabilization with thyristors	156
12.4 Stability and accuracy of regulators	158
12.4.1 Stability criteria	160
12.5 More accurate regulators	163
12.6 High-stability current regulation	165
12.6.1 Field stabilizers	168
12.7 Protection	168
12.8 Reversal switch.	169
Chapter 13 FIELD HOMOGENEITY	171
13.1 Calculation of field distribution	172
13.2 Pole field and coil field	173
13.3 Calculation of pole field.	173
13.3.1 Cylindrical poles	173
13.3.2 Tapered poles	175
13.3.3 Numerical example	178
13.4 Coil fields	178
13.5 Comparison with experimental results	182
13.6 Methods of correcting magnetic fields	183
13.7 Correction rims (shims)	184
13.8 Current shims	186
13.8.1 Linear gradient shims	187

13.8.2 Circular current shims	189
13.9 Special pole-caps	192
Chapter 14 PULSED FIELDS	194
14.1 Limitations	195
14.2 Energy storage	196
14.3 Inductive energy storage	196
14.4 Capacitive storage	198
14.5 Current and dissipation	200
14.6 Coil dimensions and field	201
14.7 Heating of the coil	206
Chapter 15 PERMANENT MAGNETS	209
15.1 Principle of operation	209
15.2 General design considerations	211
15.3 Stray flux	211
15.4 Core shape	213
15.5 Approximative calculation of a permanent magnet with cylindrical core	215
15.6 Construction	218
15.7 Magnetization	218
Chapter 16 MEASUREMENT OF MAGNETIC FIELDS	220
16.1 Ballistic field measurement	220
16.1.1 Ballistic galvanometer	221
16.1.2 Electro-mechanical flux measurement	228
16.1.3 Electronic integration	229
16.1.4 Rotating coil fluxmeters	231
16.2 Hall-effect measurements	232
16.3 Magnetoresistance effect	233
16.4 Proton magnetic resonance	233
Chapter 17 BIBLIOGRAPHY	237
Index	249