

# Contents

Preface	xi
Acknowledgments	xv
<b>Chapter 1 Introduction</b>	
1.1 Introduction	1
1.2 Concept of a Backscattering Experiment and Its Layout	3
1.3 Basic Physical Processes	6
1.4 Examples and Applications	9
1.5 Strengths and Weaknesses of Backscattering Spectrometry	12
1.6 How to Read a Backscattering Spectrum	14
1.7 Book Outline	19
References	20
<b>Chapter 2 Basic Physical Concepts</b>	
2.1 Introduction	21
2.2 Kinematic Factor $K$	22
2.3 Scattering Cross Section $\sigma$	26
2.4 Energy Loss and Stopping Cross Section	32
2.5 Linear Additivity of Stopping Cross Sections (Bragg's Rule)	43
2.6 Energy Straggling	45
2.7 Linear Additivity of Energy Straggling	51
References	52

**Chapter 3 Concepts of Backscattering Spectrometry**

3.1	Introduction	54
3.2	Depth Scale for an Elemental Sample	59
3.3	Energy $E$ before Scattering	64
3.4	Numerical Methods to Find the Energy $E$ before Scattering	67
3.5	Height of an Energy Spectrum for an Elemental Sample	68
3.6	Depth Scale for a Homogeneous Solid Containing More Than One Element (Compound Sample)	76
3.7	Height of an Energy Spectrum for a Homogeneous Solid Containing More Than One Element (Compound Sample)	80
3.8	High-Energy Edge of an Energy Spectrum for an Elemental Sample with Several Isotopes	84
3.9	Energy Loss and Yield Respond to Atoms per Unit Area	85
3.10	Numerical Methods to Compute Backscattering Spectra	87
	References	88

**Chapter 4 Backscattering Spectrometry of Thin Films**

4.1	Introduction	89
4.2	Energy Spectrum of a Thin Elemental Film	90
4.3	Energy Spectrum of Multilayered Elemental Films	94
4.4	Energy Spectrum of a Homogeneous Thin Film Containing More Than One Element (Compound Film)	105
4.5	Energy Spectrum of Multilayered Films Containing More Than One Element (Layered Compound Films)	111
4.6	Influence of Energy Straggling and System Resolution	116
	References	122

**Chapter 5 Examples of Backscattering Analysis**

5.1	Introduction	123
5.2	Surface Impurity on an Elemental Bulk Target	124
5.3	Elemental Samples Containing Uniform Concentrations of Impurities	127
5.4	Composition of Homogeneous Samples Containing More Than One Element	130
5.5	Impurities Distributed in Depth in an Elemental Sample	137
5.6	Thickness of Thin Films	144
	References	152

**Chapter 6 Instrumentation and Experimental Techniques**

by R. A. LANGLEY

6.1	Introduction	153
6.2	Accelerator	154
6.3	Energy Stabilization System	160
6.4	Energy Calibration	161
6.5	The Vacuum System	164
6.6	Beam Definition and Measurement	166
6.7	Backscattering Beam Energy Analysis	170
6.8	Sample Holders	181
	References	183

**Chapter 7 Influence of Beam Parameters**

7.1	Introduction	185
7.2	Mass Resolution	186
7.3	Accessible Depth	193
7.4	Depth Resolution at Normal Incidence	198
7.5	Depth Resolution at Glancing Incidence	203
7.6	Sensitivity to Detection of Surface Impurities	207
7.7	Low-Energy Tails	209
7.8	Non-Rutherford Scattering, Nuclear Reactions, and Detection of Low-Mass Impurities	210
7.9	Microscopic Beam and Nonuniform Layers	218
	References	220

**Chapter 8 Use of Channeling Techniques**

8.1	Introduction	223
8.2	Crystal Alignment Procedures	225
8.3	Perfect Crystal	230
8.4	Lattice Disorder Amorphous Layers and Polycrystalline Films	239
8.5	Flux Peaking and Lattice Site Location of Impurities	264
8.6	Influence of the Analysis Film	272
	References	273

**Chapter 9 Energy-Loss Measurements**

9.1	Introduction	276
9.2	Extraction of $\epsilon$ Values from $[\epsilon]$ Measurements	277
9.3	Measurement of $[\epsilon]$ from Thin-Film Data	279
9.4	Determination of $[\epsilon]$ from Signal Height	281
	References	287

**Chapter 10 Bibliography on Applications of Backscattering Spectrometry**

10.1	Introduction	288
10.2	Surfaces	292
10.3	Bulk Properties	294
10.4	Oxide and Nitride Layers	299
10.5	Deposited and Grown Layers	302
10.6	Thin-Film Reactions	305
10.7	Ion Implantation in Metals	310
10.8	Ion Implantation in Semiconductors	313
10.9	Hydrogen and Helium in Metals	315
10.10	Sputtering and Blistering Processes	317
10.11	Microbeams and Other Applications	318

**Appendix A Transformation of the Rutherford Formula from Center of Mass to Laboratory Frame of Reference**

Appendix B	<b>Influence of Energy Straggling on a Thin-Film Spectrum</b>	323
Appendix C	<b>The True Position of the Edges of a Narrow Rectangular Signal</b>	328
Appendix D	<b>List of Energy-Loss Complications</b>	332
Appendix E	<b>Rough Targets</b>	334
Appendix F	<b>Numerical Tables</b>	339
Table I.	Elements	344
Table II.	$K_{M2}$ for $^1\text{H}$ as Projectile and Integer Mass $M_2$	350
Table III.	$K_{M2}$ for $^4\text{He}$ as Projectile and Integer Target $M_2$	354
Table IV.	$\bar{K}$ for $^1\text{H}$ as Projectile	358
Table V.	$\bar{K}$ for $^4\text{He}$ as Projectile	360
Table VI.	$^4\text{He}$ Stopping Cross Sections $\epsilon$	362
Table VII.	Polynomial Fit to the $^4\text{He}$ Stopping Cross Sections $\epsilon$	364
Table VIII.	$^4\text{He}$ Stopping Cross Section Factor $[\epsilon_0]$	366
Table IX.	$^4\text{He}$ Energy-Loss Factor $[S_0]$	368
Table X.	Rutherford Scattering Cross Section of the Elements for 1 MeV $^4\text{He}$	370
Table XI.	Surface Height of Backscattering Yield for $^4\text{He}$ on Elemental Targets $H_0$	372
Indexes		375