Contents

1	Introduction Structure and Structuring of Solids	
	By H-I Oneisser	1
	11 Score	1
	1.1 Scope	2
	1.2 A-Rays and Solids	2
	1.2.1 Optics and Solid-State Physics	3
	1.2.2 A-Rays and Solid State Thysics	3
	1.2.5 Outlook	4
	1.5 Sources	.4
	1.4 Structuring with A-Ray reeningues	5
	1.5 Interferometry	6
	Pafarances	7
		,
2.	High Brilliance X-Ray Sources. By M. Yoshimatsu and S. Kozaki	
	(With 15 Figures)	9
	21 History of the Development	9
	2.2 Brilliance of X-Ray Sources on Stationary and Moving Targets	12
	2.2 Brilliance of Foci for Stationary Targets	12
	2.2.2 Brilliance of Foci for Rotary Targets	15
	2.2.2 Brinnance of Foot for Recardy Fungets	18
	2.2.5 A Ruy Heid 2.2.2.5 A Ruy H	19
	2.5 Teenment Problems	19
	2.3.2 Construction of Rotary Targets	22
	2.3.2 Constitution of Rotary Targets	24
	2.3.5 Vacuum Scals	24
	2.3.4 Cooling Watch	25
	2.5.5 Influences of Back-Seattered Dectrons	25
	2.4 Contemporary Rotary Anode X-Ray Generators	25
	2.4.1 Rotary Ander X-Ray Generators	26
	2.4.2 Microlocus A-Ray Ociliators	20
	2.5 Special X-Ray Generators	27
	2.5.1 Soft A-Ray Generators	27
	2.5.2 Super High-Power A-Ray Generators	20
	2.5.5 Extreme Brilliance A-Kay Generators	∠9 21
	$2.5.4$ Pulsed X-Kay Generators $\dots \dots \dots \dots \dots \dots \dots$	21
	2.3.3 Uutlook	21
	References	- 32

VIII	Contents

э. л- і (W	ith 32 Figures)	35
3.1	Background	35
3.2	Description	35
3.3	Wavelength Selection	36
3.4	Masks	39
	3.4.1 Silicon Membranes	40
	3.4.2 Si_3N_4 and $Si_3N_4 + SiO_2$ Membranes	41
	3.4.3 Organic Films	41
3.5	X-Ray Sources	42
	3.5.1 X-Ray Generation by Electron Bombardment	42
	3.5.2 Synchrotron Radiation Sources	45
	3.5.3 Laser Generated Plasmas as X-Ray Sources	47
3.6	X-Ray Resists	48
	3.6.1 Performance of an Ideal Resist	49
	3.6.2 Real Resists	52
	Resist Characterization (Example PMMA)	53
	Resolution	59
	Sensitized X-Ray Resists	50
	Resist Summary	62
3.7	Alignment	64
	3.7.1 Possible Alignment Configurations	65
	Optical Alignment	67
	X-Ray Alignment	67
	3.7.2 Self-Aligning Methods	68
3.8	Subsequent Processing Steps	70
3.9	X-Ray Lithographic Systems	75
	3.9.1 Parallel Exposure of Many Wafers	76
	3.9.2 Single Wafer Exposure	77
3.1	0 Applications	79
	3.10.1 Magnetic Bubble Devices	79
	3.10.2 Semiconductor Devices	80
	3.10.3 Microscopy of Biological Objects	82
3.1	1 Performance and Limitations	83
3.1	2 Outlook: Focusing Elements for Soft X-Rays	86
Re	ferences	88
Re:	ferences	88
Bv	II Bonse and W. Graeff (With 25 Figures)	03
<i>D</i> y		, ,
4.1	Essentials of X-Ray and Neutron Interferometry) 4
	4.1.1 Relation to Electron Interferometry	} 4
	4.1.2 Principles of Interferometry	95
	4.1.3 Experimental Realization of Interferometry with X-Rays and	
	Thermal Neutrons	95

	4.2	Interferometer Components			98
		4.2.1 Plane Wave Theory of Interferometric Components .			99
		Beam Splitters			100
		Mirrors and Analyzers	•		109
		Influence of Component Translations			110
		4.2.2 Nonplanar Waves	•		111
	4.3	The LLL-Interferometer			114
		4.3.1 General Expressions for the Amplitudes			. 115
		4.3.2 The Ideal Geometry			. 116
		4.3.3 Energy Flow Considerations			. 118
		4.3.4 Geometrical Tolerances, Influence of Defocusing			. 119
		4.3.5 Positional Stability, Polylithic Interferometers			. 122
	4.4	Other Interferometer Types: Suggestions and Realizations			. 123
		4.4.1 Laue Case Variations of the LLL-Interferometer	•		. 124
		4.4.2 Bragg Case Interferometers	•		. 125
		4.4.3 The Three-Beam Case Interferometer	•		. 126
		4.4.4 Mixed Bragg-Laue Case Interferometers	•		. 126
		4.4.5 Michelson Interferometers	•		. 128
	4.5	Applications			. 128
		4.5.1 Moiré Technique and Defect Study			. 129
		4.5.2 Absolute Measurement of Lattice Parameter			. 131
		4.5.3 Determination of Scattering Factors <i>f</i> and Coherent			
		Scattering Lengths b_c			. 133
		4.5.4 Phase Contrast Topography			. 136
		4.5.5 Special Applications in Neutron Interferometry	•		. 136
	4.6	Conclusions			. 139
	Rei	ferences			. 140
5.	Sec	ction Topography.			
	By	A. Authier (With 36 Figures)	• •		. 145
	5.1	Principles of X-Ray and Neutron Topography	•		. 146
		5.1.1 Basic Topographic Methods	•		. 146
		5.1.2 Section Topography	•		. 146
		5.1.3 Double Crystal Topography	•		. 149
		5.1.4 Special Techniques	•		. 149
		5.1.5 Neutron Topography	•		. 150
	5.2	Bases of the Dynamical Theory of X-Ray Diffraction	•		. 152
		5.2.1 Introduction	•		. 152
		5.2.2 The Propagation Equation	•	•	. 152
		5.2.3 Plane Wave Theory	•	•	. 154
		5.2.4 Anomalous Transmission	•		. 159
		5.2.5 Spherical Wave Theory	•	•	. 160

X Contents

	5.3	Discussion of the Intensity Distribution Across a Section Pattern 5.3.1 Intensity Distribution for Each Branch of the Dispersion	163
		Surface	163
		532 Pendellösung or Kato Fringes	164
	54	Propagation of Wave Fields in a Deformed Crystal	166
	5.1	541 Introduction	166
		54.2 Small Strains	166
		5.43 Large Strains	168
	55	Dislocation Images on a Section Tonograph	160
	5.5	5.5.1 Various Types of Images	160
		5.5.1 Various Types of Images	109
		5.5.2 Direct images	170
		5.5.5 Dynamical images	175
		5.5.4 Intermediary Images	1/5
		5.5.5 Deformation of Pendellosung Fringes in the Neighborhood of	
		a Dislocation	177
	5.6	Images of Planar Defects on Section Topographs	177
		5.6.1 Various Types of Planar Defects	177
		5.6.2 Stacking Faults	178
		$5.6.3$ Twin Boundaries \ldots \ldots \ldots \ldots \ldots	183
		5.6.4 Misorientation Boundaries	184
		5.6.5 Boundaries Associated with a Strain Gradient	185
	Ref	ferences	187
6.	Liv By	Te Topography. W. Hartmann (With 25 Figures)	191
	6.1	X-Ray Topography	192
	6.2	Direct-Display Systems	194
		6.2.1 Single-Stage Imaging	196
		6.2.2 Multiple-Stage Imaging	206
	6.3	Summary	213
	64	Future Trends	216
	0.1	641 X-Ray Sources	210
		642 Detector Systems	210
		6.1.3 Electronic Image Processing	210
	Da	forences	217
	KC.		217
Ac	lditi	onal References with Titles	221
St	bjec	ct Index	223
			-