

Contents

1. Introduction. By G. Alefeld (With 6 Figures)	1
1.1 Metal Hydrides as Heat Transformer for Energy Cascading	2
References	9
2. The System NbH(D), TaH(D), VH(D): Structures, Phase Diagrams, Morphologies, Methods of Preparation	
By T. Schober and H. Wenzl (With 48 Figures)	11
2.1 Background	11
2.2 Structures	14
2.2.1 Methods of Structure Determination	14
2.2.2 Niobium Hydrides and Deuterides	15
2.2.3 Tantalum Hydrides and Deuterides	18
2.2.4 Vanadium Hydrides and Deuterides	21
The V-H System	21
The V-D System	23
2.3 Phase Diagrams	26
2.3.1 Examples of Phase Transitions	27
2.3.2 Nomenclature; Isotope, Impurity Effects	31
2.3.3 The NbH System	31
Remarks	31
2.3.4 The Ta-H System	35
2.3.5 The V-H System	38
2.3.6 The V-D System	40
2.4 Phase Morphologies	41
2.4.1 Hydride Morphologies in the Nb-H System	43
Metallographic Results	43
Electron Microscope Results	49
2.4.2 Hydride Morphologies in the Ta-H System	51
Metallographic Results	51
Electron Microscopy of Ta-H Alloys	52
2.4.3 Hydride Morphologies in the V-H System	53
Metallography	53
Electron Microscopy of V-H Alloys	54
2.5 Preparation of Samples	55
2.5.1 Purification of the Matrix Metal	55

2.5.2 Analysis of Impurity Contents	57
2.5.3 Growth, Shaping, and Characterization of Single Crystals .	58
2.5.4 Synthesis of Hydrides	60
2.6 Conclusion	65
References	67

3. Hydrogen in Palladium and Palladium Alloys

By E. Wicke and H. Brodowsky, with cooperation by H. Züchner (With 35 Figures).	73
3.1 Overview	73
3.2 Thermodynamics	74
3.2.1 Basic Relationships	74
3.2.2 Phase Diagram, Methods, and Results	77
3.2.3 Bulk and Surface Behavior	84
3.2.4 Equilibrium Isotope Effects	88
3.2.5 Statistical Thermodynamics of Solute-Solute Interactions .	98
3.2.6 Analogous Binary Alloys	104
3.3 Interpretation of Nonideal Solution Behavior	108
3.3.1 Lattice Strain Energy	108
3.3.2 Excess Functions at Constant Volume and at Constant Pressure	111
3.3.3 The Specific Heat Anomaly at 55 K	113
3.4 Palladium Alloys	118
3.4.1 Fermi Energy Rise and Nearest Neighbor Effects in Ternary Systems	118
3.4.2 Statistical Thermodynamics of Ternary Systems	123
3.4.3 The Rigid Band Model and Its Limitations	127
3.5 Hydrogen Mobility in Palladium and Palladium Alloys	134
3.5.1 Surface Kinetics and Stationary Permeation	134
3.5.2 Time-Lag Methods (by H. Züchner)	140
References	151

4. Metal-Hydrogen Systems at High Hydrogen Pressures

By B. Baranowski (With 26 Figures)	157
4.1 High Pressure Devices	158
4.1.1 First Experiments with High Pressures of Gaseous Hydrogen	158
4.1.2 Devices Applying Liquid Transmitting Media	161
4.1.3 Devices Without Pressure Transmitting Media	162
4.2 Thermodynamic Properties	165
4.2.1 General Considerations	165
4.2.2 Palladium and Palladium Alloys	167
4.2.3 Nickel and Nickel Alloys	173

4.2.4 Other Systems	177
The Cr-H System	177
The Mn-H System	179
4.3 Electronic, Structural, and Transport Properties	180
4.3.1 Electrical Resistance	180
4.3.2 Superconductivity	187
4.3.3 Thermopower	189
4.3.4 Magnetic Measurements	192
4.3.5 X-Ray Investigations	194
4.3.6 Thermal Conductivity	195
4.3.7 Diffusion	196
4.4 Conclusions and Perspectives	197
References	198

5. Hydrogen Storage in Metals. By R. Wiswall (With 16 Figures)	201
5.1 Introduction	201
5.1.1 The Need of Storage	201
5.1.2 Methods of Storage	202
5.1.3 Other Reviews	203
5.2 Hydrides as Storage Media	203
5.2.1 Reversible and Irreversible Systems.	203
5.2.2 Pressure-Temperature-Composition (P-T-C) Relations . .	204
5.2.3 Complications of Real Systems. Hysteresis	206
5.2.4 Thermodynamics of Hydrides	209
5.2.5 Alloy-Hydrogen Reactions	210
5.2.6 Complex Hydrides	212
5.2.7 Kinetic Considerations	212
5.2.8 Hydrogen Content	215
5.2.9 Temperature and Enthalpy Criteria.	215
5.3 Survey of Hydride Storage Systems	217
5.3.1 Alkali Metals and Their Alloys	217
5.3.2 Alkaline Earth Metals and Their Alloys.	218
5.3.3 Metals of Group III and Their Alloys.	220
5.3.4 Titanium, Zirconium, Hafnium, and Their Alloys	224
5.3.5 Vanadium, Niobium, Tantalum, and Their Alloys	228
5.3.6 Palladium, Uranium, Thorium, and Their Alloys	229
5.4 Specific Applications	229
5.4.1 Remote Generation of Electricity	230
5.4.2 Electric Utility Load Leveling	230
5.4.3 Automotive Propulsion	233
5.4.4 Battery-Related Uses	236

5.4.5 Nonfuel Applications	236
Hydride Engines	236
Heat Storage	237
Thermometers	237
References	238
 6. Superconductivity in Metal-Hydrogen Systems	
By B. Stritzker and H. Wühl (With 13 Figures)	243
6.1 Superconductivity and Normal-State Parameters	243
6.2 Influence of Hydrogen on the Superconductivity of Various Metals and Metal Alloys	245
6.3 Special Preparation Methods for Superconducting Thorium and Palladium Hydrides	248
6.3.1 Preparation of Bulk Th_4H_{15}	248
6.3.2 Preparation of Superconducting Pd Hydrides ($\text{H/Pd} > 0.8$) .	249
High Pressure or Electrolytic Charging at Low Temperatures	249
H Implantation at He Temperatures	249
Codeposition of Pd and Hydrogen	250
6.4 Superconducting Properties of the Pd-H System	250
6.4.1 T_c Dependence on H(D) Concentration	251
6.4.2 Pressure Effect on T_c	252
6.4.3 Critical Field	253
6.4.4 T_c Variation in the H(D) Charged Systems Ni-Pd-Pt and Rh-Pd-Ag	253
6.4.5 T_c Variation in H(D) Charged Pd-Noble Metal Alloys .	255
6.4.6 T_c in Other Hydrogenated Pd Alloys	256
6.4.7 T_c in Pd Alloys with Interstitial Elements	257
6.5 Superconducting Properties of the Th-H System	257
6.5.1 T_c of the Th-H(D) System	257
6.5.2 Pressure Effect on T_c	258
6.5.3 Critical Field	258
6.5.4 T_c of Th Alloys with Other Interstitials	258
6.6 Electron and Phonon Properties of the Pd-H System	259
6.6.1 Low Temperature Specific Heat	259
6.6.2 Neutron-Scattering Experiments	260
6.6.3 Tunneling Experiments	261
6.6.4 Temperature Dependence of the Electrical Resistivity .	264
6.6.5 Theories	265
6.7 Electron and Phonon Properties of the Th-H System	267
6.7.1 Low Temperature Specific Heat	267
6.7.2 Neutron-Scattering Experiments	267
6.7.3 Theory	268
6.8 Conclusion	268
References	269

7. Electro- and Thermotransport of Hydrogen in Metals	
By H. Wipf (With 7 Figures)	273
7.1 Background	273
7.2 Phenomenological Description	274
7.2.1 Forces and Hydrogen Flux	274
7.2.2 The Influence of Stresses	276
7.2.3 Steady States	277
7.2.4 Time-Dependent Transport Processes	278
7.2.5 The Onsager Relations	279
7.3 Atomistic Origin of the Forces	281
7.3.1 Electrotransport	281
7.3.2 Thermotransport	283
7.4 Experimental Considerations and Techniques	284
7.4.1 The Physical Quantities of Interest	284
Z^* and Q^*	284
The Chemical Potential μ	285
Diffusion Coefficient D and Mobility M	286
7.4.2 Drift-Velocity and Flux Measurements	286
7.4.3 Steady-State Measurements	288
7.4.4 Diffusion Potential Measurements	289
7.5 Experimental Data	290
7.5.1 Effective Charge Number	290
Size of Z^*	290
Isotope Dependence	294
Temperature Dependence	294
Concentration Dependence	295
Correlation with the Hall Coefficient	296
Transport Measurements in a Hall Field	296
7.5.2 Heat of Transport	296
Size of Q^*	296
Isotope Dependence	299
Temperature Dependence	299
Effects of Concentration and Lattice Structure	300
7.6 Technological Aspects	300
References	301
8. Trapping of Hydrogen in Metals. By Ch. A. Wert (With 11 Figures)	305
8.1 Overview	305
8.2 Thermodynamics of Random Solutions	306
8.3 General Features of Trapping	307
8.4 Accumulation in Voids	308
8.5 Accumulation of Hydrogen in High Strain Fields	311
8.6 Grain Boundary Traps	313
8.7 Dislocation Trapping	316

8.8 Impurity Trapping	319
8.8.1 The Gorsky Effect	324
8.8.2 Measurement of Trapping by Study of the Kinetics of Phase Changes	325
8.8.3 Trapping by Substitutional Alloying Elements	325
8.8.4 Low Temperature Resistivity Measurements	326
8.9 Interstitial Location by Nuclear Microanalysis	326
8.10 Summary	328
References	328
 Additional References with Titles	331
 Author Index	333
 Subject Index	351