



# CONTENTS

**Preface**    **xiii**

**Symbols Used in the Text**    **xvii**

**Chapter 1**    **An Overview: Concepts, Units, and  
the Bohr Atom**    **1**

1.1 Introduction    1

1.2 Energies, Units, and Particles    4

1.3 Particle–Wave Duality and Lattice Spacings    7

1.4 The Bohr Model    9

Problems    10

References    12

**Chapter 2**    **Atomic Collisions and Backscattering  
Spectrometry**    **13**

2.1 Introduction    13

2.2 Kinematics of Elastic Collisions    15

2.3 Rutherford Backscattering Spectrometry — An  
Example    18

2.4 Scattering Cross Section and Impact  
Parameter    19

2.5 Central Force Scattering    21

2.6 Scattering Cross Section: Two-Body    25

2.7 Deviations from Rutherford Scattering at Low  
and High Energy    26

2.8	Low Energy Ion Scattering (LEIS)	29
2.9	Forward Recoil Spectrometry	31
2.10	Center of Mass to Laboratory Transformation	33
	Problems	37
	References	38

**Chapter 3 Energy Loss of Light Ions and Backscattering Depth Profiles 39**

3.1	Introduction	39
3.2	General Picture of Energy Loss and Units of Energy Loss	39
3.3	Energy Loss of MeV Light Ions in Solids	41
3.4	Energy Loss in Compounds—Bragg's Rule	47
3.5	The Energy Width in Backscattering	48
3.6	The Shape of the Backscattering Spectrum	51
3.7	Depth Profiles with Rutherford Scattering	53
3.8	Depth Resolution and Energy Loss Straggling	56
3.9	Hydrogen and Deuterium Depth Profiles	59
3.10	Ranges of H and He Ions	62
3.11	Sputtering and Limits to Sensitivity	64
3.12	Summary of Scattering Relations	66
	Problems	66
	References	68

**Chapter 4 Sputter Depth Profiles and Secondary Ion Mass Spectrometry 69**

4.1	Introduction	69
4.2	Sputtering by Ion Bombardment—General Concepts	71
4.3	Nuclear Energy Loss	74
4.4	Sputtering Yield	79
4.5	Secondary Ion Mass Spectrometry (SIMS)	81
4.6	Secondary Neutral Mass Spectrometry (SNMS)	87
4.7	Preferential Sputtering and Depth Profiles	89
4.8	Interface Broadening and Ion Mixing	91
4.9	Thomas–Fermi Statistical Model of the Atom	94
	Problems	96
	References	97

**Chapter 5 Channeling 99**

5.1	Introduction	99
5.2	Channeling in Single Crystals	99

	5.3 Lattice Location of Impurities in Crystals	104
	5.4 Channeling Flux Distributions	105
	5.5 Surface Interaction via a Two-Atom Model	109
	5.6 The Surface Peak	113
	5.7 Substrate Shadowing: Epitaxial Au on Ag(111)	117
	5.8 Epitaxial Growth	119
	5.9 Thin Film Analysis	120
	Problems	122
	References	123
<b>Chapter 6</b>	<b>Electron-Electron Interactions and the Depth Sensitivity of Electron Spectroscopies</b>	<b>125</b>
	6.1 Introduction	125
	6.2 Electron Spectroscopies: Energy Analysis	125
	6.3 Escape Depth and Detected Volume	126
	6.4 Inelastic Electron-Electron Collisions	130
	6.5 Electron Impact Ionization Cross Section	131
	6.6 Plasmons	133
	6.7 The Electron Mean Free Path	135
	6.8 Influence of Thin Film Morphology on Electron Attenuation	136
	6.9 Range of Electrons in Solids	141
	6.10 Electron Energy Loss Spectroscopy (EELS)	144
	6.11 Bremsstrahlung	148
	Problems	151
	References	152
<b>Chapter 7</b>	<b>Surface Structure</b>	<b>155</b>
	7.1 Introduction	155
	7.2 Diffraction Parameters	156
	7.3 Thermal Vibrations and the Debye-Waller Factor	158
	7.4 Low Energy Electron Diffraction (LEED)	161
	7.5 Glancing Angle X-ray Diffraction	167
	7.6 Transmission Electron Microscopy	173
	Problems	179
	References	180
<b>Chapter 8</b>	<b>Photon Absorption in Solids and EXAFS</b>	<b>181</b>
	8.1 Introduction	181
	8.2 The Schrödinger Equation	182
	8.3 Wave Functions	184
	8.4 Quantum Numbers, Electron Configuration, and Notation	187

8.5	Transition Probability	189
8.6	Photoelectric Effect — Square Well Approximation	190
8.7	Photoelectric Transition Probability for a Hydrogenic Atom	193
8.8	X-ray Absorption	195
8.9	Extended X-ray Absorption Fine Structure (EXAFS)	201
8.10	Time-Dependent Perturbation Theory	204
	Problems	211
	References	212

**Chapter 9 X-ray Photoelectron Spectroscopy (XPS) 213**

9.1	Introduction	213
9.2	Experimental Considerations	214
9.3	Kinetic Energy of Photoelectrons	218
9.4	Photoelectron Energy Spectrum	220
9.5	Binding Energy and Final State Effects	221
9.6	Binding Energy Shifts; Chemical Shifts	224
9.7	Quantitative Analysis	226
	Problems	228
	References	230

**Chapter 10 Radiative Transitions and the Electron Microprobe 233**

10.1	Introduction	233
10.2	Nomenclature in X-ray Spectroscopy	234
10.3	Dipole Selection Rules	235
10.4	Electron Microprobe	236
10.5	Transition Rate for Spontaneous Emission	240
10.6	Transition Rate for $K_{\alpha}$ Emission in Ni	240
10.7	Electron Microprobe: Quantitative Analysis	243
10.8	Proton- (and Helium-) Induced X-ray Emission (PIXE)	247
10.9	Evaluation of the Transition Probability for Radiative Transitions	249
10.10	Calculation of $K_{\beta}/K_{\alpha}$ Ratio	252
	Problems	254
	References	255

**Chapter 11 Nonradiative Transitions and Auger Electron Spectroscopy 257**

11.1	Introduction	257
11.2	Auger Transitions	258

	11.3 Yield of Auger Electrons and Fluorescence Yield	266
	11.4 Atomic Level Width and Lifetimes	268
	11.5 Auger Electron Spectroscopy	269
	11.6 Quantitative Analysis	274
	11.7 Auger Depth Profiles	275
	Problems	279
	References	281
<b>Chapter 12</b>	<b>Nuclear Techniques: Activation Analysis and Prompt Radiation Analysis</b>	<b>283</b>
	12.1 Introduction	283
	12.2 Q Values and Kinetic Energies	288
	12.3 Radioactive Decay	292
	12.4 Radioactive Decay Law	295
	12.5 Radionuclide Production	296
	12.6 Activation Analysis	298
	12.7 Prompt Radiation Analysis	299
	Problems	308
	References	309
<b>Appendix 1</b>	<b><math>K_{M_2}</math> for <math>^4\text{He}</math> as Projectile and Integer Target Mass</b>	<b>311</b>
<b>Appendix 2</b>	<b>Rutherford Scattering Cross Section of the Elements for 1 MeV <math>^4\text{He}</math></b>	<b>315</b>
<b>Appendix 3</b>	<b><math>^4\text{He}</math> Stopping Cross Sections</b>	<b>317</b>
<b>Appendix 4</b>	<b>Electron Configurations and Ionization Potentials of Atoms</b>	<b>321</b>
<b>Appendix 5</b>	<b>Electron Binding Energies (eV)</b>	<b>323</b>
<b>Appendix 6A</b>	<b>X-ray Wavelengths</b>	<b>325</b>
<b>Appendix 6B</b>	<b>Mass Absorption Coefficients and Densities</b>	<b>327</b>
<b>Appendix 7</b>	<b>KLL Auger Energies (eV)</b>	<b>329</b>
<b>Appendix 8</b>	<b>Table of the Elements</b>	<b>333</b>
<b>Appendix 9</b>	<b>Table of Fluorescence Yields for K, L, and M Shells</b>	<b>341</b>
<b>Appendix 10</b>	<b>Physical Constants, Conversions, and Useful Combinations</b>	<b>343</b>
<b>Index</b>		<b>345</b>