

CONTENTS

Preface	V
1. INTRODUCTION	1– 6
2. INTRODUCTION TO THE BASIC THEORY	7–38
2.1. Introduction	7
2.2. The diffraction of electrons by a crystal	8
2.3. The two-beam dynamical equations	12
2.4. The absorption parameters	15
2.4.1. <i>The normal absorption coefficient \mathcal{N}</i>	15
2.4.2. <i>The anomalous absorption coefficient \mathcal{A}</i>	17
2.5. The deviation of the crystal from the Bragg reflecting position	18
2.5.1. <i>The deviation vector s_g</i>	19
2.6. The extinction distance	22
2.6.1. <i>The theoretical two-beam extinction distance ξ_g</i>	22
2.6.2. <i>The apparent extinction distance ξ_{ga}</i>	25
2.7. The displacement vector R	27
2.7.1. <i>The displacement due to a stacking fault</i>	28
2.7.2. <i>The displacement vector R for a dislocation</i>	29
2.8. The foil normal F	38
3. EXPERIMENTAL TECHNIQUES	39–84
3.1. Introduction	39
3.2. Image-diffraction pattern rotation	40
3.3. Crystal tilting technique	46
3.4. Specific indexing of the orientation map and diffracting vectors	49
3.4.1. <i>Experimental examples</i>	56
3.5. Determination of beam direction B	60

3.6. Determination of defect line direction u	62
3.7. Determination of foil normal F	64
3.8. Extinction distance	69
3.9. Determination of w	75
3.10. Determination of foil thickness	79
3.11. Anomalous absorption coefficient	83
4. PRINCIPLES OF ONEDIS	85–123
4.1. Introduction	85
4.2. The two basic principles	86
<i>4.2.1. The generalised cross-section</i>	88
<i>4.2.2. Linear combinations</i>	90
4.3. Modifications to the generalised cross-section to accomodate experimental situations	95
<i>4.3.1. Tilted foils</i>	95
<i>4.3.2. Changes in the magnification and in the framing of computed micrographs</i>	96
<i>4.3.3. Variable foil thickness</i>	103
4.4. Program geometry	106
4.5. The grey scale and printing the micrograph	115
5. MATCHING WITH ONEDIS	125–143
5.1. Introduction	125
5.2. Aluminium	126
5.3. β -brass	136
6. PRINCIPLES OF TWODIS	145–173
6.1. Introduction	145
6.2. The two basic principles	146
<i>6.2.1. The generalised cross-section</i>	146
<i>6.2.2. Linear combinations</i>	150
6.3. The operation of the program	152
<i>6.3.1. Examples of the cases which may be computed with TWODIS</i>	152
<i>6.3.2. Check sums and conventions</i>	155
6.4. Program geometry and arrangement of the calculation	158
6.5. Extension of the program to more complex configurations	172
7. MATCHING WITH TWODIS	175–200
7.1. Introduction	175
7.2. Example 1, defect A	175
7.3. Example 2, defect B	181

8. APPLICATIONS OF THE TECHNIQUE	201–287
8.1. Introduction	201
8.2. Influence of elastic anisotropy on the invisibility of dislocations	202
8.3. Effective invisibility of images due to large values of w	206
8.4. Diffraction contrast from lines of dilation	206
8.5. Apparent anomalous absorption	211
8.6. Nature of stacking faults	216
8.7. Identification of bent dislocations	218
8.8. A dissociation reaction in β -brass	222
8.9. Contrast from partial dislocations	225
8.9.1. <i>Partial dislocations bordering a single stacking fault</i>	225
8.9.2. <i>Partial dislocations separating intrinsic and extrinsic faults</i>	233
8.10. Dissociated Frank dislocations	235
8.11. Growth of Frank loops by fault climb	243
8.12. Dislocation dipoles in nickel	260
8.13. Contrast from overlapping faults	274
8.14. Analysis of partial dislocations and stacking faults on closely spaced planes	279
9. DISCUSSION OF THE APPLICATIONS AND LIMITATIONS OF THE TECHNIQUE	289–308
9.1. Introduction	289
9.2. Uniqueness and the amount of information necessary to identify defects	289
9.3. Optimisation of the technique	292
9.4. Limitations in the theory	302
9.5. Restrictions inherent in the programs	305
10. COMPUTER PROGRAMS	309–375
10.1. Introduction	309
10.1.1. <i>Computer environment</i>	310
10.1.2. <i>Program speed</i>	310
10.1.3. <i>Program size</i>	311
10.1.4. <i>Program options</i>	311
10.1.5. <i>General conventions</i>	312
10.2. Program ONEDIS for one dislocation and cubic crystals	313
10.2.1. <i>General description</i>	313
10.2.2. <i>Data</i>	313
10.2.3. <i>Geometry</i>	315
10.2.4. <i>Error messages</i>	317
10.2.5. <i>Anisotropic elasticity</i>	317
10.2.6. <i>Picture output</i>	317

<i>10.2.7. Howie–Whelan differential equations</i>	318
<i>10.2.8. Picture legend</i>	321
<i>10.2.9. Listing of program ONEDIS</i>	322
10.3. Subroutines	325
<i>10.3.1. Subroutine ANCALC for cubic crystals</i>	325
<i>10.3.2. Subroutine NEWTON</i>	333
<i>10.3.3. Subroutine RKM</i>	335
<i>10.3.4. Subroutine DERIV for one dislocation</i>	338
10.4. Special test version of program ONEDIS	339
10.5. Subroutine HALFTN	342
10.6. Programs for other crystal systems	344
<i>10.6.1. Introduction</i>	344
<i>10.6.2. Program modification – general discussion</i>	345
<i>10.6.3. The tetragonal system – modification TETDIS</i>	348
<i>10.6.4. The hexagonal system – modification HEXDIS</i>	352
<i>10.6.5. The testing of programs developed for non-cubic crystal systems</i>	358
<i>10.6.6. Modification of other programs for non-cubic systems</i>	360
10.7. Isotropic elasticity	360
10.8. Modification DELUGE	361
10.9. Program 'TWODIS' for cubic crystals	364
<i>10.9.1. Introduction</i>	364
<i>10.9.2. Program TWODIS</i>	364
<i>10.9.3. Listing of program TWODIS</i>	368
<i>10.9.4. Subroutine DERIV for two dislocations</i>	374
10.10. Dark field pictures	374
APPENDIX	377–386
A.1. Introduction	377
A.2. Single dislocations	378
A.3. Single stacking faults	382
A.4. Relations between dislocation–stacking fault images	383
A.5. The symmetry of dislocation dipole images	384
A.6. The effect of elastic symmetry on dislocation images	385
REFERENCES	387
SUBJECT INDEX	390