Contents

Prefe	ace	v
СНА	PTER 1. Introduction	
	Principal Interaction Phenomena	1
1.2	Interaction Diagrams References	3 8
	Part I—General Principles	
СНА	PTER 2. Introduction to Tensor Analysis	
2.1	Definitions of Tensors	11
2.2	Symmetry Properties of Tensors	13
	Contraction of Tensors	14
2.4	Transformation of Tensors from One Set of Axes to Another	15
2.5	Vector and Scalar Products—Gradient, Divergence, and Curl of Vectors	16
2.6	The Representation Quadric	18
2.7	Tensors Involving the Direction Cosines a_{ij}	23
2.8	Polar and Axial Vectors	27
2.9	Some Integral Theorems of Interest	29
	Resume	32
	Problems	34
	References	35
CHA	PTER 3. Definition of Fundamental Variables Involved in Interaction Effects	
2.1	Electric Fields and Directorante	36
	Electric Fields and Displacements	41
	Magnetic Variables Magnetic Variables Torser Form	48
	Maxwell's Equations in Tensor Form Stress Tensors	50
	Strain Tensors	57
		63
3.7	Elasticity Thermal Variables	69
3.1	Resume	75
		77
	Problems References	78
	N ETET ETILES	, 0

X CONTENTS

CHAPTER 4. Equilibrium Thermodynamics, Thermodynamic

	Functions, and Maxwell Relations	
4.1	Thermodynamic Functions for Mechanical and Thermal Variables	79
4.2	Thermodynamic Functions for Mechanical, Electrical, and Thermal	
	Variables for Piezoelectric Crystals	82
4.3	Numerical Values for Interaction Effects	90
4.4	Electrostrictive Properties of Ferroelectric Materials	94
4.5	Magnetostrictive and Piezomagnetic Properties of Ferromagnetic	
	Materials	100
	Resume	104
	Problems References	106
	References	100
СНА	PTER 5. Crystal Symmetries and Their Effects on Tensor Properties	
5.1	Crystal Systems, Crystal Classes, and Miller Indices	108
	Crystal Point-Group Symmetries	112
5.3		116
	Resume	119
	Problems	120
	References	121
СНА	Part II—Application of Equilibrium Interaction Processes PTER 6. Applications of Piezoelectric and Piezomagnetic Materials to Transducers	
. 1	Turker desertion	125
11.000	Introduction Properties of Principal Piezoelectric Crystals	123
	Wave Transmission in Piezoelectric Crystals—Equivalent Circuits	136
	Design of Transducers from Equivalent Circuits	146
6.5	<u> </u>	
0.5	of Magnetism	152
	Resume	154
	n 11	
	Problems	155
	References	155 156
СНА		
	References PTER 7. Crystal Optics and the Electro-optic and Piezo- optic Effects	156
7.1	References PTER 7. Crystal Optics and the Electro-optic and Piezo-	

	CONTENTS	xi
7.3	Uses for the Optical Properties of Crystals	163
7.4	Thermodynamic Derivation of Electro-optic and Piezo-optic Effects	165
7.5		
7.6	of the Electro-optic and Piezo-optic Constants Quadratic Electro-optic ("Kerr") Effect in Cubic Crystals	170
	Piezo-optic Effect in Isotropic Materials	176 180
	Resume	183
	Problems	186
	References	187
СНА	PTER 8. Optical Activity and the Faraday Effect	
8.1	Introduction	188
	Optical Activity and Birefringence	190
	Optical Rotation Due to the Faraday Effect	194
	Microwave Faraday Effect	197
8.5		198
	Resume Problems	200 203
	References	203
		200
	Part III—Transport Crystalline Properties That Depend on Irreversible Thermodynamics	
СНА	PTER 9. Thermal and Electrical Conductivities	e v
9.1	Introduction: Nonreversible Thermodynamics	207
	Thermal Conductivities and Resistivities	210
9.3		to a series of the
	Electrical Conductivity	216
	Resume	216 217
	Resume Problems	216 217 219
	Resume	216 217
СНА	Resume Problems	216 217 219
СНА 10.1	Resume Problems References PTER 10. Piezoresistivity	216 217 219
	Resume Problems References	216 217 219 220
10.1	Resume Problems References PTER 10. Piezoresistivity Introduction: Energy Surfaces and Electron Flows	216 217 219 220 221 227 231
10.1 10.2	Resume Problems References PTER 10. Piezoresistivity Introduction: Energy Surfaces and Electron Flows Phenomenological Development of Piezoresistivity Best Orientations for Measuring Strains Resume	216 217 219 220 221 227 231 237
10.1 10.2	Resume Problems References PTER 10. Piezoresistivity Introduction: Energy Surfaces and Electron Flows Phenomenological Development of Piezoresistivity Best Orientations for Measuring Strains	216 217 219 220 221 227 231

xii CONTENTS

CHA	PTER 11. Hall Effect and Magnetoresistance Effect and Their Uses in Transducers	
11.1	Introduction	241
11.2	Phenomenological Derivation of Hall and Magnetoresistance Effects	246
11.3		258
	Resume	263
	Problems	265
	References	266
CHA	PTER 12. Thermoelectricity	
12.1	Introduction	267
12.2	Derivation of Thermoelectric Effects in Isotropic Solids	268
12.3	Thermoelectric Effects in Continuous Isotropic Media	272
	Practical Applications of the Thermoelectric Effect	276
12.5		282
12.6	Effect of Magnetic Flux on Thermoelectric Properties	285
	Resume	292
	Problems	298
	References	298
APPE	NDIX A. Electromagnetic Wave Propagation in a Crystalline Medium	
A.1	Solution of Maxwell's Equations	301
A.2	Derivation of the Indicatrix and Fresnel's Ellipsoids from Maxwell's	
	Equations	305
A.3	Effect of Optical Activity on the Transmission of Light Waves	
	in Crystals	309
A.4	Rotation of Light Waves Due to the Faraday Effect	318
	References	324
APPE	NDIX B. Tables of Tensor Terms for Polar and Axial Tensors	
B.1	Tables of Polar Tensors	326
B.2	Tables of Axial Tensors	334
B.3	Third-Order Elastic Moduli	340
	References	340
Autho	or Index	341
Subje	Subject Index	