

CONTENTS

CHAPTER I. PRODUCTION OF LOW TEMPERATURES	1
1. Isentropic cooling. 2. Isenthalpic cooling. 3. Air liquefiers. 4. Hydrogen liquefiers. 5. Helium liquefiers. 6. Gas purification and compression. 7. References.	
CHAPTER II. STORAGE AND TRANSFER OF LIQUEFIED GASES	34
1. Dewar vessels. 2. Transfer siphons. 3. Liquid-level indicators and depth gauges. 4. Liquid-level controllers. 5. References.	
CHAPTER III. HEAT EXCHANGERS	58
1. Introduction. 2. Calculation of pressure gradient and heat transfer. 3. Methods of construction. 4. Example of heat-exchanger analysis. 5. References.	
CHAPTER IV. TEMPERATURE MEASUREMENT	74
1. Introduction. 2. Relation of thermodynamic and gas scales to the international scale. 3. Fixed points. 4. Gas thermometry. 5. Vapour-pressure thermometry. 6. Electrical resistance of metallic elements. 7. Metallic alloys as resistance thermometers. 8. Semiconducting resistance thermometers. 9. Thermocouple thermometers. 10. References.	
CHAPTER V. HEAT TRANSFER	127
1. Introduction. 2. Conduction of heat by a gas. 3. Heat transfer through solids. 4. Heat transfer by radiation. 5. Other causes of heat transfer. 6. Example of heat-transfer calculation. 7. Heat transfer through pressed contacts. 8. Heat switches. 9. References.	
CHAPTER VI. TEMPERATURE CONTROL	157
1. Introduction. 2. Control of vapour pressure. 3. Control by electrical heating. 4. Controlled refrigeration. 5. Flow method of control. 6. References.	
CHAPTER VII. INTRODUCTION TO CRYOSTAT DESIGN	171
1. General considerations. 2. Cryostats for specific-heat measurements. 3. Cryostats for measurement of thermal conductivity and thermoelectric power. 4. Cryostat (1–300 K) for expansion measurements. 5. Cryostats for electrical resistance or Hall-effect measurements. 6. Cryostats for optical and X-ray examination of materials. 7. Magnetic susceptibility cryostats. 8. Other cryostats. 9. References.	

CHAPTER VIII. COOLING WITH HELIUM-3	201
1. Introduction. 2. Helium-3 cryostats (evaporation). 3. Helium-3 dilution. 4. Leiden 'superleak' refrigerator. 5. Pomeranchuk cooling. 6. Thermometry. 7. References.	
CHAPTER IX. ADIABATIC DEMAGNETIZATION	219
1. Introduction. 2. Paramagnetic salts. 3. Temperature measurement. 4. Cryostats. 5. Heat transfer and thermal equilibrium below 1 K. 6. Two-stage cooling, cyclic magnetic refrigeration, and nuclear demagnetization. 7. Magnets. 8. References.	
CHAPTER X. VACUUM TECHNIQUES AND MATERIALS	255
1. Introduction. 2. Vacuum technique. 3. Solders. 4. Vacuum seals and cements. 5. References.	
CHAPTER XI. PHYSICAL PROPERTIES OF SOLIDS	275
1. Heat capacity of solids. 2. Thermal expansion. 3. Electrical resistivity. 4. Thermal conductivity. 5. References.	
APPENDIX	
Tables	307
Cryogenic equipment	321
SUBJECT INDEX	327