

Table of Contents

1. Introduction	1
1.1 Interfacial Pattern Formations in Dendrite Growth and Hele-Shaw Flow	1
1.2 A Brief Review of the Theories of Free Dendrite Growth	9
1.2.1 Maximum Velocity Principle (1976)	9
1.2.2 Marginal Stability Hypothesis (1978)	10
1.2.3 Microscopic Solvability Condition (MSC) Theory (1986–1990s)	11
1.2.4 Interfacial Wave (IFW) Theory (1990)	12
1.3 Macroscopic Continuum Model	13
1.3.1 Macroscopic Transport Equations	14
1.3.2 The Interface Conditions	16
1.3.3 The Scaling and the Dimensionless System	21
References	24
2. Unidirectional Solidification and the Mullins–Sekerka Instability	27
2.1 Solidification with Planar Interface from a Pure Melt	27
2.1.1 Basic Steady State Solution	28
2.1.2 Unsteady Perturbed Solutions and Mullins–Sekerka Instability	29
2.1.3 Asymptotic Solutions in the Long-Wavelength Regime, $k = O(\varepsilon)$	38
2.1.4 Asymptotic Solutions in the Extremely Short-Wavelength Regime, $k = O(\frac{1}{\varepsilon})$	42
2.2 Unidirectional Solidification from a Binary Mixture	48
2.2.1 Mathematical Formulation of the Problem	48
2.2.2 Basic Steady State	50
2.2.3 Unsteady Perturbed Solutions	52
2.2.4 Asymptotic Solutions in the Long-Wavelength Regime, $k = O(\varepsilon)$	60
2.2.5 Asymptotic Solutions in the Extremely Short-Wavelength Regime, $\{k = O(\frac{1}{\varepsilon}); g = O(\frac{1}{\varepsilon})\}$	62
2.2.6 Some Remarks on Unidirectional Solidification	66
References	67

3. Mathematical Formulation of Free Dendrite Growth from a Pure Melt	69
3.1 Three-Dimensional Axially Symmetric Free Dendrite Growth	70
3.2 Two-Dimensional Free Dendrite Growth	75
Reference	78
4. Steady State of Dendrite Growth with Zero Surface Tension and Its Regular Perturbation Expansion	79
4.1 The Ivantsov Solution and Unsolved Fundamental Problems	79
4.2 Three-Dimensional Axially Symmetric Steady Needle Growth	81
4.2.1 Mathematical Formulation	81
4.2.2 The Regular Perturbation Expansion Solutions (RPE) as $\epsilon \rightarrow 0$	82
4.2.3 The Asymptotic Behavior of the Regular Perturbation Expansion Solution as $\xi \rightarrow \infty$	92
4.3 Two-Dimensional, Steady Needle Crystal Growth	94
4.3.1 Mathematical Formulation of Two-Dimensional Needle Growth	94
4.3.2 The Regular Perturbation Expansion Solution as $\epsilon \rightarrow 0$	95
4.3.3 Asymptotic Behavior of the Regular Perturbation Expansion Solution as $\xi \rightarrow \infty$	100
4.4 Summary and Discussion	101
References	103
5. The Steady State for Dendrite Growth with Nonzero Surface Tension	105
5.1 The Nash–Glicksman Problem and the Classic Needle Crystal Solution	105
5.2 The Geometric Model and Solutions of the Needle Crystal Formation Problem	108
5.2.1 Geometric Model of Dendrite Growth	108
5.2.2 The Segur–Kruskal Problem	109
5.2.3 Nonclassic Steady Needle Growth Problem	111
5.2.4 Needle Crystal Formation Problem	118
5.3 The Nonclassic Steady State of Dendritic Growth with Nonzero Surface Tension	120
5.3.1 The Complete Mathematical Formulation for Free Dendrite Growth	120
References	123
6. Global Interfacial Wave Instability of Dendrite Growth from a Pure Melt	125
6.1 Linear Perturbed System Around the Basic State of Three-Dimensional Dendrite Growth	126

6.2	Outer Solution in the Outer Region away from the Tip	128
6.2.1	Zeroth-Order Approximation	131
6.2.2	First-Order Approximation	134
6.2.3	Singular Point ξ_c of the Outer Solution	138
6.3	The Inner Solutions near the Singular Point ξ_c	142
6.4	Tip Inner Solution in the Tip Region	152
6.5	Global Trapped-Wave Modes and the Quantization Condition	154
6.6	Global Interfacial Wave Instability of Two-Dimensional Dendrite Growth	161
6.7	The Comparison of Theoretical Predictions with Experimental Data	172
	References	179
7.	The Effect of Surface Tension Anisotropy and Low-Frequency Instability on Dendrite Growth	181
7.1	Linear Perturbed System Around the Basic State	183
7.2	Multiple Variable Expansion Solution in the Outer Region ...	184
7.3	The Inner Equation near the Singular Point ξ_c	187
7.3.1	Case I: $\sigma_0 = O(1)$	191
7.3.2	Case II: $ \sigma_0 \ll 1$	192
7.3.3	A Brief Summary	195
7.4	Matching Conditions	197
7.5	The Spectra of Eigenvalues and Instability Mechanisms	197
7.5.1	The Global Trapped-Wave Instability	198
7.5.2	The Low-Frequency Instability	204
7.6	Low-Frequency Instability for Axially Symmetric Dendrite Growth	208
7.7	The Selection Conditions for Dendrite Growth	209
	References	212
8.	Three-Dimensional Dendrite Growth from Binary Mixtures	213
8.1	Mathematical Formulation of the Problem	214
8.2	Basic State Solution for the Case of Zero Surface Tension ...	215
8.3	Linear Perturbed System for the Case of Nonzero Surface Tension	216
8.4	The MVE Solutions in the Outer Region	220
8.4.1	The Zeroth-Order Approximation	220
8.4.2	The First-Order Approximation	222
8.5	The Inner Solutions near the Singular Point ξ_c	226
8.6	Global Modes and the Quantization Condition	229
8.7	Comparisons of Theoretical Results with Experimental Data .	238
	References	241

XII Table of Contents

9. Viscous Fingering in a Hele-Shaw Cell	243
9.1 Introduction	243
9.2 Mathematical Formulation of the Problem	249
9.3 The Smooth Finger Solution with Zero Surface Tension	251
9.4 Formulation of the General Problem in Curvilinear Coordinates (ξ, η) and the Basic State Solutions	254
9.5 The Linear Perturbed System and the Outer Solutions	257
9.6 The Inner Equation near the Singular Point ξ_c	265
9.6.1 Case I: $ \sigma_0 = O(1)$	269
9.6.2 Case II: $ \sigma_0 \ll 1$	270
9.7 Eigenvalues Spectra and Instability Mechanisms	272
9.7.1 The Spectrum of Complex Eigenvalues and GTW Instability	273
9.7.2 The Spectrum of Real Eigenvalues and the LF Instability	276
9.8 Fingering Flow with a Nose Bubble	280
9.8.1 The Basic State of Finger Formation with a Nose Bubble and Its Linear Perturbation	280
9.8.2 The Quantization Conditions for the System with a Nose Bubble	283
9.9 The Selection Criteria of Finger Solutions	287
References	289
Bibliography.....	291
Index	293

