

Preface	vii
Chapter 1 Toroidal Configuration	1
1.1 INTRODUCTION	1
1.2 GENERAL COORDINATES	5
1.3 BASIS VECTORS, METRIC TENSOR	6
1.4 VECTOR OPERATORS	9
1.5 MAGNETIC FIELD REPRESENTATION	10
1.6 MAGNETIC SURFACES	11
1.7 MAGNETIC SURFACE DESTRUCTION	12
1.8 THE STANDARD MAP	22
1.9 Problems	27
1.10 References	28
Chapter 2 Equilibrium	31
2.1 INTRODUCTION	31
2.2 THE VIRIAL THEOREM	32
2.3 FIELD LINE CURVATURE	33
2.4 GENERAL 3-D EQUILIBRIA	34
2.5 AXISYMMETRIC EQUILIBRIA	42
2.6 TOKAMAK ORDERING	43
2.7 CYLINDRICAL TOKAMAK EQUILIBRIA	44
2.8 THE SHAFRANOV EQUILIBRIUM	47
2.9 HIGH BETA EQUILIBRIUM	53
2.10 FLUX CONSERVING EQUILIBRIA	56
2.11 EQUILIBRIUM SCALING	57
2.12 EQUILIBRIUM TYPES	57
2.13 Problems	60
2.14 References	61
Chapter 3 Guiding Center Motion	63
3.1 INTRODUCTION	63
3.2 HAMILTONIAN FORMULATION	66
3.3 ORBIT CLASSIFICATION	74
3.4 INTEGRAL INVARIANTS	82
3.5 TOROIDAL PRECESSION	85
3.6 LARGE ASPECT RATIO	86
3.7 DIAMAGNETIC CURRENT	90
3.8 CONFINEMENT OF FUSION ALPHA PARTICLES	92
3.9 Problems	93

3.10 References	94
Chapter 4 Linear Ideal Modes	95
4.1 INTRODUCTION	95
4.2 PLASMA KINETIC AND POTENTIAL ENERGY	100
4.3 SELF ADJOINTNESS OF THE POTENTIAL ENERGY	101
4.4 THE ENERGY PRINCIPLE	102
4.5 CONVENIENT FORM FOR SW	103
4.6 THE ENERGY PRINCIPLE IN CYLINDRICAL GEOMETRY	107
4.7 MHD INSTABILITIES IN LOW $\beta$ TOKAMAKS	111
4.8 KINK MODE	113
4.9 THE $m=1$ EXTERNAL KINK	118
4.10 THE INTERNAL KINK MODE	119
4.11 BALLOONING INSTABILITIES	122
4.12 MAGNETIC WELL	128
4.13 BALLOONING, SIMPLE EQUILIBRIA	129
4.14 MERCIER, SUYDAM CRITERIA	132
4.15 MODIFICATION OF THE BALLOONING EQUATION	136
4.16 TAE MODES	137
4.17 AXISYMMETRIC MODES	138
4.18 NUMERICAL MHD SPECTRUM	141
4.19 SHAPE AND ASPECT RATIO	142
4.20 Problems	146
4.21 References	147
Chapter 5 Linear Resistive Modes	151
5.1 INTRODUCTION	151
5.2 THE TEARING MODE	156
5.3 THE $m = 1$ TEARING MODE	166
5.4 THE SKIN CURRENT PROFILE	172
5.5 TOROIDAL AND SHAPING EFFECTS	173
5.6 THE RESISTIVE SURFACE KINK MODE	174
5.7 OPTIMIZED PROFILES	177
5.8 THE RIPPLING MODE	179
5.9 THE RESISTIVE INTERCHANGE MODE	180
5.10 RESISTIVE BALLOONING	180
5.11 DIAMAGNETIC ROTATION	182
5.12 Problems	186
5.13 References	188

Chapter 6 Nonlinear Behavior	191
6.1 INTRODUCTION	191
6.2 THE REDUCED EQUATIONS	195
6.3 NONLINEAR EXTERNAL KINK	198
6.4 VACUUM BUBBLES	201
6.5 NONLINEAR INTERNAL KINK	205
6.6 COMPLETE RESISTIVE RECONNECTION	207
6.7 NONLINEAR TEARING MODE ANALYSIS	209
6.8 SAWTOOTH OSCILLATIONS	215
6.9 DISRUPTIONS	221
6.10 EMPIRICAL LIMITS	225
6.11 STABILIZATION OF TEARING MODES	226
6.12 Problems	230
6.13 References	231
Chapter 7 Mode-Particle Interaction	237
7.1 INTRODUCTION	237
7.2 PASSING PARTICLE RESONANCE	243
7.3 TAE MODE DRIVE AND SATURATION	245
7.4 TRAPPED PARTICLE RESONANCE	249
7.5 FISHBONE INDUCED LOSS	252
7.6 FISHBONE DESTABILIZATION	253
7.7 THE FISHBONE CYCLE	263
7.8 RESISTIVE KINETIC INTERNAL KINK	265
7.9 STABILIZATION OF THE SAWTOOTH	266
7.10 BALLOONING DESTABILIZATION	272
7.11 ALPHA PARTICLE EFFECTS	272
7.12 Problems	274
7.13 References	275
Chapter 8 Transport	279
8.1 INTRODUCTION	279
8.2 THE DRIFT KINETIC EQUATION	283
8.3 CROSS FIELD DIFFUSION	286
8.4 BOOTSTRAP CURRENT	290
8.5 NEOCLASSICAL TEARING	294
8.6 WARE PINCH	295
8.7 MAGNETIC FIELD RIPPLE TRANSPORT	295
8.8 DIFFUSION IN A STOCHASTIC FIELD	307
8.9 ISLAND INDUCED DIFFUSION	310

8.10 ANOMALOUS TRANSPORT	313
8.11 CONFINEMENT SCALING	317
8.12 BURN CONTROL	320
8.13 THE LITHIUM WALL CONCEPT	321
8.14 Problems	322
8.15 References	325
Chapter 9 Phase Integral Methods	331
9.1 INTRODUCTION	331
9.2 CONNECTION FORMULAE	334
9.3 CAUSALITY	341
9.4 BOUND STATES – INSTABILITIES	342
9.5 OVERDENSE BARRIER – SCATTERING	346
9.6 UNDERDENSE BARRIER – SCATTERING	350
9.7 EIGENVALUE PROBLEMS	353
9.8 Problems	358
9.9 References	361
Index	363