

MEASUREMENT QUALITY ASSURANCE FOR IONIZING RADIATION DOSIMETRY

CONTENTS

PREFACE	1
ABSTRACT	5
EXECUTIVE SUMMARY	7
1 INTRODUCTION	9
2 DEVELOPMENT OF THE QUALITY SYSTEM AND QUALITY MANUAL	11
2.1 Principal concepts	11
2.1.1 <i>Calibration quantities and concepts</i>	13
2.2 Elements of the quality system	13
2.2.1 <i>Elements of the quality system for accredited calibration laboratories and SSDLs</i>	13
2.2.2 <i>Elements of the quality system for facilities performing measurements</i>	14
2.2.3 <i>Elements of the quality system for manufacturers</i>	15
2.2.4 <i>Elements of the quality system for end users</i>	15
3 MEASUREMENT QUALITY ASSURANCE	17
3.1 Specification of measurement quality	17
3.2 Effects of influence quantities on measurement quality	17
3.3 Methods for the evaluation of uncertainty	17
3.3.1 <i>Type A methods to evaluate the uncertainty</i>	18
3.3.2 <i>Type B methods to evaluate the uncertainty</i>	19
3.3.3 <i>Calculation of the standard uncertainty of the output estimate</i>	20
3.3.4 <i>Expanded uncertainty and coverage factor k</i>	22
3.4 Equipment control system	23
3.4.1 <i>Confirmation, calibration, and verification</i>	23
3.4.2 <i>Determination of lower limit of detection or minimal detectable amount</i>	24
3.4.3 <i>Corrections to measurements</i>	25
4 MEASUREMENT ANALYSIS METHODS	27
4.1 Control charts	27
4.2 Long-term statistical analysis of data	27
4.3 Treatment of outliers	27
4.4 Error (quality anomaly) correction procedures	28
4.5 Review and approval of records	29
4.6 Quality audit and quality system review	29

5	PRACTICAL APPLICATIONS AND RECOMMENDATIONS	31
5.1	Examples of recorded and reported information	31
5.2	Practical considerations for measurement providers	31
5.2.1	<i>Primary laboratory</i>	31
5.2.2	<i>Secondary laboratories</i>	31
5.2.3	<i>Dosimetry service</i>	33
5.2.4	<i>Manufacturer</i>	34
5.2.5	<i>End user</i>	34
5.3	Computer handling of data and measurement control	34
5.4	Environmental factors	35
5.5	Characteristics of calibration procedures	35
5.5.1	<i>Determining the dosimetric quantity at a point in the radiation field</i>	35
5.5.2	<i>Determining the dosimetric quantity from a radiation source calibration</i>	36
5.6	Materials and equipment control	36
5.7	Interactions between manufacturers and calibration laboratories	37
5.8	Incorrect use of devices	38
5.9	Source encapsulation problems	38
	DEFINITIONS AND GLOSSARY OF TERMS	39
	APPENDIX A	43
	APPENDIX B	45
	REFERENCES	47