

Quantitative Aspects of Bone Densitometry

Contents

Preface	1
Abstract	3
1 Introduction	5
2 Quantities and Units in Bone Densitometry	7
2.1 Introduction	7
2.2 Quantities and Units of Mass, Density, and Concentration	8
2.3 Quantities and Units for X-Ray Bone Densitometry	8
2.4 Quantities and Units for Ultrasonic Bone Densitometry	9
3 Quality and Performance Measures in Bone Densitometry	11
3.1 Introduction	11
3.2 Physical Performance Measures	12
3.2.1 Trueness and Bias	12
3.2.2 Precision	13
3.2.2.1 Short-term Imprecision	13
3.2.2.2 Long-term Imprecision	14
3.2.3 Clinical Limitations of Physical Performance Measures	14
3.3 Diagnostic Performance Measures	14
3.3.1 Conceptual Definition of Osteoporosis	14
3.3.2 Diagnostic Criteria for the Individual Patient	15
3.3.2.1 Fracture Status	15
3.3.2.2 Low Bone Mineral Density	15
3.3.2.3 Clinical Limitations of the WHO Definition of Osteoporosis	16
3.3.3 Diagnostic Performance of Techniques	17
3.3.3.1 Concepts of Diagnostic Performance	17
3.3.4 Reference Data	18
3.3.5 Clinical Limitations of Bone Mineral Density as Diagnostic Criterion	19
3.4 Performance Measures to Assess Fracture Risk	20
3.4.1 Relevance of Fracture Risk Assessment	20
3.4.2 Basic Definitions	20
3.4.3 Risk Factors and Fracture Risk	21
3.4.4 Statistical Methods for Characterizing Fracture Risk	22
3.4.4.1 Student's <i>t</i> -test Analysis	22
3.4.4.2 Linear Discriminant Analysis	23
3.4.4.3 Logistic Regression Analysis	24
3.4.4.4 Poisson Regression Model	25
3.4.4.5 Cox Proportional Hazard Model	25
3.4.5 Comparison of Statistical Methods	26

3.4.5.1	Discriminant Analysis versus Logistic Regression	26
3.4.5.2	Comparison of Regression and Survival Models	27
3.4.6	Performance Measures for Risk Prediction	28
3.4.7	Combination of Risk Factors	28
3.4.8	The Individual Patient	28
3.4.8.1	Assessment of Fracture Risk	28
3.4.8.2	Treatment Decisions	29
3.5	Performance Measures to Assess Monitoring	29
3.5.1	Measures of Change	29
3.5.1.1	Longitudinal Response and Response Rates	29
3.5.1.2	Significant Changes and Monitoring Intervals	29
3.5.2	Monitoring Performance of Techniques	30
3.5.2.1	Longitudinal Sensitivity	30
3.5.2.2	Standardized Imprecision	30
3.5.3	Monitoring of Individual Patients	30
4	Concepts of Quality Assurance and Standardization	33
4.1	Introduction	33
4.2	Standardization	33
4.3	Calibration	34
4.4	Longitudinal Instrument Control	34
4.5	Other Quality Assurance Measures	35
5	X-ray Absorptiometry	37
5.1	Introduction	37
5.2	Physics of Absorptiometry	37
5.2.1	Sources of Systematic Errors	39
5.2.2	Single-Energy Absorptiometry	39
5.2.3	Dual-Energy Absorptiometry	41
5.3	Radiographic Absorptiometry	41
5.3.1	Equipment and Data Acquisition	41
5.3.1.1	Skeletal Sites	41
5.3.1.2	Image Formation	42
5.3.1.3	Image Calibration and Analysis	42
5.3.2	Performance Measures	43
5.3.2.1	Trueness	43
5.3.2.2	Imprecision	43
5.3.3	Reference Data	44
5.4	Radiogrammetry	44
5.4.1	Equipment and Data Acquisition	44
5.4.1.1	Image Formation	44
5.4.1.2	Image Analysis	45
5.4.1.3	Digital X-ray Radiogrammetry	46
5.4.2	Performance Measures	46
5.4.2.1	Trueness	46
5.4.2.2	Precision	46
5.4.3	Reference Data	47
5.5	Single- and Dual-Energy X-ray Absorptiometry	48
5.5.1	Equipment	48
5.5.1.1	X-ray Sources	48
5.5.1.2	Detectors	49
5.5.2	Data Acquisition	49
5.5.2.1	Imaging Geometry	49
5.5.2.2	Skeletal Sites	50
5.5.3	Performance Measures	53

5.5.3.1	Trueness	53
5.5.3.2	Imprecision	56
5.5.4	Reference Data	57
5.5.5	Standardization	57
6	Quantitative Computed Tomography	59
6.1	Introduction	59
6.2	CT Physics Relevant to QCT	59
6.2.1	Single-Energy QCT (SEQCT)	59
6.2.2	Dual-Energy QCT (DEQCT)	60
6.2.3	Scan Modes	61
6.3	QCT of the Lumbar Spine	62
6.3.1	Equipment and Data Acquisition	62
6.3.1.1	Localizer Radiograph	62
6.3.1.2	CT Images	62
6.3.2	Quantitative Image Analysis	63
6.3.2.1	Regions of Interest	63
6.4	Peripheral QCT	64
6.4.1	Equipment and Data Acquisition	64
6.4.2	Quantitative Image Analysis	64
6.5	Volumetric QCT	65
6.6	Performance Measures	65
6.6.1	Sources of Error	66
6.6.1.1	Trueness	66
6.6.1.2	Precision	67
6.6.2	Reference Data	68
6.7	Standardization	69
7	Quantitative Ultrasound	71
7.1	Introduction	71
7.2	Physics of Ultrasound Relevant for the Characterization of Bone	72
7.2.1	Fundamentals of Ultrasound	72
7.2.1.1	Frequency–Period–Wavelength	73
7.2.1.2	Phase Velocity–Group Velocity	73
7.2.1.3	Stress	73
7.2.1.4	Acoustic Impedance	73
7.2.1.5	Intensity	73
7.2.1.6	Speed of Sound	74
7.2.2	Tissue Interaction	76
7.2.2.1	Specular Reflection and Refraction	76
7.2.2.2	Attenuation	80
7.3	Principles of Data Acquisition and Signal Processing	82
7.3.1	Transverse Transmission	82
7.3.1.1	Broadband Ultrasound Attenuation	82
7.3.1.2	Speed of Sound	84
7.3.2	Axial Transmission	86
7.4	Equipment	86
7.4.1	Transverse Transmission of the Heel	87
7.4.1.1	Parameters	87
7.4.1.2	Water-Based Devices	87
7.4.1.3	Dry Contact Devices	87
7.4.1.4	Fixed Versus Moving Transducers	88
7.4.1.5	Imaging Devices	88
7.4.2	Transverse Transmission of the Finger Phalanges	88

7.4.3	Axial Transmission	89
7.5	Performance Measures	90
7.5.1	Trueness	90
7.5.1.1	Diffraction	91
7.5.1.2	Phase Cancellation	91
7.5.1.3	Algorithms	92
7.5.1.4	Soft Tissue and Cortical Endplates	92
7.5.1.5	Incorrect ROI Positioning	93
7.5.2	Imprecision	93
7.5.2.1	Coupling	94
7.5.2.2	Temperature	94
7.5.2.3	Soft Tissue	94
7.5.2.4	Patient Position and Movement	95
7.5.2.5	Operator	95
7.5.2.6	Recommendations to Improve Precision	95
7.6	QUS Variables Related to Bone Strength	95
7.6.1	Solution of Direct and Inverse Problems	96
7.6.1.1	Cortical Bone	96
7.6.1.2	Cancellous Bone	98
7.6.1.3	Conclusion	100
7.6.2	Experimental Results	101
7.6.2.1	Cortical Bone	101
7.6.2.2	Cancellous Bone	102
7.6.2.3	Reflection Techniques	103
8	Summary and Recommendations	105
9	Terminology and Abbreviations	107
9.1	General Terminology	107
9.2	X-Ray-based Techniques	108
9.3	Ultrasound-based Techniques	111
References		115