

CONTENTS

PREFACE	v
CONTENTS	vii
LIST OF MOST IMPORTANT SYMBOLS; PREFERRED UNITS	xi
CHAPTER 1. BASIC CONCEPTS	1
1. Introduction	1
2. Methods of growth from the melt	4
3. Methods of growth from solution	8
4. Other methods for the growth of crystals	10
4.1. Crystal growth in the solid state	10
4.2. Crystal growth from the vapour	12
5. Phase relations	14
6. Growth kinetics.	17
7. Transport effects	22
CHAPTER 2. SOLIDS, LIQUIDS AND GASES	26
1. Introduction	26
2. Binding forces in solids	26
3. Crystal lattices	28
4. Equilibrium defects	30
5. Non-equilibrium defects	33
6. Impure solids	40
7. The solid-liquid transition	42
8. Sublimation and evaporation	44
9. Phase relations	46
9.1. Major components	47
9.2. Minor components	53
10. The estimation of relevant physical properties	64
10.1. Background	64

10.2. Specific heats	65
10.3. Phase transitions	70
10.4. Viscosities	70
10.5. Diffusion coefficients	71
10.6. Thermal conductivities.	73
10.7. Thermal expansion	73
10.8. Surface tension	75
10.9. Emissivities	76
10.10. Solutions	77
10.11. Conclusions	77
CHAPTER 3. GROWTH KINETICS.	78
1. Introduction	78
2. The driving force	79
3. Crystal morphology	81
4. Possible types of interface	85
5. Nucleation	89
6. Growth on rough sharp interfaces.	97
7. Growth on perfect sharp singular interfaces.	103
8. Growth on imperfect sharp singular interfaces	110
9. Diffuse interfaces	117
10. Some conclusions about growth mechanisms	119
11. The interface segregation coefficient	120
CHAPTER 4. TRANSPORT PROCESSES	128
1. Introduction	128
2. Boundary layer theory	129
3. Transport in bulk liquids.	138
4. Transport in solids	143
5. Transport effects at growing interfaces	150
5.1. The steady state growth rate	150
5.2. Effective segregation coefficients	154
5.3. Non-steady state effects	158
6. Interface stability	160
CHAPTER 5. GENERAL TECHNIQUES	171
1. Introduction	171
2. Constructional materials.	171
3. Methods of heating	175

4. Temperature measurement	180
5. Temperature control.	183
6. The production of slow movements	190
7. Methods for attaching seed crystals	192
8. Containers	194
9. Atmospheres	197
10. Starting materials	201
11. Methods of assessment	202
CHAPTER 6. MELT GROWTH IN CRUCIBLES	207
1. Introduction	207
2. General considerations	209
3. Apparatus for normal freezing	211
3.1. Crucibles	211
3.2. Furnaces	214
4. Apparatus for zone methods	218
5. Techniques for volatile materials	220
6. The control of perfection.	223
CHAPTER 7. PULLING FROM THE MELT	226
1. Introduction	226
2. Some basic concepts.	228
2.1. The shape of the liquid surface	228
2.2. The interface shape	230
2.3. Static heat flow	231
2.4. Dynamic heat flow	232
2.5. The rate of growth	233
3. Apparatus	234
4. Volatile materials	240
5. Some modifications to the method.	244
5.1. The growth of dendrites	244
5.2. Pulling shaped crystal	245
6. The addition of dopants	247
7. The control of perfection.	252
7.1. The control of crystallographic quality.	253
7.2. The control of homogeneity	255
CHAPTER 8. MELT GROWTH WITHOUT CRUCIBLES	258
1. Introduction	258
2. The Verneuil technique	259

3.	Floating zone refining	265
3.1.	Stability of floating zones	265
3.2.	Means for producing molten zones	269
3.3.	Other apparatus requirements	274
3.4.	The control of perfection.	277
4.	The submerged-arc fusion method.	279
CHAPTER 9. LOW TEMPERATURE SOLUTION GROWTH		282
1	Introduction	282
2.	Solvents	284
3.	Other general considerations	288
4.	Slow cooling methods	290
5.	Evaporation methods	293
6.	Temperature gradient methods	295
7.	The control of perfection.	297
CHAPTER 10. HIGH TEMPERATURE SOLUTION GROWTH		301
1.	Introduction	301
2.	Properties of typical solvents	302
3.	Slow cooling methods	308
4.	Evaporation methods	317
5.	Temperature gradient methods	319
6.	Some special methods	324
7.	The control of perfection.	327
CHAPTER 11. THE SELECTION OF METHODS		330
1.	Introduction	330
2.	Technical choices	330
3.	Available experience.	331
4.	Economic aspects	333
5.	Optimization	335
6.	Some conclusions on crystal growth	337
REFERENCES		338
AUTHOR INDEX		363
SUBJECT INDEX		377