Contents

No	otat	ion	ciii
1.	Int	roduction	1
	1.1.	Surface States and Surface Sites	1
		1.1.1. The Chemical Versus Electronic Representation of	
		the Surface	1
		1.1.2. The Surface State on the Band Diagram	4
		1.1.3. The Fermi Energy in the Surface State Model .	6
		1.1.4. Need for Both Surface Site and Surface State Models	6
	1.2.	Bonding of Foreign Species to the Solid Surface	7
		1.2.1. Types of Interaction	7
		1.2.2. The Chemical Bond	10
		1.2.3. Acid and Basic Surface Sites on Solids	14
		1.2.4. Adsorbate Bonding on Various Solid Types	16
		1.2.5. Movement of Surface Atoms: Relaxation,	
		Reconstruction, and Relocation	17
		1.2.6. The Electronic Energy Level (Surface State) of a	
		Sorbate/Solid Complex	19
	1.3.	Surface Hydration on Ionic Solids	20
	1.4.	Surface Heterogeneity	22
2.	Spa	ace Charge Effects	25
	2.1.	General	25
		2.1.1. The Double Layer Involving Two Planar Sheets of	
		Charge	28

Contents

		2.1.2.	The Space Charge due to Immobile Ions: The	•••
		2.1.3.	The Double Layer in the Band Diagram, Fermi Energy Pinning	29 31
	2.2.	Space	Charge Effects with Reactive Surface Species	35
		2.2.1.	The Accumulation Layer	37
		2.2.2.	The Inversion Layer	38
	2.3.	Electro	n and Hole Transfer between the Solid and Its	
		Surface		39
		2.3.1.	Basic Physical Model of Electron and Hole Capture or Injection	40
		2.3.2.	Electron and Hole Transfer with Large Changes in	
			the Surface Barrier	44
		2.3.3.	Charge Transfer to a Surface Species in a Polar	
			Medium: The Fluctuating Energy Level Mechanism	47
3.	Exp	perim	ental Methods	57
	3.1.	Surface	Measurements Based on Electrical and Optical	
		Tachai		50
		rechnic	ques	58
		3.1.1.	Work Function.	58 59
		3.1.1. 3.1.2.	Work Function. Surface Conductivity	58 59 60
		3.1.1. 3.1.2. 3.1.3.	Work Function. .	58 59 60 62
		3.1.1. 3.1.2. 3.1.3. 3.1.4.	Work Function. .	58 59 60 62 63
		3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5.	Work Function. Surface Conductivity Surface Conductivity Surface Conductivity Field Effect Surface Conductivity Surface Photovoltage Surface Conductivity	58 59 60 62 63 64
		3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6.	Work Function. .	58 59 60 62 63 64 66
		3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7.	Work Function. .	58 59 60 62 63 64 66 68
		3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8.	Work Function.	58 59 60 62 63 64 66 68 69
		3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9.	Work Function.	58 59 60 62 63 64 66 68 69 71
		3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10.	Work Function.	58 59 60 62 63 64 66 68 69 71 72
	3.2.	3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10. The Su	Work Function.	58 59 60 62 63 64 66 68 69 71 72 73
	3.2.	3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10. The Su 3.2.1.	Work Function.	58 59 60 62 63 64 66 68 69 71 72 73 76
	3.2.	3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10. The Su 3.2.1. 3.2.2.	Work Function.Surface ConductivityElectroreflectanceField EffectSurface PhotovoltageCapacity of the Double LayerChannel MeasurementsPowder ConductanceEllipsometryOther Electrical and Optical Measurementsurface SpectroscopiesUltraviolet Photoelectron Spectroscopy (UPS)Energy Loss Spectroscopy (ELS)	58 59 60 62 63 64 66 68 69 71 72 73 76 79
	3.2.	3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10. The Su 3.2.1. 3.2.2. 3.2.3.	JuesWork FunctionWork FunctionSurface ConductivityElectroreflectanceField EffectSurface PhotovoltageCapacity of the Double LayerChannel MeasurementsPowder ConductanceEllipsometryOther Electrical and Optical MeasurementsUltraviolet Photoelectron Spectroscopy (UPS)Energy Loss Spectroscopy (ELS)Soft X-Ray Appearance Potential Spectroscopy(SXAPS)	58 59 60 62 63 64 66 68 69 71 72 73 76 79 80
	3.2.	3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10. The Su 3.2.1. 3.2.2. 3.2.3. 3.2.4	Work Function. Surface Conductivity Surface Conductivity Surface Conductivity Field Effect Field Effect Surface Photovoltage Surface Conductage Capacity of the Double Layer Capacity of the Double Layer Channel Measurements Channel Measurements Powder Conductance Surface Spectroscopies Char Electrical and Optical Measurements Surface Spectroscopy (UPS) Energy Loss Spectroscopy (ELS) Soft X-Ray Appearance Potential Spectroscopy (SXAPS) Field Emission (FEM) Surface Spectroscopy (ELS)	58 59 60 62 63 64 66 68 69 71 72 73 76 79 80 81
	3.2.	3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10. The Su 3.2.1. 3.2.2. 3.2.3. 3.2.4. 3.2.5	JuesWork FunctionWork FunctionSurface ConductivitySurface ConductivitySurface ConductivityField EffectField EffectSurface PhotovoltageSurface ConductageCapacity of the Double LayerCapacity of the Double LayerChannel MeasurementsSurface ConductancePowder ConductanceSurface SpectroscopiesCharnel MeasurementsSurface SpectroscopiesUltraviolet Photoelectron Spectroscopy (UPS)Energy Loss Spectroscopy (ELS)Soft X-Ray Appearance Potential SpectroscopyField Emission (FEM)Field Lon Microscopy (ELM)	58 59 60 62 63 64 66 68 69 71 72 73 76 79 80 81 83
	3.2.	3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10. The Su 3.2.1. 3.2.2. 3.2.3. 3.2.4. 3.2.5. 3.2.6	Work Function. Work Function. Surface Conductivity Surface Conductivity Electroreflectance Field Effect Surface Photovoltage Surface Photovoltage Capacity of the Double Layer Capacity of the Double Layer Channel Measurements Channel Measurements Powder Conductance Surface Photovoltage Other Electrical and Optical Measurements Surface Spectroscopies Ultraviolet Photoelectron Spectroscopy (UPS) Energy Loss Spectroscopy (ELS) Soft X-Ray Appearance Potential Spectroscopy (SXAPS) Surface Spectroscopy (FIM) Field Ion Microscopy (FIM) Surface Spectroscopy (INS)	58 59 60 62 63 64 66 68 69 71 72 73 76 79 80 81 83 84
	3.2.	3.1.1. 3.1.2. 3.1.3. 3.1.4. 3.1.5. 3.1.6. 3.1.7. 3.1.8. 3.1.9. 3.1.10. The Su 3.2.1. 3.2.2. 3.2.3. 3.2.4. 3.2.5. 3.2.6. 3.2.7.	JuesWork FunctionWork FunctionSurface ConductivityElectroreflectanceField EffectSurface PhotovoltageCapacity of the Double LayerChannel MeasurementsPowder ConductanceEllipsometryOther Electrical and Optical MeasurementsUltraviolet Photoelectron Spectroscopy (UPS)Energy Loss Spectroscopy (ELS)Soft X-Ray Appearance Potential SpectroscopyField Emission (FEM)Field Ion Microscopy (FIM)Ion Neutralization Spectroscopy (INS)Low-Energy Electron Diffraction (LEED)	58 59 60 62 63 64 66 68 69 71 72 73 76 79 80 81 83 84 85

		3.2.8.	Methods of Chemical Composition Determination	
			for the Surface	87
		3.2.9.	Studies of Chemical Reactions due to the Impinging	
			Beam	90
	3.3.	Chemi	cal Measurements	92
		3.3.1.	Infrared Absorption	93
		3.3.2.	Temperature-Programmed Desorption	95
		3.3.3.	Adsorption of Gaseous Acids and Bases or of	
			Indicators	96
4.	The	e Ad	sorbate-Free Surface	99
	4.1.	Introd	uction	99
		4.1.1.	The Classification of Solids	99
		412	Prenaration of a Clean Surface	101
	4 2	Theore	tical Models	103
		421	Quantum Models	103
		422	Semiclassical Models: The Madelung Model for	105
			Ionic Solids	114
		4.2.3.	Models for Electron Pair Sharing: Lewis and	
		112.01	Brønsted Sites	117
		424	Comparison of the Various Surface States and Sites	121
	4.3.	Measu	rements on Adsorbate-Free Ionic Solids	125
		4.3.1.	Reconstruction on Ionic Solids	125
		4.3.2	Physical Measurements on Ionic Solids	127
		433	Chemical Measurements on Ionic Solids	133
	4.4.	Measu	rements on Adsorbate-Free Covalent or Metallic	100
		Solids		140
		4.4.1.	Reconstruction on Covalent and Metallic Solids	140
		4.4.2.	Electrical Measurements of Intrinsic Surface States	
			on Covalent Solids	142
		4.4.3.	Measurement by the Surface Spectroscopies	146
				110
_	_			
5.	Bo	nding	of Foreign Species at the Solid	
	Su	face		151
	5.1.	Recons	struction and Relocation in Bonding	152
	5.2.	The Se	miclassical Model of Bonding: The Surface Molecule	153
		5.2.1.	Surface Molecule Versus Rigid Band Model	153
		5.2.2.	Adsorbate Bonding to Covalent or Metallic Solids	156
			8	

х

Contents

Contents

		 5.2.3. Adsorbate Bonding to Ionic Solids	162
	53	Phase	168
	5.5.	5.3.1 Solid State Theories: The Semi-infinite Crystal	169
		5.3.2. Cluster Models	169
		5.3.3. The Interacting Surface Molecule (the Model	
		Hamiltonian Analysis)	171
		5.3.4. Other Quantum Models	175
		5.3.5. Remarks	175
	5.4.	Measurement of Adsorbate Surface States on Covalent or	
		Metallic Solids	76
		5.4.1. Screening Shifts and Other Inaccuracies in Mea-	176
		542 Bond Angles 1	179
		5.4.3. Surface State Energy Levels of Sorbate/Sorbent	
		Bonds	80
	5.5.	The Chemistry of Surface States	84
		5.5.1. Change of Surface State Energy Associated with	
		Bonding	85
		5.5.2. The Influence of a Polar Medium or Coadsorbate	
		on the Surface State Energy	88
		5.5.3. Surface States due to Multiequivalent Foreign	
		Adsorbates	90
	5.6.	The Formation of Surface State Bands 1	93
6.	No	nvolatile Foreign Additives on the	
	Sol	id Surface	95
	6.1.	General	95
	6.2.	Dispersion of Additives	96
		6.2.1. Techniques for Dispersing Additives 1	96
		6.2.2. Measurement of Dispersion	.98
		6.2.3. Sintering of Dispersed Particles: Surface Diffusion	
		of Adsorbates	.99
	6.3.	The Cluster, the Transition between a Molecule and a Solid 2	202
	6.4.	Ine Control of Surface Properties with Additives 2	205
		6.4.2 Observations of Additive Effects	203
	65	The Deal Surface)10)10
	0.5.		.17

7.	Ad	sorption	223
	7.1.	Adsorption Isotherms and Isobars7.1.1. Physical Adsorption7.1.2. Heat and Activation Energy of Adsorption,	223 223
		Irreversible Chemisorption	227
		7.1.3. The Adsorbate Superstructure	235
	7.2.	Ionosorption on Semiconductors	238
		7.2.1. The Surface State Representation of Adsorbed	
		Species	238
		7.2.2. Observations of Ionosorption	244
	7.3.	Adsorption with Local Bonding	252
		7.3.1. Adsorption on Ionic Solids	252
		7.3.2. Adsorption on Platinum	259
8.	The	Solid/Liquid Interface	263
	8.1.	Introduction	263
	8.1. 8.2.	Introduction . <t< th=""><th>263 265</th></t<>	263 265
	8.1. 8.2.	IntroductionTheory8.2.1.Double Layers and Potentials in Electrochemical	263 265
	8.1. 8.2.	Introduction	263 265 265
	8.1. 8.2.	Introduction	263 265 265
	8.1. 8.2.	Introduction	263 265 265 269
	8.1. 8.2.	Introduction	263 265 265 269
	8.1. 8.2.	Introduction	 263 265 265 269 274 277
	8.1.8.2.8.3.	Introduction	 263 265 265 269 274 277 277
	8.1.8.2.8.3.	Introduction	263 265 265 269 274 277 277 280
	8.1.8.2.8.3.	Introduction	263 265 265 269 274 277 277 280 283
	8.1.8.2.8.3.	Introduction	263 265 265 269 274 277 280 283
	8.1.8.2.8.3.	Introduction	263 265 265 269 274 277 277 280 283 288
	8.1.8.2.8.3.8.4	Introduction	263 265 265 269 274 277 277 280 283 288

9. Photoeffects at Semiconductor Surfaces 301

9.1.	General	•		•		•	•	•	•		•	•	•	•	•	•	301

	9.2.1.	Theory	304
	9.2.2.	Experimental Results	305
9.3.	Photoa	dsorption and Photodesorption	308
	9.3.1.	Theory	308
	9.3.2.	Experimental Observations of Photoadsorption and	
		Photodesorption	313
9.4.	Photoc	atalysis	317
	9.4.1.	Photodecomposition of Adsorbed Species	318
	9.4.2.	Photostimulated Catalytic Reactions	319
9.5.	Direct	Excitation of Surface States by Photons	322
10. Su	urfac	e Sites in Heterogeneous	
Ca	atalys	SIS	327
10.1.	Genera	al Concepts	327
	10.1.1.	The Role of the Catalyst	327
	10.1.2.	Some Correlations in Heterogeneous Catalysis .	328
10.2.	Surface	e Sites Associated with Steps and Other Geometrical	
	Factor	S	331
10.3.	The R	ole of Acid and Basic Sites in Catalytic Reactions	333
10.4.	Covale	ent Bonding to Coordinatively Unsaturated Metal	
	and C	ationic Sites	335
10.5.	Sites in	n Oxidation Catalysis	337
	10.5.1.	Introduction	337
	10.5.2.	Oxygen Exchange Sites in Oxidation Catalysis .	341
	10.5.3.	Dangling Bonds as Active Sites for Adsorption and	
		Electron Exchange	347
	10.5.4.	Wide Bands as Electron Sources and Sinks: <i>n</i> -Type	
		and <i>p</i> -Type Semiconductors	352
10.6.	Examp	oles of Oxidation Catalysis	355
	10.6.1.	Platinum	355
	10.6.2.	Partial Oxidation Catalysts: Bismuth and Iron	
		Molybdate	357
Reference	s		363
Author I	ndex .		389
Subject I	ndex .		403